	I wall	N.M. Oi		ns. DIV-Dist	1. 2	
trm 3160-3 4	5-05 framy	, , ,	N. G	arand Avenu	CHILICATE	Budget Buleau No. 1004-0150
Secemiser 1990)	UNIT DEPARTMEN	ED STATES	sia,	NM 88210"	ide)	Expires: December 31, 1991
n 66	,	LAND MANA	GEMEN	T		5. LEASE DESIGNATION AND SERIAL NO. NMNM-103875
APPLI	CATION FOR PE	RMIT TO D	RILL	OR DEEPEN		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
TYPE OF WORK	. 12	DEEDEN [_			7. UNIT AGREEMENT NAME
DRII TYPE OF WELL	LL 🖾	DEEPEN				28867
	as OTHER			NGLE MULTIP ONE ZONE	LE	8. FARM OR LEASE NAME, WELL NO. Brown Bear Federal Com #2
NAME OF OPERATOR Mack Energy Corp	oration	13837				9. API WELL NO.
DDRESS AND TELEPHONE NO.		1000.				30-015-34498
P.O. Box 960, Artes	sia, NM 88211-0960	(505) 74	48-128	8 RECEI		10. FIELD AND POOL, OR WILDCAT Crow Flats Morrow, SE
LOCATION OF WELL At surface	. (Report location clearly a	nd in accordance	with any	State requirement () 2,1	2005	11. SEC., T., R., M., OR BLK. 96840
At proposed prod. zon		760 FSL & 990	FWL	OCD-AM	TERM	
						Sec 35-T16S-R28E
DISTANCE IN MILES AN	D DIRECTION FROM NEAR	est town or post theast of Artesi				12. COUNTY OR PARISH 13. STATE Eddy NM
DISTANCE FROM PROPO	SED*	meast UI AFTESI		OF ACRES IN LEASE		F ACRES IN LEASE
LOCATION TO NEAREST PROPERTY OR LEASE I (Also to nearest drip	INE, FT.	760		480	тот	HIS WELL 320
DISTANCE FROM PROPO TO NEAREST WELL, DR	SED LOCATION*	1980	19. PR(DPOSED DEPTH	20. ROTA	RY OR CABLE TOOLS
OR APPLIED FOR, ON TH		1700		10,500	<u> </u>	Rotary
	3611' GR	Roswel	II Contr	olled Water Basin		22. APPROX. DATE WORK WILL START* 6/1/2005
		PROPOSED CASI	NG AND	CEMENTING PROGRA	M	
SIZE OF HOLE	GRADE, SIZE OF CASING	WEIGHT PER FO	тоот	SETTING DEPTH	T	QUANTITY OF CEMENT
						*
17 1/2	H-40,13 3/8	48		500		Circ
12 1/4	J-55, 8 5/8	24		500 1800		Circ Sufficient to Circ
				500		Circ
12 1/4 7 7/8	J-55, 8 5/8 L-80, 5 1/2	24 17	ent to	500 1800 10,500	mation fo	Circ Sufficient to Circ
12 1/4 7 7/8 Mack Energ	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to	24 17 a depth suffici		500 1800 10,500 test the Morrow For		Circ Sufficient to Circ Sufficient to Circ
12 1/4 7 7/8 Mack Energ asing will be cemen	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to	24 17 a depth suffici e, plugging and	d aban	500 1800 10,500 test the Morrow For doning in a manner	consisten	Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2"
12 1/4 7 7/8 Mack Energ asing will be cemen rograms as per On	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive	24 17 a depth suffici e, plugging and	d aban ined in	500 1800 10,500 test the Morrow For doning in a manner the following attach	consisten	Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2"
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or	24 17 a depth suffici e, plugging and der #1 are outl 4. <u>Certi</u>	d aban ined in fication	500 1800 10,500 test the Morrow For doning in a manner the following attach	consisten	Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" t with federal regulation. Specific 7. Responsibility Statement
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat nity Map	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr	d aban ined in fication ogen S oit #7-	500 1800 10,500 test the Morrow For doning in a manner the following attach ulfide Drilling Oper.	consistent nments: ation Plan	Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" t with federal regulation. Specific 7. Responsibility Statement
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr	d aban ined in fication ogen S oit #7-	500 1800 10,500 test the Morrow For doning in a manner the following attach ulfide Drilling Oper.	consistent nments: ation Play ent GEN	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" t with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO WERAL REQUIREMENTS
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per One 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat nity Map ation Verification Ma	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr p Exhib	d aban ined in fication ogen S oit #7-	500 1800 10,500 test the Morrow For doning in a manner the following attached the following attached the following Operation of the Safety Equipment of the following Sign H2S Safety Equipment Operation Sign Sign Sign Sign Sign Sign Sign Sig	consistent nments: ation Plan AFF ent GEN	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO JERAL REQUIREMENTS AND CIAL STIPULATIONS
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat nity Map ation Verification Ma	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr Exhit Exhit 6. Blow	d aban ined in fication ogen S bit #7- bit #8-	500 1800 10,500 test the Morrow For doning in a manner the following attached the following attached the following Operation of the Safety Equipment of the following Sign H2S Safety Equipment Operation Sign Sign Sign Sign Sign Sign Sign Sig	consistent nments: ation Plan AFF ent GEN	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" t with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO WERAL REQUIREMENTS
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & 6	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat nity Map ation Verification Ma	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr Exhib Exhib 6. Blow Exhib	d aban ined in fication ogen S oit #7- oit #8- out Pre oit #9-	500 1800 10,500 test the Morrow For doning in a manner the following attach nulfide Drilling Operates Warning Sign H2S Safety Equipment of the following Sign Safety Equipment Of the following S	consistent nments: ation Plan ation Plan Ent GEN SPE ATT	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO JERAL REQUIREMENTS AND COLAL STIPULATIONS ACHED ments
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & 6 Exhibit #4- One Exhibit #5- Progra	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat nity Map ation Verification Ma Operating Plan Mile Radius Map duction Facilities Lay	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr Exhib Exhib Exhib	d aban ined in fication ogen S bit #7- bit #8- out Pro bit #9- bit #10-	500 1800 10,500 test the Morrow For doning in a manner the following attach nulfide Drilling Oper. H2S Warning Sign H2S Safety Equipment of the following Sign Sign Sign Sign Safety Equipment Of the following Sign Sign Sign Sign Safety Equipment Of the following Sign Sign Sign Sign Sign Sign Sign S	consistent nments: ation Plan ation Plan Ent GEN SPE ATT	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO WERAL REQUIREMENTS AND COLL STIPULATIONS CIAL STIPULATIONS
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per One 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & G Exhibit #4- One Exhibit #5- Progexhibit #6- Loc	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat inity Map ation Verification Ma Decrating Plan Mile Radius Map duction Facilities Lay ation Layout	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr Exhib Exhib Exhib Exhib Exhib Exhib	d aban ined in fication ogen S bit #7- bit #8- bit #9- bit #10- bit #11-	500 1800 10,500 test the Morrow For doning in a manner the following attach mulfide Drilling Operates Warning Sign H2S Warning Sign H2S Safety Equipment Eventers BOPE Schematic Blowout Preventer Choke Manifold	consistent nments: ation Play ent GEN SPE ATT	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO WERAL REQUIREMENTS AND COLORS COLL STIPULATIONS CACHED THE SUBJECT TO WERAL REQUIREMENTS AND COLORS COLORS 13 3/8 4 COMENT J.
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & 6 Exhibit #4- One Exhibit #5- Progra Exhibit #6- Loc Above space describe	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat inity Map ation Verification Ma Decrating Plan Mile Radius Map duction Facilities Lay ation Layout	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr Exhib Exhib 6. Blow Exhib Exhib out Exhib	d aban ined in fication ogen S oit #7- oit #8- oit #9- oit #10- oit #11-	500 1800 10,500 test the Morrow For doning in a manner of the following attach of the following attach of the following Sign H2S Warning Sign H2S Safety Equipment of the following Sign H2S Safety Equipment of the following Preventer of the Manifold of the following Productive zone of the following Productive Producti	ation Play ent GEN ATT	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROVAL SUBJECT TO SERAL REQUIREMENTS AND COLL STIPULATIONS COLL STIP
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & G Exhibit #4- One Exhibit #5- Progra Exhibit #6- Loc ABOVE SPACE DESCRIE	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat nity Map ation Verification Ma Deerating Plan e Mile Radius Map duction Facilities Lay ation Layout	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr Exhib Exhib 6. Blow Exhib Exhib out Exhib	d aban ined in fication ogen S oit #7- oit #8- out Pre oit #9- oit #10- oit #11-	1800 1800 10,500 test the Morrow For doning in a manner the following attach mulfide Drilling Oper. H2S Warning Sign H2S Safety Equipment of the Blowout Preventer Choke Manifold that on present productive zon all depths. Give blowout preventer	ation Plan ent SPE ATT Requiren	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROVAL SUBJECT TO SERAL REQUIREMENTS AND COLL STIPULATIONS COLL STIP
12 1/4 7 7/8 Mack Energon Sasing will be cemen rograms as per On 1. Surveys Exhibit #1- Well Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & Exhibit #4- One Exhibit #5- Programity #5- Programity #6- Loc ABOVE SPACE DESCRIE SIGNED	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat nity Map ation Verification Ma Deerating Plan e Mile Radius Map duction Facilities Lay ation Layout	24 17 a depth suffici e, plugging and der #1 are outl 4. Certi 5. Hydr Exhib Exhib 6. Blow Exhib Exhib out Exhib	d aban ined in fication ogen S oit #7- oit #8- out Pre oit #9- oit #10- oit #11-	1800 1800 10,500 test the Morrow For doning in a manner the following attach mulfide Drilling Oper. H2S Warning Sign H2S Safety Equipment of the Blowout Preventer Choke Manifold that on present productive zon all depths. Give blowout preventer	ation Plan ent SPE ATT Requiren	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROVAL SUBJECT TO JERAL REQUIREMENTS ACTIONS ACTIONS ACTIONS ACTIONS ACTIONS ACTION Lead new productive zone. If proposal is to drill or if any.
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & G Exhibit #4- One Exhibit #5- Programity #6- Loc ABOVE SPACE DESCRIED COMPANY AND SIGNED COMPANY SIG	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat inity Map ation Verification Mam Operating Plan e Mile Radius Map duction Facilities Lay ation Layout the PROPOSED PROGRAM: Intent data on subsurface location of the Company of the Company of the Proposed Program: Intent data on subsurface location of the Company of the Company of the Proposed Program: Intent data on subsurface location of the Company of the Company of the Proposed Program: Intent data on State office use)	24 17 a depth sufficie, plugging and der #1 are outl 4. Certi 5. Hydr Exhib Exhib 6. Blow Exhib Exhib out Exhib out TITL	d aban ined in fication ogen S oit #7- oit #8- oit #9- oit #10- oit #11- en, give da rue vertica	1800 1800 10,500 test the Morrow For doning in a manner of the following attach of the following attach of the following Sign H2S Warning Sign H2S Safety Equipment of the following Sign H2S Safety Equipment of the following Productive zone of the following Production Classics of the following Production Production Classics of the following Production Production Production Produ	ation Play ent GEF ATT Requirent me and proposenter program. lerk	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROVAL SUBJECT TO JERAL REQUIREMENTS ACTIONS ACTIONS ACTIONS ACTIONS ACTIONS ACTION Lead new productive zone. If proposal is to drill or if any.
12 1/4 7 7/8 Mack Energy asing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & G Exhibit #4- One Exhibit #5- Progra Exhibit #6- Loc ABOVE SPACE DESCRIE Expen directionally, give pertin SIGNED (This space for Feder PERMIT NO. Application approval does n	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat inity Map ation Verification Mam Operating Plan Mile Radius Map duction Facilities Lay ation Layout SE PROPOSED PROGRAM: Intent data on subsurface location Generating Plan Security W.	24 17 a depth sufficie, plugging and der #1 are outl 4. Certi 5. Hydr Exhib 6. Blow Exhib Exhib out Froposal is to deepers and measured and to	d aban ined in fication ogen S oit #7- oit #8- out Pre oit #9- oit #10- oit #11- en, give da rue vertica	1800 10,500 test the Morrow For doning in a manner the following attach mulfide Drilling Oper. H2S Warning Sign H2S Safety Equipment of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that on present productive zonal depths. Give blowout preventer of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that are the subject that the subject the subject that the subject	ation Play ent GEN ATT Requiren cand proposenter program. lerk	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO WERAL REQUIREMENTS ACHED IN THE STATE OF
12 1/4 7 7/8 Mack Energy asing will be cemen programs as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & G Exhibit #4- One Exhibit #5- Progra Exhibit #6- Loc ABOVE SPACE DESCRIBE EXHIBIT MO. Application approval does n	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat inity Map ation Verification Mam Operating Plan Mile Radius Map duction Facilities Lay ation Layout SE PROPOSED PROGRAM: Intent data on subsurface location Generating Plan Security W.	24 17 a depth sufficie, plugging and der #1 are outl 4. Certi 5. Hydr Exhib 6. Blow Exhib Exhib out Froposal is to deepers and measured and to	d aban ined in fication ogen S oit #7- oit #8- out Pre oit #9- oit #10- oit #11- en, give da rue vertica	1800 10,500 test the Morrow For doning in a manner the following attach mulfide Drilling Oper. H2S Warning Sign H2S Safety Equipment of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that on present productive zonal depths. Give blowout preventer of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that are the subject that the subject the subject that the subject	ation Play ent GEN ATT Requiren cand proposenter program. lerk	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO WERAL REQUIREMENTS ACHED IN THE STATE OF
12 1/4 7 7/8 Mack Energy asing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & G Exhibit #4- One Exhibit #5- Progra Exhibit #6- Loc ABOVE SPACE DESCRIE SIGNED (This space for Feder PERMIT NO. Application approval does in	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat inity Map ation Verification Mam Operating Plan Mile Radius Map duction Facilities Lay ation Layout SE PROPOSED PROGRAM: Intent data on subsurface location Generating Plan Security W.	24 17 a depth sufficie, plugging and der #1 are outl 4. Certi 5. Hydr Exhib 6. Blow Exhib Exhib out Froposal is to deepers and measured and to	d aban ined in fication ogen S oit #7- oit #8- out Pre oit #9- oit #10- oit #11- en, give da rue vertica	1800 10,500 test the Morrow For doning in a manner the following attach mulfide Drilling Oper. H2S Warning Sign H2S Safety Equipment of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that on present productive zonal depths. Give blowout preventer of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that are the subject that the subject the subject that the subject	ation Play ent GEN ATT Requiren cand proposenter program. lerk	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROYAL SUBJECT TO WERAL REQUIREMENTS ACHED IN THE STATE OF
12 1/4 7 7/8 Mack Energasing will be cemen rograms as per On 1. Surveys Exhibit #1- Wel Exhibit #2- Vici Exhibit #3- Loc 2. Drilling Progra 3. Surface Use & Exhibit #4- One Exhibit #5- Programit #5- Programit #6- Loc ABOVE SPACE DESCRIE pen directionally, give perting the space for Feder Permit No. Application approval does in	J-55, 8 5/8 L-80, 5 1/2 gy proposes to drill to ted. If non-productive shore Oil and Gas Or Il Location Plat inity Map ation Verification Mam Operating Plan Mile Radius Map duction Facilities Lay ation Layout SE PROPOSED PROGRAM: Intent data on subsurface location Generating Plan Security W.	24 17 a depth sufficie, plugging and der #1 are outl 4. Certi 5. Hydr Exhib 6. Blow Exhib Exhib out Froposal is to deepers and measured and to	d aban ined in fication ogen S oit #7- oit #8- out Pre oit #9- oit #10- oit #11- en, give da rue vertica	1800 10,500 test the Morrow For doning in a manner the following attach mulfide Drilling Oper. H2S Warning Sign H2S Safety Equipment of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that on present productive zonal depths. Give blowout preventer of the Manifold that an present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that an on present productive zonal depths. Give blowout preventer of the Manifold that are the subject that the subject the subject that the subject	ation Play ent GEN ATT Requiren cand proposenter program. lerk	Circ Sufficient to Circ Sufficient to Circ Sufficient to Circ or oil gas. If productive, 5 1/2" It with federal regulation. Specific 7. Responsibility Statement ROVAL SUBJECT TO WERAL REQUIREMENTS CIAL STIPULATIONS PACHED IN THE STATE OF

State of New Mexico

DISTRICT I 1625 N. FRENCE DR., HOBBS, NM 88240

Energy, Minerals and Natural Resources Department

DISTRICT II

1301 W. GRAND AVENUE, ARTESIA, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 OIL CONSERVATION DIVISION 1220 SOUTH ST. FRANCIS DR. Santa Fe, New Mexico 87505

Form C-102
Revised JUNE 10, 2003
Submit to Appropriate District Office
State Lease - 4 Copies
Pee Lease - 3 Copies


DISTRICT IV 1220 S. ST. FRANCIS DR., SANTA PE, NM 87505	WELL LOCATION AND	ACREAGE DEDICATION PLAT	AMENDED REPORT
API Number	Pool Code	Pool Name	
	96840	Crow Flats Morrow,	SE
Property Code	Prop	erty Name	Well Number
28867	BROWN BEAR	R FEDERAL COM	2
OGRID No.	Oper	ator Name	Elevation
013837	MACK ENERG	Y CORPORATION	3611'

Surface Location North/South line Section Lot Idn Feet from the Feet from the East/West line UL or lot No. Township Range County 28-E WEST М 35 16-S 760 SOUTH 990 **EDDY**

Bottom Hole Location If Different From Surface UL or lot No. Section Township Range Lot Idn Feet from the North/South line Feet from the East/West line County Dedicated Acres Joint or Infill Consolidation Code Order No. 320

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

GEODETIC COORDINATES NAD 27 NME Y=681776.2 N X=555754.2 E	OPERATOR CERTIFICATION I hereby certify the the information contained herein is true and complete to the best of my knowledge and belief.
LAT. = 32*52'26.95" N LONG. = 104*09'06.24" W	Signature W. Shenell
	Jerry W. Sherrell Printed Name Production Clerk Title
	5/2/2005 Date SURVEYOR CERTIFICATION
	I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervison, and that the same is true and correct to the best of my belief.
3628.0' 3607.7'	MARCH 21, 2005 Date Surveyed JR Signature Scaling Professional Surveyort
990' - 8	Bary Ballin 3/30/05
3638.3'	Certainate No. GARY ETISON 12641



DRILLING PROGRAM

1. Geologic Name of Surface Formation

Quaternary

2. Estimated Tops of Important Geologic Markers:

Quaternary	Surface	Wolfcamp	6800'
San Andres	2126'	Atoka	9610'
Glorieta	3558'	Morrow	9800'
Tubb	4890'		
Abo	5519'		

3. Estimated Depths of Anticipated Fresh Water, Oil and Gas:

Water Sand	150'	Fresh Water	Abo	5519'	Oil/Gas
San Andres	2126'	Oil/Gas	Wolfcamp	6800'	Oil/Gas
Paddock	3558'	Oil/Gas	Atoka	9610'	Gas
Tubb	4890'	Oil/Gas	Morrow	9800'	Gas

No other formations are expected to give up oil, gas or fresh water in measurable quantities. Setting 13 3/8" casing to 500' and circulating cement back to surface will protect the surface fresh water sand. Salt Section will be protected by setting 8 5/8" casing to 1800' and circulating cement back to surface. Any shallower zones above TD, which contain commercial quantities of oil and/or gas, will have cement circulated across them by cementing 5 1/2" production casing, which will be run at TD.

4. Casing Program:

Hole Size	Interval	OD Casing	Weight, Grade, Jt, Cond., Type
17 ½" 12 ¼"	0-500' 0-1800'	13 3/8" 8 5/8"	48#, H-40, ST&C, New, R-3 24#, J-55, ST&C, New, R-3
7 7/8"	0-TD	5 1/2"	17#, L-80, LT&C, New, R-3

Drilling Program Page 1

5. Cement Program:

- 13 3/8" Surface Casing: Circulate to Surface with Class C w/2% CaCl2.
- 8 5/8 Intermiate Casing: Circulate to Surface with Class C W/2% CaCl2.
- 5 1/2" Production Casing: Cement Casing with Class C w/6# Salt & 2/10 of 1% CFR-3 per sack. We will run a hole caliper and run sufficient cement to circulate to surface.

6. Minimum Specifications for Pressure Control:

CORRECTION
BY JERRY
SHERRELL
MACK ENERGY
5/2/05
L. B.M.L.

The blowout preventer equipment (BOP) shown in Exhibit #9 will consist of a double ramtype (The blowout preventer equipment (BOP) shown in Exhibit #9 will consist of a double ramtype (2000 psi WP) preventer. This unit will be hydraulically operated and the ram type preventer will be equipped with blind rams on top of 4 1/2" drill pipe rams on bottom. The BOP will be nippled up on the 13 3/8" surface casing and tested to 2000 ## by a 3rd party. The BOP will then be nippled up on the 8 5/8" intermediate casing and tested by a 3rd party to 2000 psi and used continuously until TD is reached. All BOP's and accessory equipment will be tested to 2000 psi before drilling out of intermediate casing. Pipe rams will be operationally checked each 24-hour period. Blind rams will be operationally checked on each trip out of the hole. These checks will be noted on the daily tour sheets. Other accessories to the BOP equipment (Exhibit #10) will include a Kelly cock and floor safety valve and choke lines and choke manifold (Exhibit #11) with 2000 psi WP rating.

7. Types and Characteristics of the Proposed Mud System:

The well will be drilled to TD with a combination of brine, cut brine and polymer mud system. The applicable depths and properties of this system are as follows:

D	EPTHTYPE	WEIG	HT	VISCOSITY	WATERLOSS
0-	-500 [*]	Fresh Water	8.5	28	N.C.
50	00-1800'	Brine	10	30	N.C.
18	300'-TD	Cut Brine	9.1	29	N.C.

Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept at the well site at all times.

8. Auxiliary Well Control and Monitoring Equipment:

- A. Kelly cock will be kept in the drill string at all times.
- B. A full opening drill pipe-stabbing valve with proper drill pipe connections will be on the rig floor at all times.

9. Logging, Testing and Coring Program:

- A. The electric logging program will consist of GR-Dual Laterolog, Spectral Density, Dual Spaced Neutron, CSNG Log and will be ran from T.D. to 8 5/8 casing shoe.
- B. Drill Stem test is not anticipated.
- C. No conventional coring is anticipated.
- D. Further testing procedures will be determined after the 5 1/2" production casing has been cemented at TD based on drill shows and log evaluation.

10. Abnormal Conditions, Pressures, Temperatures and Potential Hazards:

No abnormal pressures or temperatures are anticipated. The estimated bottom hole at TD is 110 degrees and estimated maximum bottom hole pressure is 2300 psig. Low levels of Hydrogen sulfide have been monitors in producing wells in the area, so H2S may be present while drilling of the well a plan is attached to the Drilling program. No major loss of circulation zones has been reported in offsetting wells.


11. Anticipated Starting Date and Duration of Operations:

Road and location work will not begin until approval has been received from the BLM. The anticipated spud date is June 1, 2005. Once commenced, the drilling operation should be finished in approximately 31 days. If the well is productive, an additional 30 days will be required for completion and testing before a decision is made to install permanent facilities.

SURFACE USE AND OPERATING PLAN

1. Existing & Proposed Access Roads

- A. The well site and elevation plat for the proposed well is shown in Exhibit #1. John West Engineering, Hobbs, NM, staked the well.
- B. All roads to the location are shown in Exhibit below. The existing lease roads are illustrated in Blue and are adequate for travel during drilling and production operations. Upgrading existing roads prior to drilling well will be done where necessary.
- C. Directions to Location: From intersection of Hwy 82 and CR 209, turn north 5.5 miles, turn left on caliche road to existing well Brown Bear #1, go west from this location on 2-track road 6/10 mile, then south 800' to location.
- D. Routine grading and maintenance of existing roads will be conducted as necessary to maintain their condition as long as any operations continue on this lease.



New Access Road

Upgrade of existing road

2. Proposed Access Road:

Exhibit #3 shows 800' of new access road and 3500' of upgraded road to be constructed. The road will be constructed as follows:

- A. The Maximum width of the running surface will be 14'. The road will be crowned and ditched and constructed of 6" rolled and compacted caliche.

 Ditches will be at 3:1 slope and 4 feet wide. Water will be diverted where necessary to avoid ponding, prevent erosion, maintain good drainage, and to be consistent with local drainage patterns.
- B. The average grade will be less than 1%.
- C. No turnouts are planned.
- D. No culverts, cattleguard, gates, low water crossings or fence cuts are necessary.
- E. Surfacing material will consist of native caliche. Caliche will be obtained from the nearest BLM approved caliche pit or reserve pit area.
- F. The proposed access road as shown in Exhibit #3 has been centerline flagged by John West Engineering, Hobbs, New Mexico.

3. Location of Existing Wells & Proposed flow lines for New Wells:

Exhibit #4 shows all existing wells within a one-mile radius of this well. As shown on this plat there are wells producing from the Morrow formation. Proposed flow lines, will stay on the same location as the well (Exhibit #4).

4. Location of Existing and/or Proposed Facilities:

- A. Mack Energy Corporation does not operate a production facility on this lease.
- B. If the well is productive, contemplated facilities will be as follows:
 - 1) Morrow Completion: Will be sent to the Brown Bear Federal #2 Tank Battery. The Facility is shown in Exhibit #5.
 - 2) The tank battery and facilities including all flow lines and piping will be installed according to API specifications.
 - 3) Any additional caliche will be obtained from a BLM approved caliche pit. Any additional construction materials will be purchased from contractors.

4) It will be necessary to run electric power if this well is productive. Power will be run by CVE and they will send in a separate plan for power.




Exhibit #5

- A. If the well is productive, rehabilitation plans are as follows:
 - 1) The reserve pit will be back filled after the contents of the pit are dry (within 120 days after the well is completed).
 - 2) Topsoil removed from the drill site will be used to recontour the pit area to the original natural level, as nearly as possible, and reseeded as per BLM specifications.

5. Location and Type of Water Supply:

The well will be drilled with combination brine and fresh water mud system as outlined in the drilling program. The water will be obtained from commercial water stations in the area and hauled to location by transport truck over the existing and proposed access roads shown in Exhibit #4. If a commercial fresh water source is nearby, fasline may be laid along existing road ROW's and fresh water pumped to the well. No water well will be drilled on the location.

6. Source of Construction Materials:

All caliche required for construction of the drill pad and proposed new access road (approximately 2500 cubic yards) will be obtained from a BLM approved caliche pit or the reserve pit.

7. Methods of Handling Water Disposal:

- A. Drill cuttings not retained for evaluation purposes will be disposed into the reserve pit.
- B. Drilling fluids will be contained in a lined working pit. The reserve pit will contain any excess drilling fluid or flow from the well during drilling, cementing and completion operations. The reserve pit will be an earthen pit, approximately 125' X 125' X 10' deep with a dividing wall dividing it into two horseshoe style pits and fenced on three sides prior to drilling. It will be fenced on the fourth side immediately following rig removal. The reserve pit will be lined 125' X 125' X 10'. The reserve pit will be lined (12-mil thickness) to minimize loss of drilling fluids and saturation of the ground with brine water.
- C. Water produced from the well during completion may be disposed into the reserve pit or a steel tank (depending on the rates). After the well is permanently placed on production, produced water will be collected in tanks (fiberglass) until pumped to an approved disposal system; produced oil will be collected in steel tanks until sold.
- D. Garbage and trash produced during drilling or completion operations will be collected in a trash bin and hauled to an approved landfill. All water and fluids will be disposed of into the reserve pit. Salts and other chemicals produced during drilling or testing will be disposed into the reserve pit. No toxic waste or hazardous chemicals will be produced by this operation.
- E. After the rig is moved out and the well is either completed or abandoned, all waste materials will be cleaned up within 30 days. The reserve pit will be completely fenced and kept closed until it has dried. When the reserve pit is dry enough to breakout and backfill and reseeded as per BLM specifications as weather permits. In the event of a dry hole only a dry hole marker will remain.

8. Ancillary Facilities:

No airstrip, campsite or other facilities will be built as a result of the operation on this well.

9. Well Site Layout:

- A. The drill pad layout, with elevations staked by John West Engineering, is shown in Exhibit #6. Dimensions of the pad and pits are shown. Topsoil, if available, will be stockpiled per BLM specifications. Because the pad is almost level no major cuts will be required.
- B. Diagram below shows the proposed orientation of reserve pit, working pit. There is a possibility that the pits will be moved around depending on Caliche in the area. No permanent living facilities are planned, but a temporary foreman/toolpusher's trailer will be on location during the drilling operations.
- C. The reserve pit will be lined with high quality plastic sheeting (12 mil thickness).




Exhibit #6

10. Plans for Restoration of the Surface:

- A. Upon completion of the proposed operations, the pit area, after allowing drying, will be broken out and leveled. The original topsoil will be returned to the pit area, which will be leveled and contoured to as nearly the original topography as possible.
- B. The disturbed area will be revegetated by reseeding during the proper growing season with a seed mixture of native grasses as recommended by the BLM.
- C. Three sides of the reserve pit will be fenced prior to and during drilling operations. At the time that the rig is removed, the reserve pit will be fenced on the rig (fourth) side to prevent livestock from being entrapped. The fencing will remain in place until the pit area is cleaned up and leveled. No oil will be left on the surface of the fluid in the pit.
- D. Upon completion of proposed operations, if the well is completed, the reserve pit area will be treated as outlined above within the same prescribed time. Any additional caliche required for facilities will be obtained from a BLM approved caliche pit. Topsoil removed from the drill site will be used to recontour the pit area to its original natural level and reseeded as per BLM specifications.

11. Surface Ownership:

The well site and lease is located entirely on Federal surface. We have notified the surface lessee of the impending operations. According to BLM the leasee is Bogel Farms, Lewis Derrick, P.O. Box 441 Artesia, NM 88210.

12. Other Information:

- A. The area around the well site is grassland and the topsoil is sandy. The vegetation is native scrub grass with sagebrush.
- B. There is no permanent or live water in the immediate area.
- C. A Cultural Resources Examination has been requested and will be forwarded to your office in the near future.

13. Lessee's and Operator's Representative:

The Mack Energy Corporation representative responsible for assuring compliance with the surface use plan is as follows:

Jerry W. Sherrell Mack Energy Corporation P.O. Box 960 Artesia, NM 88211-0960 Phone (505) 748-1288 (office)

CERTIFICATION

I hereby certify that I, or person under my direct supervision, have inspected the proposed drill site and access route; that I am familiar with the conditions which currently exist; that the statements made in this plan are to the best of my knowledge, true and correct; and the work associated with the operations proposed herein will be performed by Mack Energy Corporation and its contractors and subcontractors in conformity with this plan and the terms and conditions which it is approved. This statement is subject to the provisions of 18 U.S.C. 1001 for the filing of a false statement.

Date: 5-2-2005

Signed:

Surface Use Plan

Page 10

Mack Energy Corporation

Hydrogen Sulfide Drilling Operation Plan

I. HYDROGEN SULFIDE TRAINING

All personnel, whether regularly assigned, contracted, or employed on an unscheduled basis, will receive training from a qualified instructor in the following areas prior to commencing drilling operations on this well:

- 1. The hazards an characteristics of hydrogen sulfide (H2S)
- 2. The proper use and maintenance of personal protective equipment and life support systems.
- 3. The proper use of H2S detectors alarms warning systems, briefing areas, evacuation procedures, and prevailing winds.
- 4. The proper techniques for first aid and rescue procedures.

In addition, supervisory personnel will be trained in the following areas:

- 1. The effects of H2S on metal components. If high tensile tubular are to be used, personnel well be trained in their special maintenance requirements.
- 2. Corrective action and shut-in procedures when drilling or reworking a well and blowout prevention and well control procedures.
- 3. The contents and requirements of the H2S Drilling Operations Plan and Public Protection Plan.

There will be an initial training session just prior to encountering a known or probable H2S zone (within 3 days or 500 feet) and weekly H2S and well control drills for all personnel in each crew. The initial training session shall include a review of the site specific H2S Drilling Operations Plan and the Public Protection Plan. The concentrations of H2S of wells in this area from surface to TD are low enough that a contingency plan is not required.

H2S Plan Page 11

II. H2S SAFETY EQUIPMENT AND SYSTEMS

Note: All H2S safety equipment and systems will be installed, tested, and operational when drilling reaches a depth of 500 feet above, or three days prior to penetrating the first zone containing or reasonable expected to contain H2S.

1. Well Control Equipment:

- A. Flare line.
- B. Choke manifold.
- C. Blind rams and pipe rams to accommodate all pipe sizes with properly sized closing unit.
- D. Auxiliary equipment may include if applicable: annular preventer & rotating head.

2. Protective equipment for essential personnel:

A. Mark II Survive air 30-minute units located in the doghouse and at briefing areas, as indicated on well site diagram.

3. H2S detection and monitoring equipment:

A. 1 portable H2S monitors positioned on location for best coverage and response. These units have warning lights and audible sirens when H2S levels of 20 PPM are reached.

4. Visual warning systems:

- A. Wind direction indicators as shown on well site diagram (Exhibit #8).
- B. Caution/Danger signs (Exhibit #7) shall be posted on roads providing direct access to location. Signs will be painted a high visibility yellow with black lettering of sufficient size to be readable at a reasonable distance from the immediate location. Bilingual signs will be used, when appropriate. See example attached.

5. Mud program:

A. The mud program has been designed to minimize the volume of H2S circulated to surface. Proper mud weight, safe drilling practices, and the use of H2S scavengers will minimize hazards when penetrating H2S bearing zones.

H2S Plan Page 12

6. Metallurgy:

- A. All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, and valves shall be suitable for H2S service.
- B. All elastomers used for packing and seals shall be H2S trim.

7. Communication:

- A. Radio communications in company vehicles including cellular telephone and 2-way radio.
- B. Land line (telephone) communication at Office.

8. Well testing:

- A. Drill stem testing will be performed with a minimum number of personnel in the immediate vicinity, which are necessary to safely and adequately conduct the test. The drill stem testing will be conducted during daylight hours and formation fluids will not be flowed to the surface. All drill-stem-testing operations conducted in an H2S environment will use the closed chamber method of testing.
- B. There will be no drill stem testing.

EXHIBIT #7


WARNING YOU ARE ENTERING AN H2S

AUTHORIZED PERSONNEL ONLY

- 1. BEARDS OR CONTACT LENSES NOT ALLOWED
- 2. HARD HATS REQUIRED
- 3. SMOKING IN DESIGNATED AREAS ONLY
- 4. BE WIND CONSCIOUS AT ALL TIMES
- 5. CHECK WITH MACK ENERGY FOREMAN AT OFFICE

MACK ENERGY CORPORATION 1-505-748-1288

DRILLING LOCATION H2S SAFTY EQUIPMENT Exhibit # 8



- H2S Monitors with alarms at the bell nipple
- ☐ Wind Direction Indicators
- Safe Briefing areas with caution signs and breathing equipment min 150 feet from


Attachment to Exhibit #9 NOTES REGARDING THE BLOWOUT PREVENTERS Brown Bear Federal Com #2 Eddy County, New Mexico

- 1. Drilling nipple to be so constructed that it can be removed without use of a welder through rotary table opening, with minimum I.D. equal to preventer bore.
- 2. Wear ring to be properly installed in head.
- 3. Blow out preventer and all fittings must be in good condition, 2000 psi WP minimum.
- 4. All fittings to be flanged.
- 5. Safety valve must be available on rig floor at all times with proper connections, valve to be full 2000 psi WP minimum.
- 6. All choke and fill lines to be securely anchored especially ends of choke lines.
- 7. Equipment through which bit must pass shall be at least as large as the diameter of the casing being drilled through.
- 8. Kelly cock on Kelly.
- 9. Extension wrenches and hands wheels to be properly installed.
- 10. Blow out preventer control to be located as close to driller's position as feasible.
- 11. Blow out preventer closing equipment to include minimum 40-gallon accumulator, two independent sources of pump power on each closing unit installation all API specifications.


Blowout Preventers Page 15

Mack Energy Corporation

Exhibit #9 BOPE Schematic



Choke Manifold Requirement (2000 psi WP) No Annular Required




Mack Energy Corporation

Minimum Blowout Preventer Requirements

2000 psi Working Pressure 2 MWP EXHIBIT #10

Stack Requirements

NO.	Items	Min.	Min.
		I.D.	Nominal
1	Flow line		2"
2	Fill up line		2"
3	Drilling nipple		
4	Annular preventer		
5	Two single or one dual hydraulically operated rams		
6a	Drilling spool with 2" min. kill line and 3" min choke line outlets		2" Choke
6b	2" min. kill line and 3" min. choke line outlets in ram. (Alternate to 6a above)		
7	Valve Gate Plug	3 1/8	
8	Gate valve-power operated	3 1/8	
9	Line to choke manifold		3"
10	Valve Gate Plug	2 1/16	
11	Check valve	2 1/16	
12	Casing head		
13	Valve Gate Plug	1 13/16	
14	Pressure gauge with needle valve		
15	Kill line to rig mud pump manifold		2"



OPTIONAL

	,		
16	Flanged Valve	1 13/16	

CONTRACTOR'S OPTION TO FURNISH:

- All equipment and connections above
 Braden head or casing head. Working
 pressure of preventers to be 2000-psi
 minimum.
- Automatic accumulator (80 gallon, minimum) capable of closing BOP in 30 seconds or less and, holding them closed against full rated working pressure.
- BOP controls, to be located near drillers' position.
- Kelly equipped with Kelly cock.
- Inside blowout preventer or its equivalent on derrick floor at all times with proper threads to fit pipe being used.
- 6. Kelly saver-sub equipped with rubber casing protector at all times.
- 7. Plug type blowout preventer tester.
- 8. Extra set pipe rams to fit drill pipe in use on location at all times.
- Type RX ring gaskets in place of Type R.

MEC TO FURNISH:

- 1. Braden head or casing head and side valves.
- 2. Wear bushing. If required.
- 3.

GENERAL NOTES:

- Deviations from this drawing may be made only with the express permission of MEC's Drilling Manager.
- All connections, valves, fittings, piping, etc., subject to well or pump pressure must be flanged (suitable clamp connections acceptable) and have minimum working pressure equal to rated working pressure of preventers up through choke valves must be full opening and suitable for high pressure mud service.
- Controls to be of standard design and each marked, showing opening and closing position
- 4. Chokes will be positioned so as not to hamper or delay changing of choke beans.

 Replaceable parts for adjustable choke, or bean

- sizes, retainers, and choke wrenches to be conveniently located for immediate use.
- All valves to be equipped with hand-wheels or handles ready for immediate use.
- Choke lines must be suitably anchored.
- 7. Hand wheels and extensions to be connected and ready for
- Valves adjacent to drilling spool to be kept open. Use outside valves except for emergency.
- All seamless steel control piping (2000 psi working pressure) to have flexible joints to avoid stress. Hoses will be permitted.
- Casing head connections shall not be used except in case of emergency.
- 11. Do not use kill line for routine fill up operations.

Mack Energy Corporation Exhibit #11


Exhibit #11

MIMIMUM CHOKE MANIFOLD

3,000, 5,000, and 10,000-PSI Working Pressure

2 M will be used or greater

3 MWP - 5 MWP - 10 MWP



Below Substructure

Mimimum requirements

			5	,000 MWP		1	10,000 MWP			
No.		I.D.	NOMINAL	Rating	I.D.	Nominal	Rating	I.D.	Nominal	Rating
l	Line from drilling Spool		3"	3,000		3"	5,000		3"	10,000
2	Cross 3" x 3" x 3" x 2"			3,000			5,000			
2	Cross 3" x 3" x 3" x 2"									10,000
3	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000
4	Valve Gate Plug	1 13/16		3,000	1 13/16		5,000	1 13/16		10,000
4a	Valves (1)	2 1/16		3,000	2 1/16		5,000	2 1/16		10,000
5	Pressure Gauge			3,000			5,000			10,000
6	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000
7	Adjustable Choke (3)	2"		3,000	2"		5,000	2"		10,000
8	Adjustable Choke	1"		3,000	1"		5,000	2"		10,000
9	Line		3"	3,000		3"	5,000		3"	10,000
10	Line		2"	3,000		2"	5,000		2"	10,000
11	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000
12	Line		3"	1,000		3"	1,000		3"	2,000
13	Line		3"	1,000		3"	1,000		3"	2,000
14	Remote reading compound Standpipe pressure quage			3,000			5,000			10,000
15	Gas Separator		2' x5'			2' x5'			2' x5'	
16	Line		4"	1,000		4"	1,000		4"	2,000
17	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000

- (1) Only one required in Class 3M
- (2) Gate valves only shall be used for Class 10 M
- (3) Remote operated hydraulic choke required on 5,000 psi and 10,000 psi for drilling.

EQUIPMENT SPECIFICATIONS AND INSTALLATION INSTRUCTION

- 1. All connections in choke manifold shall be welded, studded, flanged or Cameron clamp of comparable rating.
- 2. All flanges shall be API 6B or 6BX and ring gaskets shall be API RX or BX. Use only BX for 10 MWP.
- 3. All lines shall be securely anchored.
- 4. Chokes shall be equipped with tungsten carbide seats and needles, and replacements shall be available.
- 5. Choke manifold pressure and standpipe pressure gauges shall be available at the choke manifold to assist in regulating chokes. As an alternate with automatic chokes, a choke manifold pressure gauge shall be located on the rig floor in conjunction with the standpipe pressure gauge.
- 6. Line from drilling spool to choke manifold should bee as straight as possible. Lines downstream from chokes shall make turns by large bends or 90 degree bends using bull plugged tees.

CONDITIONS OF APPROVAL - DRILLING

Operator's Name: Well Name & No.

MACK ENERGY CORPORATION
2 - BROWN BEAR FEDERAL COM

Location:

760' FSL & 990' FWL - SEC 35 - T16S - R28E - EDDY COUNTY

Lease: NM-103875

I. DRILLING OPERATIONS REQUIREMENTS:

1. The Bureau of Land Management (BLM) is to be notified at the Roswell Field Office, 2909 West Second St., Roswell NM 88201, (505) 627-0272 for wells in Chaves and Roosevelt Counties; the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 234-5909 or (505) 361-2822 (After hours) - for wells in Eddy County; and the Hobbs Field Station, 414 West Taylor, Hobbs NM 88240, (505) 393-3612 for wells in Lea County, in sufficient time for a representative to witness:

- A. Spudding
- B. Cementing casing: 13-3/8 inch 8-5/8 inch 5-1/2 inch
- C. BOP tests
- 2. Low levels of hydrogen sulfide (H2S) gas has been monitored in producing wells in the area. A Hydrogen Sulfide Drilling Plan will be present at the rig site should H2S gas be encountered.
- 3 Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 4. Submit a Sundry Notice (Form 3160-5, one original and five copies) for each casing string, describing the casing and cementing operations. Include pertinent information such as; spud date, hole size, casing (size, weight, grade and thread type), cement (type, quantity and top), water zones and problems or hazards encountered. The Sundry shall be submitted within 15 days of completion of each casing string. The reports may be combined into the same Sundry if they fall within the same 15 day time frame.
- 5. The API No. assigned to the well by NMOCD shall be included on the subsequent report of setting the first casing string.
- 6. A Communitization Agreement covering the acreage dedicated to this well must be filed for approval with the BLM. The effective date of the agreement shall be prior to any sales.

II. CASING:

- 1. The <u>13-3/8</u> inch surface casing shall be set at <u>500 feet</u>, below usable water and cement circulated to the surface. If cement does not circulate to the surface the appropriate BLM office shall be notified and a temperature survey or cement bond log shall be run to verify the top of the cement. Remedial cementing shall be completed prior to drilling out that string.
- 2. The minimum required fill of cement behind the <u>8-5/8</u> inch intermediate casing is <u>circulate cement to</u> the surface.
- 4. The minimum required fill of cement behind the 5-1/2 inch production casing is cement shall extend upward a minimum of 500 feet above the uppermost hydrocarbon bearing interval.

III. PRESSURE CONTROL:

- 1. All BOP systems and related equipment shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2. The BOP and related equipment shall be installed and operational before drilling below the 13-3/8 inch casing shoe and shall be tested as described in Onshore Order No. 2. Any equipment failing to test satisfactorily shall be repaired or replaced.
- 2. Minimum working pressure of the blowout preventer and related equipment (BOPE) required for drilling the surface and intermediate casing shall be <u>2000</u> psi. Minimum working pressure of the blowout preventer and related equipment (BOPE) required for drilling below the <u>8-5/8</u> inch casing shall be <u>3000</u> psi.
- 3. The appropriate BLM office shall be notified in sufficient time for a representative to witness the tests.
- The tests shall be done by an independent service company.
- The results of the test shall be reported to the appropriate BLM office.
- Testing fluid must be water or an appropriate clear liquid suitable for sub-freezing temperatures. Use of drilling mud for testing is not permitted since it can mask small leaks.
- Testing must be done in a safe workman-like manner. Hard line connections shall be required.
- BOPE must be tested prior to drilling into the **Wolfcamp** Formation by an independent service company.

IV. DRILLING MUD:

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the **Wolfcamp** Formation, and shall be used until production casing is run and cemented. Monitoring equipment shall consist of the following:

- 1. Recording pit level indicator to indicate volume gains and losses.
- 2. Mud measuring device for accurately determining the mud volumes necessary to fill the hole during trips.
- 3. Flow-sensor on the flow line to warn of abnormal mud returns from the well.