



marbob
energy corporation

30-015-34562

January 31, 2006

Oil Conservation Division
1301 W. Grande Ave.
Artesia, N.M. 88210

RECEIVED

FEB 01 2006

ODD-ARTESIA

Attention: Bryan Arrant

RE: Dodd Federal Unit #506
1030' FSL & 1650' FEL
Section 15, T17S, R29E
Eddy County, New Mexico

Dodd Federal Unit #511
1980' FNL & 1305' FWL
Section 14, T-17S, R-29E
Eddy County, New Mexico

✓
Dodd Federal Unit #512
255' FNL & 330' FEL
Section 14, T-17S, R-29E
Eddy County, New Mexico

Dodd Federal Unit #513
660' FNL & 1295' FEL
Section 14, T-17S, R-29E
Eddy County, New Mexico

Dodd Federal Unit #514
250' FSL & 2310' FEL
Section 11, T-17S, R-29E
Eddy County, New Mexico

Dodd Federal Unit #515
1425' FSL & 330' FEL
Section 11, T-17S, R-29E
Eddy County, New Mexico

Dodd Federal Unit #516
1195' FSL & 1345' FEL
Section 11, T-17S, R-29E
Eddy County, New Mexico

Dodd Federal Unit #517
2615' FSL & 2615' FEL
Section 11, T-17S, R-29E
Eddy County, New Mexico

Dodd Federal Unit #518
2525' FSL & 1310' FEL
Section 11, T-17S, R-29E
Eddy County, New Mexico

Dear Bryan:

Marbob Energy has conducted a review to determine if an H2S contingency plan is required for the above referenced wells. We were able to conclude that any potential hazardous volume would be minimal. H2S concentrations of wells in this area from surface to TD are low enough; therefore we do not believe that an H2S Contingency Plan would be necessary.

Please advise us if you feel differently or need further information.

Sincerely,

Nancy T. Bratcher

Nancy T. Bratcher
Land Department

/nb