UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Ca	rlsbad F	ield	FORM APPROVED Code 004-0135 2010 31, 2010			
		5. Lease Serial No.				

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	

SUNDKI	NOTICES AND REPU	KIS ON WI	ELLO	· 17,22.18.2	B.A. INNEUDERGH 10D				
Do not use thi abandoned we	6. If Indian, Allottee or Tribe Name								
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.								
1. Type of Well Gas Well Got	8. Well Name and No. NOSLER FEDERAL 3								
Name of Operator BURNETT OIL COMPANY IN	9. API Well No. 30-015-38635-00-S1								
3a. Address 801 CHERRY STREET UNIT FORT WORTH, TX 76102-68	. (include area code 33-8730	e) ·	10. Field and Pool, or Exploratory FREN						
4. Location of Well (Footage, Sec., T	11. County or Parish, and State								
Sec 24 T17S R31E SESE 25F		EDDY COUNTY, NM							
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DA	ГА		
TYPE OF SUBMISSION		TYPE OF ACTION							
☑ Notice of Intent	☐ Acidize	Deepen		☐ Production (Start/Resume)		■ Water Shut-Off			
_	☐ Alter Casing	☐ Fracture Treat		Reclam Reclam	□ Reclamation		■ Well Integrity '		
☐ Subsequent Report	☐ Casing Repair	□ Nev	v Construction	☐ Recomp	olete		□ Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug	g and Abandon	▼ Temporarily Abandon					
	☐ Convert to Injection	Plug Back		☐ Water I	□ Water Disposal				
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Burnett is requesting an extension to the previously approved Temporary Abandonment of this well. The TA status was approved through 2/4/16 and Burnett is requesting a year extension to the TA status through the end of February 2017. We would like to keep this well in TA status in order to further study currently drilling and planned horizontal wells within the lease area before cutting a horizontal window into this existing vertical well. SEE ATTACHED FOR CONDITIONS OF APPROVAL Accepted for record NMOCD 21 5-1/16									
14. I hereby certify that the foregoing is	Electronic Submission #3	OIL COMPAN	Y INC, sent to the	he Carlsbad	•				
Name (Printed/Typed) LESLIE C	BARVIS	Title REGULATORY COORDINATOR							
Signature (Electronic S	Submission)	Date 01/20/2016							
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE				
Approved By TEUNGKU MUCHLI Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	TitlePETROLEUM ENGINEER Office Carlsbad			Date 05/04/2016					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	crime for any po to any matter w	erson knowingly an ithin its jurisdiction	d willfully to ma	ake to any department or	agency	of the United		

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Nosler Federal 3 30-015-38635

1. Well may be approved to be TA/SI for a period of 12 months or until <u>Date: 02/04/2017</u> after successful MIT and subsequent report is submitted.