Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT RY NOTICES AND THE

FORM APPROVED 010

	UMB NO. 1004-01
.	Expires: July 31, 20
)	5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS	JUL	19
. mak upa this farm for proposals to drill or to re anter	~	

NMLC029435B

abandoned wel	l. Use form 3160-3 (APE	)) for such proposals.	CEIVED	5. If Indian, Allottee o	r Tribe Name		
SUBMIT IN TRII	PLICATE - Other instruc			7. If Unit or CA/Agree	ement, Name and/or No.		
Type of Well		8. Well Name and No.					
☐ Oil Well ☐ Gas Well 🛛 Oth	er: INJECTION			JL KEEL B 7	<u></u>		
Name of Operator LINN OPERATING INCORPO	्Contact:   RATED E-Mail: İmoreno@li	_AURA A MORENO nnenergy.com		9. API Well No. 30-015-05108-0	10-S1		
Address 600 TRAVIS STREET SUITE HOUSTON, TX 77002	5100	3b. Phone No. (include area cod Ph: 713-904-6657 Fx: 832-209-4316	le)	10. Field and Pool, or Exploratory GRAYBURG			
Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish,	and State		
Sec.8 T17S R31E NENW 660	FNL 1980FWL		}	EDDY COUNT	Y, NM		
	1			•			
12. CHECK APPE	OPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA ,		
TYPE OF SUBMISSION		TYPE	OF ACTION				
	☐ Acidize	☐ Deepen	☐ Production	n (Start/Resume)	☐ Water Shut-Off		
Notice of Intent ,	☐ Alter Casing	☐ Fracture Treat	— Reclamat		☐ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recompl	ete	Other		
☐ Final Abandonment Notice	☐ Change Plans		☐ Tempora	rily Abandon			
	☐ Convert to Injection	☐ Plug Back	□ Water Di	sposal			
THE SUBJECT WELL FAILED OFFSET PRODUCTION HAS CURRENT ECONOMIC ENVI	BEEN OBSERVED SINC	E WELL HAS BEEN OFFL	INE. THIS WE	F DETRIMENTAL LL HAS NO UTILI	EFFECT IN TY IN THE		
PROPOSED PA PROCEDUR 1. SET 4 1/2 CIBP @ 2780°. C 2. SPOT 20 SX CMT @ 1410 3. PERF & SQZ 45 SX CMT @ 4. PERF & SQZ 65 SX CMT @	2940 IRC HOLE W/MLF, SPO 1 <del>2210</del> 1460 - 1260 0 650-550', WOC & TAG				TON PROCEDURE TACHED		
5. CUT OUT WELLHED AND	WELD ON DRY HOLE M	ARKER	SEE	<b>ATTACHED</b>	FOR		
*SEE ATTACHED CURRENT	& PROPOSED WBD'S				APPROVAL		
Ground level dry	, hole marke	- required	CON	DITIONS OF	ALLINOVAL		
. I hereby certify that the foregoing is	true and correct. Electronic Submission #3	342878 verified by the BLM W FING INCORPORATED, sent ng by CHRISTOPHER WALLS	/ell Information to the Carlsbad	0 A 27Ciii -	NWC		
Commit Name(Printed/Typed) LAURA A		' I	<b>S on 07/06/2016</b> JLATORY ADV		2 Podagood		
. Tamo (17 time at 1) peay LAOTA A	WORLING	This REGO	DEATORT ADV	10010			
Signature (Electronic S	ubmission)	Date 06/22	/2016				
	THIS SPACE FO	R FEDERAL OR STATE	OFFICE US	E			
pproved By the Walls		Title Er	vj .		Date 7/7/16		
ditions of approval, if any, are attached ify that the applicant holds legal or equ ch would entitle the applicant to condu	itable title to those rights in the						

#### LINN **NM Schematic** Energy Well Name: KEELJLB7INJ APMWID TO THE Name T Survey Eddy) County Township Townsh Ground Elevation (ft) Orig KB Elev (ft) 3.785.00 KB-Grd (ft) 0:00} Initial Spud Dale 5/25/1951 TD Date 3.785.00 Original Hole Data Original Hole, 5/18/2016 3 31;31 PM MD Wellbores: Vertical schematic (actual) (fixB) North-South Distance (It) East-West Distance (ft) NS Flag 660.0 1,980.0 FWL. Casing Strings 00 Csq Des 00 Noms | DINom | | WA en (IT | String Gr | 10|3/41 | 10.1925 | 32!751 | | H40| Surface 600.0 5/25/1951 Surface Casing Cement; 0.0-600.0 Cso Des Set Dept. DD Nomi 10 Nema 6:276 Willers (C Run Date Intermediate 2,916.0 26:00 5/26/1951 Weilbore; 12,000, 0.0-600.0 Cag Dea Sel Deot. DO Nom 1110 Nom WALen III Run Date Production 3,381.0 4/1/2 4!09 9:50 6/1/1964 -SALT (final) Cement Stages Surface; Casing; 0 0-Bim (ftKB) Eval Method Description Top (ftKS) Comment 100 Surface Casing 0.0 600.0 100 SXS CMT 600.0 Cement Eval Method Description 9800 200 SXS CMT. TOC Intermediate 980.0 2,916.0 Casing Cement 980' (CBL) 1 410.1 TANSILL (final) Description Ten (BKR) Bim (NKA) Eval Method Production 2.833.0 3,381.0 **CMT W/125 SXS ENCORE & 125 GALS** Casing Cement 1 6023 1 YATES (final) LAYTEX Wellbore, 8.000, 600.0-Tubing Strings 2,916.0 SEVEN RIVERS (fil Intermediate Casing Tubing Description Sel Depth 2,763,0 Run Dale 5/10/2011 Pul Date Cement; 980.0-2,916.0 Tubing Perforations QUEEN (final) Top :ftKB1 3.377.0 2,912.0 274.2 Top (fKB) Btm (fiKB) 2.990.0 3.258.0 Formations Friel Btm SALT. 575.0 1 408 0 37009 Fenal Top Fotal Bim TANSILL 1.410.0 3 753 8 YATES 1,600.0 Final Top SEVEN RIVERS 1,648.0 2 833 0 Final Top nal Bin Comment QUEEN 2,485.0 1 437.9 Final Top Final Btm Comment **GRAYBURG** 2,909.0 GRAYBURG (final) 29121 Intermediate, Casing, 0.0-2.916.0 Perforated; 2,990,0-**Production Casing** 3,258,0 Cement; 2,833.0-3,381.0 Wellbore, 6,250; 2 916,0-Perforated; 2,912.0-3,377.0 3 384 0 ŽШ 3 # 2,B 3 177 0 21718 Production Casing: 2 107 9 2,633.0-3,381.0 Wellbore: 3 875; 3,384 0-3.821.0 71109 Wellbore; 3,821,0 3 (30) ( Report Printed: 5/18/2016 www.peloton.com Page 1/1

皿	NW Schematic									
Well	版) Name: KEELJLB7INJ									
				····						
30015	Fieto Name  Figure Pagaveurg West C				017-S		31 E	Surviva	Block	12.00
Ground 3,785	Elevation (ft) Ong KB Elev (ft) XB-Grd (ft) = 0:000 (ff : 2)	Inital Spud 5/25/195	Date Rig Release Date TO	Date	32	iude (1) (7) 25 1:11 5.9	387NF32A	Longitude ( 1034/53)	38.522 W	Yes A
	Original Hole, 6/20/20	16 2.48:38 PI	vi -	]		. (	Original	Hole Data	l	
MD (ftKB)	Vertical sche	matic (actual	)	Welibores .	, ·		3 10 dig quader y E			
,b,		,		North-South Dis 660.0			NS Flag FNL	East-West Dist 1,980.0	ance (II)	EW Flag FWL
B.G	Marie and American Street, and a series of the series of t		Cement Plug, 0.0-200.0	Casing Stri	s	et Dept.   Di	D Namu (D:N	om. : WV en (	II Bung Grade	
46.9			Surface Casing Cement,	Surface Csg Des	5	et Dept. ID	D Nom I ID N	1921 32.75	12 Carica Grade	5/25/1951 Run Date
2021	Perforated PROPOSED:		0.0-600 0 Wellbors: 12.000; 0.0-	Intermediate Csg Des		.916.0 7, et Dept.   Di	5.2 D Nom (1 D' N	76. 25.00	SE Song Grade	5/26/1951 T Run Date
	200.0		600.0 Cement Plug: 550.0-	Production Cement Sta		381.0 4	1/2 4:0	9 (19:50:	)  b/55	6/1/1964
549.9			650.0	Description Cement Plu	_	Top (NK8)	21	Eval Method	Comment	D: Set CIBP at
£7%:	— SALT (final) ————			Joennesit Flu	_	2780	2940	2940	2789'. Cap	
ea.			Surface, Casing; 0.0-	Description		Top (RKB)	Sim (RXS)	Eval Method	Comment	D. D
4419	Perforated PROPOSED,		200.0	Cement Plu	<b></b>	1 <del>,210.</del> 0 1260	1.410.0		cmt 1410-1	D: Spot 20 sks 210.
	650,0	्म.		Cement Ptu	.g	Top (NKB) 550.0	8tm (ftX8) 650.0	Eval Method		D: Perf & Sqz
umt d		<b>3</b> 0	1260	Description		Top (fiKB)	Birm (ftKB)	Eval Method	45 sks cmt	650-550.
1,7*80			Cement Plug 1:210.0- 	Compat Ph	ıg	0.0	200.0			D: Perf & Sqz 200-surface.
1 452 1	TANSILL (final)	<b>***</b> _	1460	Description Surface Ca	sina	Top (fiKB)	Etrn (ftKB) 600.0	Eval Method	Comment 100 SXS C	
16501	— YATES (final)	4.		Cement	0			Eval Method	Comment	
		31	Wellbore; 8.000; 600.0- / 2,916 0	Intermediat Casing Cen		Top (MKB) 980.0	8tm (ftKB) 2,916.0	COMMENS.	200 SXS C 980' (CBL)	MT. TOC
18480	- SEVEN RIVERS (fi		tntermediate Casing Cement; 980.0-2,916,0	Description	i e i il	Top (RKB)	Birn (ftKB)	Eval Method	Comment	z cvc
2 444 7	QUEEN (final)		2780 -	Production Casing Cen	nent	2,833.0	3,381.0			5 SXS L 125 GALS
27354	i i i i i i i i i i i i i i i i i i i	***	Cement Plug: 2-720;0- 	Tubing Str	ings	l	ــــــــــــــــــــــــــــــــــــــ	.l	LAYTEX	·
277 <b>9-9</b>			2940 WOLFING	Tம்ற Descripti Tubing	ton	_		Depth R = D		Full Date 5/1/2016
2785			Bridge Plug - Permanent: 2. <del>780.0-2.785.</del> 0; 6 000	Perforation	19. Etm (f	ve. To	omment			
			2940	200.0	200.	D			·	
71336				Top (flKB) 650.0	8tm (f 650.		omment			
26273				Top (ftKB) 2,912.0	8tm (f) 3,37	7.0	omment			
7 859-1	GRAYBURG (final)	⊴1 _	· · · · · · · · · · · · · · · · · · ·	Top (RKB) 2,990.0	8tm (f 3,25		omment			····
2 912 1		38		Other In He		Top (RKB)	Born (NKB)	Run Date	1	Com
	3 R (s)		Intermediate, Casing: 0 0-	Bridge Plug Permanent	i -	2.780.0	2,785.0			
2 916:	Perforated; 2,990 0-	A COLOR	2.916.0 Production Casing	Formations			1 			
2 99012	3,258.0 Perforated; 2,912.0-	3 211	Cement, 2,833 0-3,381.0 Wellbore, 6,250, 2,916.0-	Formation SALT		575.0	1,408.0	Comment		
3 <del>2</del> 7 6	3,377.0	15 Kg	3 384.0	Formation TANSILL		Final Top. 1,410.0		Comment		
ל זוגנ				Formation YATES		Final Top. 1,500.0		Comment		
			•	Formation SEVEN RIV	/ERS	Final Top 1,648.0		Comment		
12039		jiÿ ∥		Formation QUEEN		Final Top 2,485.0	Final Bim	Comment		
3.3802 0		1	Production; Casing: 2.833.0-3.381.0	Formation GRAYBUR		Final Top 2,909,0	Final Bim	Comment		
1 2423.9	in the second second		Malbara 2 075 0 004 5	3.01,000		12,500,0	<del></del>	L	· ·	·,• <del>=</del> , -· ·-
1499		3-1-1-	Welfbore, 3,875; 3,384,0- 3,821,0	-						
74559	ET.	ш <b>г</b>								
1488	nafatan nam			<u> </u>	···········	1	<u></u>	· M -	nost 11-2	. 6/20/2045
WWW.	peloton.com		Page 1/1	١.				Re	part Ennted	: 6/20/2016

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 1 9 2016

RECEIVED

### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C"; for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/Condition of Approval for Lesser Prairie-Chicken:

From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



# United States Department of the Interior

#### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

#### Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work. needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Linda Denniston Environmental Protection Specialist 575-234-5974

Henryetta Price Environmental Protection Specialist 575-234-5951

Dara Glass Environmental Protection Specialist 575-234-5924

Shelly Tucker Environmental Protection Specialist 575-234-5979