Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD	Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMNM0404441

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			L		
			6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agre	ement, Name and/or No.	
1. Type of Well			8. Well Name and No.		
☑ Oil Well ☐ Gas Well ☐ Oth	TODD 13E FEDE	.RAL 20			
Name of Operator Contact: LINDA GOOD DEVON ENERGY PRODUCTION CO EPMail: linda.good@dvn.com			9. API Well No. 30-015-32632-00-S1		
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102	Ph: 4	one No. (include area code) 05-552-6558	10. Field and Pool or INGLE WELLS-	10. Field and Pool or Exploratory Area INGLE WELLS-DELAWARE	
4. Location of Well (Footage, Sec., T		11. County or Parish,	11. County or Parish, State		
Sec 13 T23S R31E SWNW 19		EDDY COUNTY	Y, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	DICATE NATURE OF	NOTICE, REPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
The Control of the Co	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
☑ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	□ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	▼ Temporarily Abandon		
	☐ Convert to Injection	Plug Back	□ Water Disposal		
recompletion.	., L.P. respectfully requests to sh	ut-in this well to evalua	•	or record CD 2/28/17 DATE HAS PASSED,	
Act The St	NA DISTRICT	DEE ATTACHED FOR		7-011	
FER 2 2 300. SEE ATTACHED FOR CONDITIONS OF APPRO			AL APROVAC	DATE HAS	
RE	CEIVE		ATTER 1811	TABLE,	
14. I hereby certify that the foregoing is Comm Name (Printed/Typed) LINDA GO	Electronic Submission #349363 For DEVON ENERGY PRO itted to AFMSS for processing by	DUCTION CO LP, sent t DEBORAH MCKINNEY o	o the Carlsbad		
Signature (Electronic S	Submission)	Date 08/29/20	016		
	THIS SPACE FOR FEI	DERAL OR STATE (OFFICE USE		
Approved By CHARLES NIMMER		TitlePFTROLFU	JM ENGINEER	Date 02/14/2017	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		ant or			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for	r any person knowingly and		r agency of the United	

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

TODD 13E FEDERAL 26

- 1. Well is approved to be TA/SI for a period of 12 months or until 2/14/17
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 2/14/17
- 3. COA's met at this time.