В	UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANAC NOTICES AND REPOF	GEMENT	00	D-ARTI	QMB N	I APPROVED NO. 1004-0137 January 31, 2018	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well       1. Type of Well      Image: Second state of the second state of	her		<u></u>		8. Well Name and No LITTLEFIELD AI		
2. Name of Operator Contact: SHEILA A FISHER DEVON ENERGY PRODUCTION CO EPMail: Sheila.Fisher@dvn.com					9. API Well No. 30-015-20362		
3a. Address PO BOX 250 ARTESIA, NM 88211	3b. Phone No. (include area code) Ph: 575-748-1829			10. Field and Pool or Exploratory Area SHUGART YATES			
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)				11. County or Parish EDDY COUNT		
	PPROPRIATE BOX(ES)	TO INDICATE NA	TURE O	F NOTICE,	REPORT, OR OT	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> </ul>	<ul> <li>Acidize</li> <li>Alter Casing</li> </ul>	Deepen Hydraulic	Ũ	🗖 Reclama		<ul> <li>Water Shut-Off</li> <li>Well Integrity</li> </ul>	
Final Abandonment Notice	<ul> <li>Casing Repair</li> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	<ul><li>New Const</li><li>Plug and A</li><li>Plug Back</li></ul>		<ul> <li>Recomp</li> <li>Tempora</li> <li>Water D</li> </ul>	arily Abandon	☐ Other	
<ol> <li>Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wi following completion of the involve testing has been completed. Final A determined that the site is ready for</li> <li>This well is producing from</li> <li>Water produced is approx</li> <li>There is one 500bbl wated</li> <li>Water will be piped to the AB Battery via transfer pump 14(location of this well includ suction tanks and it is dispos Shugart Unit 3(location of Un a) API # 30-015-20434 and b</li> </ol>	hally or recomplete horizontally, ork will be performed or provide d operations. If the operation res- bandonment Notices must be file final inspection. In the Shugart Yates. A simately 8 BWPD In tank located at the Littlefie a) Littlefield Waterflood Pri to 3 injection wells one of ed) b.) East Shugart Unit W ed into 12 injection wells vi it 3 included)a.) Devon En- b) API # 30-015-05683.	give subsurface location the Bond No. on file wi sults in a multiple comp ed only after all required SEE / CONDITI( eld AB Fed Battery. oject-water travels which is the Littlefic Vaterflood Facility v ia trunk line one of ergy Corporation b.	is and measu th BLM/BIA letion or reco nents, includ NTTACHEL NS OF AI irom the Li eld AB Feo vhere it tra which is th Magua Su	red and true ve: Required sub- impletion in a n ing reclamation PROVAL ittlefield vels to e.East cia,LLC. if for record	rtical depths of all per sequent reports must l ew interval, a Form 3	tinent markers and zones. be filed within 30 days 160-4 must be filed once d and the operator has	
14. I hereby certify that the foregoing Name (Printed/Typed) SHEILA	Electronic Submission #3 For DEVON ENERG Committed to AFMSS for p	SY PRODUCTION CO	RAH MCKI	to the Carlsb	ad 13/2016 ()	ML CONSERVATIO Artesia district APR 1 0 2017	
Signature (Electronic	Submission)	Date	11/30/2	016		RECEIVED	
)	THIS SPACE FO	R FEDERAL OR	STATE	OFFICE US	SE		
_Approved By	Juch	Title	Ef	2V		3/31/17	
Conditions of approval it any, are attach certify that the applicant holds legal or ex which would entitle the applicant to cond	ustable title to those rights in the	not warrant or subject lease Offic	e C	W			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ke to any department	or agency of the United	

### Additional data for EC transaction #359320 that would not fit on the form

#### 32. Additional remarks, continued

5. a) SW4SE4, Sec 22, T18S, R31E b) NE4NE4, Sec 34, T18S, R31E

6. a) R-4438 b) R-3059

.

÷

# WATER PRODUCTION & DISPOSAL INFORMATION

\*In order to process your disposal request, the following information must be completed in full\*

Site Name: Littlefield AB Fed 13

1. Name(s) of formation(s) producing water on the lease: Shugart Yates

2. Amount of water produced from all formations in barrels per day: 8bbls

4. How water is stored on lease: 1 500bbl water tank at the Littlefield AB Fed Battery

5. How water is moved to the disposal facility: Piped

6. Identify the Disposal Facility by:

A. Facility Operators Name: a) Devon Energy Corporation b) Agua Sucia LLC

B. Facility or well name/number: a) Littlefield Waterflood Project-water travels from the Littlefield AB Battery via transfer pump to 3 injection wells one of which is the Littlefield AB Fed 14(location of this well included) b) East Shugart Unit Waterflood Facility-water travels to suction tanks where it is disposed into 12 injection wells via trunk line one of which is the East Shugart Unit 3(location of Unit 3 included)

C. Type of Facility or well (WDW) (WIW): a) WIW b) WIW

D.1) Location by <sup>1</sup> / <sub>4</sub> <sup>1</sup> / <sub>4</sub> SW/4 SE/4	Section 22	Township 18S	Range 31E
D.2) Location by <sup>1</sup> / <sub>4</sub> <sup>1</sup> / <sub>4</sub> NE/4 NE4	Section 34	Township 18S	Range 31E

Submit to this office, 620 EAST GREENE ST, CARLSBAD NM, 88220, the above required information on a Sundry Notice 3160-5. Submit 1 original and 5 copies, within abatement period. (This form may be used as an attachment to the Sundry Notice.)

30-015-20299 ORRID 169355 PROP 23446 POOI 56439

IT IS THEREFORE ORDERED:

11-16-12 R-4438

5-7-70

Radioactivity Log

(1) That the applicant, Gulf Oil Corporation, is hereby authorized to institute a waterflood project in the Shugart Yates-Seven Rivers, Queen-Grayburg Pool by the injection of water into the Queen formation through the following-described wells in Section 22, Township 18 South, Range 31 East, NMPM, Eddy County, New Mexico:

Federal "AB" Littlefield Well No. 9, Unit H Federal "AB" Littlefield Well No. 10, Unit B Federal "AB" Littlefield Well No. 14, Unit O

(2) That injection in each of the aforesaid wells shall be through internally plastic-coated tubing set in a packer located as near as is practicable to the uppermost perforation; that the casing-tubing annulus of each injection well shall be loaded with an inert fluid and equipped with a pressure gauge at the surface.

m 9-331 ay 1963)				
	U TED STATES	SUBMIT IN TRI		R1424.
DEPA	ARTMEINT OF THE INTER	lor verse side)	5. LEASE DESIGNATION AND SERIAL	
	GEOLOGICAL SURVEY	1 pri th	LC 029392 (a)	
SUNDRY N	NOTICES AND REPORTS	ON WELLS	6. IF INDIAN, ALLOTTER OR TRIBE	NAME
(Do not use this form for	proposals to drill or to deepen or plug	back to a different reservoir.		
Use "AF	PPLICATION FOR PERMIT-" for such	proposals.)		
OIL GAS			7. UNIT AGREEMENT NAME	
WELL WELL OT	HER	RECEIN	8. FARM OR LEASE NAME	
	efining Company			
ADDRESS OF OPERATOR	erraria content		Hinkle #A*	
•	, Rosvell, New Maxi			
LOCATION OF WELL (Report loca	ation clearly and in accordance with an	ly State requirements.	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface		ARTESIA, OFF	14 Shugart-Queen	
0001 MMT 3301			IT. BBC, T., K., M., UK BUK. AND	
AAA. 1801 326.	FEL (Unit Letter A	· J	SUBVET OR AREA	
			Sec. 34, 7-185,	R 3
PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATI	£
			Rđđy R	.н.
Cher	ck Appropriate Box To Indicate	Nature of Notice Report or		
			그 같은 눈 수 있는 것 같이 것 같이 않는 것 않는 것 같이 않는 것 같이 않는 것 않는	
NOTICE OF	INTENTION TO:	80382	QUENT EEPORT OF: .	
TEST WATES SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		_
FRACTURE TREAT	MULTIPLE COMPLETE	FBACTURE TREATMENT	ALTEBING CASING	_
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*	_
REPAIR WELL	CHANGE PLANS	(Other)	ts of multiple completion on Well	
	O Water injection X TED OPERATIONS (Clearly state all pertin	Completion or Recom	pletion Report and Log form.)	
	as in the following		ter an	
1. Set CI	BP in 7" casing at	34801.		
	ate Yates and Queen		-	07
2813.	2818, 3324 ± 3330'	(6 boles).		
	these new perfs w/l			
	<b>E.</b> Frac $\sqrt{30.000}$ g			
sealer		allong of freeb w		
sealer: send.		allons of fresh w	ter 4 30,000# of 2	
sand.			ster & 30,0000 of ;	20/4
send. 4. Run on	e string of 2" tubi	ng w/hookwall pack	ster & 30,0000 of ;	20/4
sand. 4. Run on: 5. Inject	e string of 2" tubi water into above n	ng w/hookwall pack	ster & 30,0000 of ;	20/4
sand. 4. Run on: 5. Inject	e string of 2" tubi	ng w/hookwall pack	ster & 30,0000 of ;	20/4
sand. 4. Run on: 5. Inject	e string of 2" tubi water into above n	ng w/hookwall pack	ster & 30,0000 of ;	20/4
sand. 4. Run on: 5. Inject	e string of 2" tubi water into above n	ng w/hookwall pack	ster & 30,0000 of ;	20/4
send. 4. Run on: 5. Inject	e string of 2" tubi water into above n	ng w/hookwall pack	ster & 30,0000 of ;	20/4
send. 4. Run on: 5. Inject	e string of 2" tubi water into above n	ng w/hookwall pack	ster & 30,0000 of ;	20/4
send. 4. Run on: 5. Inject	e string of 2" tubi water into above n	ng w/hookwall pack	ster & 30,0000 of ;	20/4
sand. 4. Run on 5. Inject 2735 au	e string of 2" tubi water into above n nd 3402 to 3440.	ng w/hookwall pack	ster & 30,0000 of ;	20/4
send. 4. Run on 5. Inject 2735 au hereby certif	e string of 2" tubi water into above m nd 3402 to 3440.	ng w/hookwall pack ew perfs and exist	Ar bet at 2590'. ing parts 2632 to MAY Support of the second se	20/4
send. 4. Run one 5. Inject 2735 au hereby certh <b>Originale Sigg</b> O. D. Bratche	e string of 2" tubi water into above m nd 3402 to 3440.	ng w/hookwall pack	Ar bet at 2590'. ing parts 2632 to MAY Support of the second se	20/4
send. 4. Run ond 5. Inject 2735 at 2735 at 275	e string of 2" tubi: water into above m nd 3402 to 3440.	ng w/hookwall pack ew perfs and exist	Ar bet at 2590'. ing parts 2632 to MAY Support of the second se	20/4
send. 4. Run ond 5. Inject 2735 au 1 hereby certif <b>Originale Sigg</b> SIGNEDO. D. Bretche	e string of 2" tubi: water into above m nd 3402 to 3440.	ng w/hookwall pack ew perfs and exist	Ar bet at 2590'. ing parts 2632 to MAY Support of the second se	20/4
send. 4. Run ond 5. Inject 2735 and 1 hereby certh <b>Originale Sugar</b> SIGNED O. D. Bretcher (This space for Federal or State)	e string of 2" tubi: water into above m nd 3402 to 3440.	ng w/hookwall pack ew perfs and exist	Ar bet at 2590'. ing parts 2632 to MAY Support of the second se	20/4
send. 4. Run ond 5. Inject 2735 and 1 hereby certh <b>Originale Sugar</b> SIGNED O. D. Bretcher (This space for Federal or State)	e string of 2" tubi: water into above m nd 3402 to 3440.	ng w/hookwall pack ew perfs and exist	Expet at 2590'. ing parts 2632 to MAY of the second seco	20/4
send. 4. Run ond 5. Inject 2735 an 2735 an Anticipation of the Sign IGNED O. D. Bretcher This space for Federal or Sta	e string of 2" tubi: water into above m nd 3402 to 3440.	ng w/hookwall pack ew perfs and exist	Expet at 2590'. ing parts 2632 to MAY of the second seco	20/4
send. 4. Run ond 5. Inject 2735 and 1 hereby certiforginale Sigger BIGNED O. D. Bretcher (This space for Federal or State O. D. Bretcher (This space for Federal or State O. D. Bretcher (This space for Federal or State O. D. Bretcher (This space for Federal or State) O. D. Bretcher (This space for Federal or State) (This space for Federal or State)	e string of 2" tubi: water into above m nd 3402 to 3440. rebag is true and correct <u>s</u>	ng w/hookwall pack ew perfs and exist ist. Drilling Supe	Expet at 2590'. ing parts 2632 to MAY of the second seco	20/4
send. 4. Run ond 5. Inject 2735 and 1 hereby certh <b>Originale Sugar</b> SIGNED O. D. Bretcher (This space for Federal or State)	e string of 2" tubi: water into above m nd 3402 to 3440. rebag is true and correct <u>s</u>	ng w/hookwall pack ew perfs and exist	Expet at 2590'. ing parts 2632 to MAY of the second seco	20/4
send. 4. Run ond 5. Inject 2735 and 1 hereby certiforginale Sigger BIGNED O. D. Bretcher (This space for Federal or State O. D. Bretcher (This space for Federal or State O. D. Bretcher (This space for Federal or State O. D. Bretcher (This space for Federal or State) O. D. Bretcher (This space for Federal or State) O. D. Bretcher (This space for Federal or State) (This space) (This space for Federal or State) (This space) (This	e string of 2" tubi: water into above m nd 3402 to 3440. rebag is true and correct <u>s</u>	ng w/hookwall pack ew perfs and exist ist. Drilling Supe	Expet at 2590'. ing parts 2632 to MAY of the second seco	20/4

# BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Disposal of Produced Water From Federal Wells Conditions of Approval

Approval of the produced water disposal methodology is subject to the following conditions of approval:

- 1. This agency shall be notified of any change in your method or location of disposal.
- 2. Compliance with all provisions of Onshore Order No. 7.
- 3. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 4. This agency reserves the right to modify or rescind approval whenever it determines continued use of the approved method may adversely affect the surface or subsurface environments.
- 5. Any on-lease open top storage tanks shall be covered with a protective cover to prevent entry by birds and other wildlife.
- 6. This approval should not constitute the granting of any right-of-way or construction rights not granted by the lease instrument.
- 7. If water is transported via a pipeline that extends beyond the lease boundary, then you need to submit within 30 days an application for right-of-way approval to the Realty Section in this office if you have not already done so.
- 8. Disposal at any other site will require prior approval.
- 9. Subject to like approval by NMOCD.

7/10/14