Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 expires: January 31, 2018

	Expires:	Januar
5.	Lease Serial No.	
	NMNM02864	

SUNDRY N	OTICES AND	REPORTS	ON WELL	.S
Do not use this	form for propo	sals to drill	or to re-ent	er an
handanad wall				

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well					8. Well Name and No. POKER LAKE UNIT 170		
Name of Operator BOPCO LP Contact: TRACIE J CHERRY E-Mail: tracie_cherry@xtoenergy.com					9. API Well No. 30-015-31744-00-S1		
3a. Address 6401 HOLIDAY HILL RD BLD MIDLAND, TX 79707	. (include area code) 3.2277		10. Field and Pool or Exploratory Area NASH DRAW-DELAWARE				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, State		
Sec 33 T23S R30E NESW 21			EDDY COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE, I	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Production	on (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclamat	ion	■ Well Integrity	
Subsequent Report	□ Casing Repair	□ New	Construction	□ Recompl	ete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	🛭 Plug	gand Abandon	- •	rily Abandon		
	☐ Convert to Injection	Plug	g Back	□ Water Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BOPCO, LP respectfully submits this sundry notice to report plug and abandonment of the referenced well. 01/05/18 - 01/09/18 MIRU. ND WH NU BOP. POOH w/packer and tbg. PU workstring, tag PBTD @ 7803'. Spot 50 sx H cmt or top. WOC. Tag @ 7405'. BLM witnessed. 01/10/18 RIH w/4-1/2" CIBP to 4200'. Tag to verify setting. Circulated salt gel mud, pressure test to 500 PST (good). Spot 90 sx C cmt to 2810' RECLANATION BUR AU SE LAND MANAGEMENT OARS SAD FIELD OFFICE							
	epted for record - NMC	ocd DUI	8-16-	18	<u> </u>	TO THE CHIEF	
14. I hereby certify that the foregoing is	Electronic Submission #	BOPCO LP, se	ent to the Carlsba	d	5.44 5.73%	CONSERVATION	
Name (Printed/Typed) TRACIE J	CHERRY		Title REGUL	ATORY ANA	•	EAD 1 9 2019	
Signature (Electronic Submission) Date 02/27/201				018	To the state of th	PECEME	
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	E		
_Approved By			Title			Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the appli	sitable title to those rights in the		Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #405878 that would not fit on the form

32. Additional remarks, continued

Tag TOC @ 2875'. Perf sqz holes 2800' and 930', set pkr @ 983'. Establish injection rate, sqz 360 sx. Unset pkr. WOC.

01/12/18
Tag TOC 1395'. BLM required additional 45 sx C be spotted to bring cmt above 850'. Spot cmt, WOC. Tag @ 775'. BLM ok'd. Perf @ 60'. Circulate 20 sx mt to surface.

02/16/18 Cut of WH. Install P&A marker. Backfill. Well P&A'd