Office.	State of New	Mexico	Form C-103
Office District I	Energy, Minerals and	Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVAT	ION DIVISION	30-015-34644
District III	1220 South St.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NI		STATE STEE
District IV	Santa Pe, INI	VI 0/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			35467
	ICES AND REPORTS ON WI	ELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO			Livingston Ridge 36 State
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FORM C-1	01) FOR SUCH	8. Well Number 1
	Gas Well 🛛 Other		
2. Name of Operator	Gas Well 23 Outer	05050/50	9. OGRID Number 20165
Samson Resources Company		RECEIVED	5. OGRID Number 20103
3. Address of Operator		APR 1 8 2006	10. Pool name or Wildcat
Two West Second Street, Tulsa, O	k. 74103		Sand Dunes; Morrow, North (Gas)
4. Well Location		OCU-ARTESIA	
1		4. 1:	1 0002 food for made a Fred Line
Unit Letter O	<del></del>	outh line and	
Section 36	Township 22S		NMPM Eddy County
ARMED TO STANKE USE OF	11. Elevation (Show whethe	r DR, RKB, RT, GR, etc.)	
Pia C P. L. A. L.	3471 GL		
Pit or Below-grade Tank Application	<del></del>		
Pit typeDepth to Groundv	vaterDistance from nearest f	resh water well Dist	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	nstruction Material
12. Check	Appropriate Box to Indica	te Nature of Notice,	Report or Other Data
NOTICE OF IN	ITENTION TO	CUD	CEOUENT DEPORT OF
	TENTION TO:	L. Company of the com	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPL	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER:	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐ F JOB ☑
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13: Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly states)	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and	ALTERING CASING LLING OPNS. P AND A D STORM STOR
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or compof starting any proposed w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly states)	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐ F JOB ☑
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13: Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly states)	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and	ALTERING CASING LLING OPNS. P AND A D STORM STOR
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:	PLUG AND ABANDON CHANGE PLANS DILETCH COMPL DILETCH COMPLETE DILETCH COMPLET	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At	ALTERING CASING LLING OPNS. P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mi	PLUG AND ABANDON CHANGE PLANS DIED CHANGE PLANS DIED COMPL DIED COMPLET D	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  C. Cemented with 430 sacks of surface. Tested pipe rams, blind	ALTERING CASING LLING OPNS. P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:	PLUG AND ABANDON CHANGE PLANS DIED CHANGE PLANS DIED COMPL DIED COMPLET D	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  C. Cemented with 430 sacks of surface. Tested pipe rams, blind	ALTERING CASING LLING OPNS. P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mi	PLUG AND ABANDON CHANGE PLANS DIED CHANGE PLANS DIED COMPL DIED COMPLET D	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  C. Cemented with 430 sacks of surface. Tested pipe rams, blind	ALTERING CASING LLING OPNS. P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mi	PLUG AND ABANDON CHANGE PLANS DIED CHANGE PLANS DIED COMPL DIED COMPLET D	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  C. Cemented with 430 sacks of surface. Tested pipe rams, blind	ALTERING CASING LLING OPNS. P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mi	PLUG AND ABANDON CHANGE PLANS DIED CHANGE PLANS DIED COMPL DIED COMPLET D	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  C. Cemented with 430 sacks of surface. Tested pipe rams, blind	ALTERING CASING LLING OPNS. P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mimanifold 250 psi low and 2500 psi high. Wall hereby certify that the information	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Marked at 14.8 ppg. Circulated 53 Bbls to ited 22 hours before drilling out cemental above is true and complete to	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  3'. Cemented with 430 sacks of surface. Tested pipe rams, blind t.	ALTERING CASING LLING OPNS. P AND A D T JOB D D D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mimanifold 250 psi low and 2500 psi high. Wall hereby certify that the information	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Marked at 14.8 ppg. Circulated 53 Bbls to ited 22 hours before drilling out cemental above is true and complete to	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  3'. Cemented with 430 sacks of surface. Tested pipe rams, blind t.	ALTERING CASING LLING OPNS. P AND A D T JOB D D D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mimanifold 250 psi low and 2500 psi high. Wall hereby certify that the information grade tank has been/will be constructed or	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Marked at 14.8 ppg. Circulated 53 Bbls to ited 22 hours before drilling out cement above is true and complete to relosed according to NMOCD guided.	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  3'. Cemented with 430 sacks of surface. Tested pipe rams, blind t.  the best of my knowledge lines □, a general permit □	ALTERING CASING LLING OPNS. P AND A DIT JOB DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mimanifold 250 psi low and 2500 psi high. Wall hereby certify that the information	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Marked at 14.8 ppg. Circulated 53 Bbls to ited 22 hours before drilling out cemental above is true and complete to	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  3'. Cemented with 430 sacks of surface. Tested pipe rams, blind t.  the best of my knowledge lines  , a general permit	ALTERING CASING LLING OPNS. P AND A DIT JOB DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or composed was or recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 min manifold 250 psi low and 2500 psi high. Was I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Mark Mark Mark Mark Mark Mark Mark Mar	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  Commented with 430 sacks of surface. Tested pipe rams, blind the best of my knowledge lines  a general permit  EDTIlling Engineer	ALTERING CASING LLING OPNS. P AND A DIT JOB DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER:  13. Describe proposed or compost of starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mimanifold 250 psi low and 2500 psi high. Was I hereby certify that the information grade tank has been/will be constructed of SIGNATURE SIGNATURE Total Wiley For State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Modern Market 14.8 ppg. Circulated 53 Bbls to ited 22 hours before drilling out cement above is true and complete to relosed according to NMOCD guide TITI	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  Commented with 430 sacks of surface. Tested pipe rams, blind the best of my knowledge lines  a general permit  EDTIlling Engineer	ALTERING CASING LLING OPNS. P AND A DIT JOB DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER:  13. Describe proposed or compost of starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mimanifold 250 psi low and 2500 psi high. Was I hereby certify that the information grade tank has been/will be constructed of SIGNATURE SIGNATURE Total Wiley For State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Modern Market 14.8 ppg. Circulated 53 Bbls to ited 22 hours before drilling out cement above is true and complete to relosed according to NMOCD guide TITI	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  Commented with 430 sacks of surface. Tested pipe rams, blind the best of my knowledge lines  a general permit  EDTIlling Engineer	ALTERING CASING LLING OPNS. P AND A DIT JOB DI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER:  13. Describe proposed or compost of starting any proposed wor recompletion.  3/25/06 17:00 Spud Well. 3/26/2006 Set 13:365 sacks of Premium Plus w/ 2% CaCl2 mimanifold 250 psi low and 2500 psi high. Was I hereby certify that the information grade tank has been/will be constructed of SIGNATURE SIGNATURE Total Wiley For State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly statork). SEE RULE 1103. For Mark Mark Mark Mark Mark Mark Mark Mar	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: e all pertinent details, and fultiple Completions: At  3'. Cemented with 430 sacks of surface. Tested pipe rams, blind t.  the best of my knowledge lines □, a general permit □  LE Drilling Engineer fley@samson.com Te	ALTERING CASING LLING OPNS. P AND A DIT JOB DI

Office	State of New Mexico	Form C-103		
210111411	rgy, Minerals and Natural Resources	May 27, 2004 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II	CONCEDIATION DIVIGION	30-015-34644		
1301 W. Gialia Avc., Attesia, INVI 60210	L CONSERVATION DIVISION	5. Indicate Type of Lease		
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE STATE		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
87505		35467		
SUNDRY NOTICES AND		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DE DIFFERENT RESERVOIR. USE "APPLICATION FOI		Livingston Ridge 36 State		
PROPOSALS.)		8. Well Number 1		
1. Type of Well: Oil Well Gas Well 2. Name of Operator	☑ Other	9. OGRID Number 20165		
Samson Resources Company	RECEIVED	9. OGRID Number 20103		
3. Address of Operator	APR 1 8 2006	10. Pool name or Wildcat		
Two West Second Street, Tulsa, Ok. 74103		Sand Dunes; Morrow, North (Gas)		
4. Well Location	OCD-AHTESIA			
Unit Letter O : 660	feet from theSouth line and	1,980'feet from theEastline		
Section 36	Township 22S Range 31E	NMPM Eddy County		
	vation (Show whether DR, RKB, RT, GR, et			
3471 GL				
Pit or Below-grade Tank Application or Closure				
		stance from nearest surface water		
		Construction Material		
12. Check Appropris	ate Box to Indicate Nature of Notice	, Report or Other Data		
	1			
NOTICE OF INTENTION	ON TO: SU	RSEQUENT REPORT OF		
NOTICE OF INTENTIC PERFORM REMEDIAL WORK   PLUG A	ON TO: SUI AND ABANDON □ REMEDIAL WO	BSEQUENT REPORT OF:  RK □ ALTERING CASING □		
PERFORM REMEDIAL WORK PLUG A	NND ABANDON ☐ REMEDIAL WO			
PERFORM REMEDIAL WORK PLUG A	NND ABANDON ☐ REMEDIAL WO	RK		
PERFORM REMEDIAL WORK  PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP	REMEDIAL WO SE PLANS COMMENCE DI CASING/CEME	RK		
PERFORM REMEDIAL WORK  PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP OTHER:	REMEDIAL WO SE PLANS	RK		
PERFORM REMEDIAL WORK  PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed operator of starting any proposed work). SEE	REMEDIAL WO SE PLANS COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed operations.	REMEDIAL WO SE PLANS COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.	REMEDIAL WO SE PLANS COMMENCE DE CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions:	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo	REMEDIAL WO COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A cented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme	REMEDIAL WO COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A cented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo	REMEDIAL WO COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A cented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo	REMEDIAL WO COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A cented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo Tested casing to 1500 psi for 30 minutes, ok. Waited 19.5	REMEDIAL WO COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: An are and complete to the best of my knowled  True and complete to the best of my knowled	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo Tested casing to 1500 psi for 30 minutes, ok. Waited 19.5	REMEDIAL WO COMMENCE DI CASING/CEME  OTHER: ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: An are and complete to the best of my knowled  True and complete to the best of my knowled	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed operator of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615". Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo Tested casing to 1500 psi for 30 minutes, ok. Waited 19.5  I hereby certify that the information above is trigrade tank has been/will be constructed or closed accounts.	REMEDIAL WO COMMENCE DE CASING/CEME  OTHER:  ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A  cented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000 hours before drilling out cement.  True and complete to the best of my knowled reding to NMOCD guidelines , a general permit [	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed operator of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo Tested casing to 1500 psi for 30 minutes, ok. Waited 19.5  I hereby certify that the information above is trested tank has been/will be constructed or closed according to 1500 psi for 30 minutes.	REMEDIAL WO COMMENCE DE CASING/CEME  OTHER:  ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A  ented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000 hours before drilling out cement.  Tue and complete to the best of my knowled rding to NMOCD guidelines   TITLE Drilling Engine	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo Tested casing to 1500 psi for 30 minutes, ok. Waited 19.5  I hereby certify that the information above is tr grade tank has been/will be constructed or closed accord  SIGNATURE	REMEDIAL WO COMMENCE DE CASING/CEME  OTHER:  ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A  ented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000 hours before drilling out cement.  Tue and complete to the best of my knowled rding to NMOCD guidelines , a general permit [	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo Tested casing to 1500 psi for 30 minutes, ok. Waited 19.5  I hereby certify that the information above is tr grade tank has been/will be constructed or closed accord  SIGNATURE	REMEDIAL WO COMMENCE DE CASING/CEME  OTHER:  ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A  ented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000 hours before drilling out cement.  Tue and complete to the best of my knowled rding to NMOCD guidelines , a general permit [	RK		
PERFORM REMEDIAL WORK PLUG A TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTIP  OTHER:  13. Describe proposed or completed opera of starting any proposed work). SEE or recompletion.  4/2/06 Set 9 5/8", 40#, HCK-55, BTC csg at 4,615'. Ceme Circulated 187 Bbls to surface. Tested BOP's, Kelly, Floo Tested casing to 1500 psi for 30 minutes, ok. Waited 19.5  I hereby certify that the information above is tr grade tank has been/will be constructed or closed accord  SIGNATURE	REMEDIAL WO COMMENCE DE CASING/CEME  OTHER:  ations. (Clearly state all pertinent details, a RULE 1103. For Multiple Completions: A  ented with 1390 sacks of Interfill C mixed at 11.9 ppg or valves and choke manifold from 250 psi low to 5000 hours before drilling out cement.  Tue and complete to the best of my knowled reding to NMOCD guidelines, a general permit [	RK		