Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to report and Field (abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM13624		
SUBMIT I	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well ☐ Oil Well ⊠ Gas Well □ Other					8. Well Name and No. AVALON FEDERAL 1		
2. Name of Operator Contact: ADDISON GUELKER FASKEN OIL & RANCH LIMITED E-Mail: addisong@forl.com					9. API Well No. 30-015-21814-00-S1		
3a. Address 6101 HOLIDAY HILL ROAD MIDLAND, TX 79707	o. (include area code) 37-1777	BURTON FLAT					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 1 T21S R26E SESE 80			EDDY COUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	Acidize	Dec	epen	Product	ion (Start/Resume)	□ Water Shut-Off	
	□ Alter Casing	🗖 Hy	draulic Fracturing	Reclamation	ation	U Well Integrity	
Subsequent Report	Casing Repair	🗖 Nev	w Construction	🛛 Recomp	olete	□ Other	
Final Abandonment Notice	Change Plans	Change Plans Plug a		Temporarily Abandon			
	Convert to Injection	🗖 Plu	g Back	U Water D	ter Disposal		
 Describe Proposed or Completed If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for Fasken Oil and Ranch, Ltd. 	onally or recomplete horizontally work will be performed or provid- ved operations. If the operation re Abandonment Notices must be fi r final inspection.	r, give subsurface e the Bond No. c esults in a multip iled only after all	locations and measur n file with BLM/BIA le completion or reco requirements, includ	red and true ve . Required sul mpletion in a r ing reclamation	ertical depths of all pertin psequent reports must be new interval, a Form 316	ent markers and zones. filed within 30 days 0-4 must be filed once	
procedure, current and prop	osed wellbore diagrams.				RECEIVED		
CC 5-24-18 Accepted for record - NMOCD DISTRICT II-ARTESIA O.C.D.							
14. I hereby certify that the foregoing	Electronic Submission #	#413159 verifie	d by the BLM Wel	I Information	n System		
For FASKEN OIL & RANCH LIMITED, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 05/04/2018 (18PP1588SE)							
Name (Printed/Typed) ADDISC	Title REGUL	ATORY AN	ALYST				
Signature (Electronic Submission)		Date 05/02/2018					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By /s/ Jonathon Shepard			Title PETROLEUM ENGINEER				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office				Fð			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instructions on page 2) ** BLM RE	VISED ** BLM REVISE	D ** BLM R	EVISED ** BLN	REVISED) ** BLM REVISEI) **	

3 4

Fasken Oil and Ranch, Ltd Avalon Federal No. 1 350' FEL & 803' FSL Sec 1, T21S, R26E Eddy County, New Mexico AFE 3307

APJ. 30 15-21814	
Completed: Rig released about 6-28-76, Com	Dieled 7-6-76
WELL DATA	
13-3/8" 48#/ft H-40 casing. 9-5/8" 32#H40, 36#K55 casing.	Set at 500" KB Cmt-230sx low density+150sx "C. Circ 35 sx to surf. Set at 2560" KB, Cmt 150sx Folse set#250sx low density+200sx -C. 11" w/330sx "C. Circ 5 sx to surf.
5-1/2" 15.5# 17#1 6# N-80&K55 casing	
(15:5 # K55 1898-5560))	Set at 11:361 KB, Critt 300:50/50 Poz 2% get (14:2000)+350 ex ::H" w/silica flour (15:7000) TOC 8750 by CBL
Pers:	Morrow (Active): 11046-52, 11028-32, 1096-42, 10968-98, 10976-96, 10842, 75, 10724-30, 10715-22, Total */-360 holes, Morrow (Inactive;Sqz0,1797): 11120-66, 10642-57, 1028-30, 10585-96, 10545-56, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96, 10545-56, 10642-57, 1028-30, 10585-96
Tubing	2-7/8" SN (0.30)) +/-347/jts 2-7/8 EUE 8rd 6 5#/ft N-80 000 ((11.016)). EOT 11.027.3" K8
TD PBTD Last Tubing Pail	11 450 11 102 sm retainer. (FC @ 11,279) 2-2-97

- 1. Test mast anchors.
- 2. Set test tank and lay flowline.

OBJECTIVE: Strawy Recommendation

- 3. RUPU. Set matting board, pipe racks.
- 4. Receive 10,000' 2-3/8" 4.7#/ft N80 EUE 8rd tubing with AB modified couplings.

Gurrentstatus SIACO

- 5. Blow down casing pressure.
- 6. RU pump truck and pump via tubing 35 bbls 3% KCL w/ clay stabilizer, corrosion inhibitor and oxygen scavenger.
- 7. NDWH, NU BOP.
- 8. POW with +/-11016' 2-7/8" 6.5#/ft EUE 8rd N-80 tubing and SN.
- RUWL lubricator and RIW w/ 4.75" gauge ring to 10,665' and set 5-1/2" 17# CIBP at +/-10,665' (maximum 50' above perfs). RDWL.
- 10. RIW with notched collar, SN, 2-7/8 EUE 8rd 6.5#/ft N-80 tubing to 10,665' and lightly tag CIBP.
- 11. RU pump truck and reverse circulate well with 3% Kcl water containing packer fluid and clay stabilizer. Test casing and plug to 500 psi.
- 12. RU cementers spotting 31 sx (250') class "H" cement (1.07 cuft/sk yield) above CIBP 10,665' in 5-1/2" 17#/ft csg (0.1305 cuft/ft) for a PBTD of 10,415'. WOC 2 hours and tag plug at 10,415'.
- 13. POW laying down 2-7/8" tubing.
- 14. Change out BOP rams to 2-3/8".
- 15. RIW with 2-3/8" wireline entry guide, 4' x2-3/8" EUE 8rd N-80 tubing sub, Arrowset IX 10k packer, TOSSD with 1.781" "F" profile nipple, picking up 2-3/8" EUE 8rd N-80 tubing to +/- 9870'.

- 16. RU pumping service and pickle tubing with 500 gal 15% HCL acid. Reverse load water to test tank.
- 17. ND BOP. NUWH for 2-3/8" tubing, setting packer in 12 points compression.
- 18. RU pump truck and test casing to **1200** psi (25% of 5-1/2" 15.50#/ft K55 burst 4810 psi) with chart recorder. Report results to BLM.
- 19. RUWL with 3000 psi lubricator and grease. Perforate <u>Strawn limestone</u> with 1-11/16" strip gun as follows:

9,944' – 62' (17h, 1JSPF) 10,012' – 18' (7h, 1JSPF) 10,056' – 66' (11h, 1JSPF) 10,122' – 46' (25h, 1JSPF)

60 total holes by Schlumberger Cement Bond Log dated 7-1-76 (Corrected collars are corrected to the Dresser Atlas Compensated Densilog/Compensated Neutron Log dated 6-26-76). POW, make sure all shots fired, and RDWL.


20. RU pumping service. Install tree saver. Trap 1200 psi on annulus. Acidize Strawn perfs 9944'-10146' (56', 60 holes, 0.21" EHD) via 2-3/8" tubing with 2500 gal (45 gal/ft) 15% NEFE HCI. Flush with 40 bbls 2% KCL water and dropping ball sealers for diversion. Rate 5-10 bpm at max pressure 5000 psi. RD stimulation company and tree saver.

21. Swab and flow back acid and load water to steel test tank and evaluate.


22. RDPU

23. Return well to sales.

2



5-1-18 Avalon1Fed1_WBD.xls



5-1-18 Avalon1Fed1_WBD.xls

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary. Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>. If plugging back to a new zone submit a Completion Report, form 3160-4 with the Subsequent Report.

7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

8. <u>If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken:</u> From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted