	UNITED STATI DEPARTMENT OF THE JREAU OF LAND MAN	INTERIOR	NMO0 Artes			04-0137	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian. Allottee or Tribe Name			
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/	Agreement, Narr	ne and/or No.		
1. Type of Well Image: Contract of Well Image: Co			8. Well Name and No. AMOCO FEDERAL 004				
2. Name of Operator REMNANT OIL OPERATING, LLC				9. API Well No. 30-015-25080			
a. Address .O. BOX 5375 MDLAND, TX 79704	· · ·	3b. Phone No. (include a 432-242-4965	rea code)	10. Field and Po 29490; HACKE			
Location of Well <i>(Footage. Sec.</i> 90 FNL 1980 FEL; UL B SEC 21 T19S R		n)		II. Country or P EDDY, NM	arish, State		
12. C	HECK THE APPROPRIATE B	OX(ES) TO INDICATE NA	ATURE OF NOTI	ICE. REPORT OR	OTHER DATA		
TYPE OF SUBMISSION	· · · · · · · · · · · · · · · · · · ·		TYPE OF AC	TION	··· · · · ·	 	
Notice of Intent	Acidize	Deepen Fracture Treat	· _	duction (Start/Resur	_	ner Shut-Off II Integrity	<u> </u>
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon Dig Plug Back	on 🗌 Ten	complete nporarily Abandon ter Disposal	Out	ner	
following completion of the ir	he work will be performed or pr volved operations. If the operation	rovide the Bond No. on file tion results in a multiple con	with BLM/BIA. npletion or recom	pletion in a new in	terval, a Form 31	60-4 must be fi	ed once
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read 6/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W 6/28/16 FINISHED TRIPPING IN THE IF WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF 1 DRUM TS-84 XCHEM CHEM	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU 3 DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED W TH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING	rovide the Bond No. on file tion results in a multiple con t be filed only after all requi F LOAD BB TUBING AND T AND 5-1/2" CASING S VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A S 15% NEFE HCI ACID V PERFS STARTED TAKI	with BLM/BIA. npletion or recom rements, includin Accepted for LL- D LOAD OLD TL CRAPPER. TAG D MAKE HOLE CIDIZING TO A WITH ADDITVE NG TREATMEN	pletion in a new in g reclamation, have C - 4 - 7 8 record - NMAC JBING GGED . POOH CIDIZE S AND IT 3 BPM	terval, a Form 31 e been completed	60-4 must be fi	nt has
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read 6/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W 6/28/16 FINISHED TRIPPING IN THE H WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU 3 DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED W TH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING	rovide the Bond No. on file tion results in a multiple con t be filed only after all requi F LOAD BB TUBING AND T AND 5-1/2" CASING S VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A S 15% NEFE HCI ACID V PERFS STARTED TAKI	with BLM/BIA. npletion or recom rements, includin Accepted for LL- D LOAD OLD TL CRAPPER. TAG D MAKE HOLE CIDIZING TO A WITH ADDITVE NG TREATMEN	pletion in a new in g reclamation, have C - 4 - 7 8 record - NMAC JBING GGED . POOH CIDIZE S AND IT 3 BPM	terval, a Form 31 e been completed	ABCEIVED	nt has
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read 5/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W 5/28/16 FINISHED TRIPPING IN THE IF WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF 1 DRUM TS-84 XCHEM CHEM WITH 400 PSI. RATE REMAIN	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU 3 DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED W TH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING ED @ 1100 PSI THROUGHC	rovide the Bond No. on file tion results in a multiple con t be filed only after all requi F LOAD BB TUBING AND T AND 5-1/2" CASING SI VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A S 15% NEFE HCI ACID N PERFS STARTED TAKI DUT TREATMENT. ISIP 7	with BLM/BIA. npletion or recom rements, includin Accepted for ILL- D LOAD OLD TL CRAPPER. TAG D MAKE HOLE CIDIZING TO AN WITH ADDITVE NG TREATMEN 775 PSI. 5M 390	pletion in a new in g reclamation, have record - NMAC JBING GGED . POOH CIDIZE S AND JT 3 BPM D. 10M	terval, a Form 31 e been completed	ABCEIVED	nt has
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read S/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W S/28/16 FINISHED TRIPPING IN THE I WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF 1 DRUM TS-84 XCHEM CHEM WITH 400 PSI. RATE REMAIN	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU 3 DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED W TH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING ED @ 1100 PSI THROUGHC	rovide the Bond No. on file tion results in a multiple con- t be filed only after all requi- F LOAD BB TUBING ANE T AND 5-1/2" CASING Si- VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A S 15% NEFE HCI ACID V PERFS STARTED TAKI DUT TREATMENT. ISIP 7 red/Typed) Title RI	with BLM/BIA. npletion or recom rements, includin Accepted for ILL- D LOAD OLD TL CRAPPER. TAG D MAKE HOLE CIDIZING TO A WITH ADDITVE NG TREATMEN 75 PSI. 5M 390	pletion in a new in g reclamation, have C - 4 - 7 8 record - NMAC JBING GGED . POOH CIDIZE S AND IT 3 BPM	terval, a Form 31 e been completed CD DISTRIC	FRECEIVEE MAY 3 1 20	nt has
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read 5/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W 5/28/16 FINISHED TRIPPING IN THE IF WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF 1 DRUM TS-84 XCHEM CHEM WITH 400 PSI. RATE REMAIN	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU G DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED W TH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING ED @ 1100 PSI THROUGHC	rovide the Bond No. on file tion results in a multiple con- t be filed only after all requi- F LOAD BB TUBING ANE T AND 5-1/2" CASING SI VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A S 15% NEFE HCI ACID V PERFS STARTED TAKI DUT TREATMENT. ISIP 7 red/Typed) Title RI	with BLM/BIA. npletion or recom rements, includin Accepted for ILL- D LOAD OLD TL CRAPPER. TAG D MAKE HOLE CIDIZING TO A WITH ADDITVE NG TREATMEN 775 PSI. 5M 390	pletion in a new in g reclamation, have record - NMAC JBING GGED . POOH CIDIZE S AND JT 3 BPM D. 10M FFAIRS COORD	terval, a Form 31 e been completed CD DISTRIC	FRECEIVEE MAY 3 1 20	nt has
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read S/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W S/28/16 FINISHED TRIPPING IN THE I WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF 1 DRUM TS-84 XCHEM CHEM WITH 400 PSI. RATE REMAIN	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU G DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED W TH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING ED @ 1100 PSI THROUGHC	rovide the Bond No. on file tion results in a multiple con- t be filed only after all requi- F LOAD BB TUBING AND T AND 5-1/2" CASING SI VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A S 15% NEFE HCI ACID N PERFS STARTED TAKI DUT TREATMENT. ISIP 7 Title RI Date 07 E FOR FEDERAL O	with BLM/BIA. npletion or recom rements, including Accepted for ILL- D LOAD OLD TL CRAPPER. TAC D MAKE HOLE CIDIZING TO AN WITH ADDITVE NG TREATMEN 775 PSI. 5M 390 EGULATORY AN 7/08/2016 R STATE OF	pletion in a new in g reclamation, have record - NMAC JBING GGED . POOH CIDIZE S AND JT 3 BPM D. 10M FFAIRS COORD	DISTRIC	FRECEIVEE MAY 3 1 20	nt has
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read 6/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W 5/28/16 FINISHED TRIPPING IN THE H WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF 1 DRUM TS-84 XCHEM CHEM WITH 400 PSI. RATE REMAIN	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU B DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED WITH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING ED @ 1100 PSI THROUGHC	rovide the Bond No. on file tion results in a multiple con- t be filed only after all requi- UMP AND RODS. ND WE F LOAD BB TUBING AND T AND 5-1/2" CASING SI VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A .S 15% NEFE HCI ACID V PERFS STARTED TAKI DUT TREATMENT. ISIP 7 Title RE Date 07 E FOR FEDERAL O	with BLM/BIA. npletion or recom rements, including Accepted for ILL- D LOAD OLD TL CRAPPER. TAC D MAKE HOLE CIDIZING TO AN WITH ADDITVE NG TREATMEN 775 PSI. 5M 390 EGULATORY AI 7/08/2016 R STATE OF e	pletion in a new in g reclamation, have record - NMAC JBING GGED POOH CIDIZE S AND IT 3 BPM D. 10M FFAIRS COORD FFAIRS COORD FFAIRS COORD	DISTRIC INATOR D FOR R	ABCEIVER MAY 3 1 20 T II-ARTESIA	nt has
Attach the Bond under which following completion of the ir testing has been completed. E determined that the site is read S/27/16 MIRU. UN HANG, UNSEATED HEAD. NU BOP. POOH LAYIN AND SENT BACK TO L&R PIP FILL @ 2326' (7' ABOVE BOTT WITH TOOLS. PU AND RIH W 5/28/16 FINISHED TRIPPING IN THE H WITH 5-1/2" BAKER TYPE AD PERFS 2224'-2326' WITH 2 DF 1 DRUM TS-84 XCHEM CHEM WITH 400 PSI. RATE REMAIN	he work will be performed or provived operations. If the operational Abandonment Notices must y for final inspection.) PUMP ANF POOH WITH PU B DOWN OLD TUBING. OFF E YARD. PU 4-1/2" USED BI OM PERF). CIRCULATED W TH AD-1 TENSION PACKEF IOLE 1 PACKER TO 2170'. SET P UMS OF XYLENE, 500 GAL ICAL DOWN 2-3/8" TUBING ED @ 1100 PSI THROUGHC IS true and correct. Name (Prime THIS SPACE ached. Approval of this notice do able title to those rights in the subj ions thereon. e 43 U.S.C. Section 1212, make in	rovide the Bond No. on file tion results in a multiple con- t be filed only after all requi- provide the Bond No. on file tion results in a multiple con- t be filed only after all requi- provide the Bond No. on file t LOAD BB TUBING AND T AND 5-1/2" CASING SI VELL CLEAN AND COUL R. PACKER, MIRU CRAIN A S 15% NEFE HCI ACID N PERFS STARTED TAKI DUT TREATMENT. ISIP 7 Title RI Date 07 E FOR FEDERAL O	with BLM/BIA. npletion or recom rements, including Accepted for ILL- D LOAD OLD TL CRAPPER. TAC D MAKE HOLE CIDIZING TO AN WITH ADDITVE NG TREATMEN 775 PSI. 5M 390 EGULATORY AN 7/08/2016 R STATE OF e	pletion in a new in g reclamation, have record - NMAC JBING GGED POOH CIDIZE S AND IT 3 BPM D. 10M FFAIRS GOORD ACCEPTE	INATOR DISTRIC	GECEIVEE MAY 3 1 20 T II-ARTESIA	18 0.C.D.

AMOCO FEDERAL 004

6/29/16

PU NOTCH COLLAR & 74 JTS OF TBG. RIH TO 2320' FTKB PU POWER SWIVEL WASH DOWN TO 2326' FTKB. CIR 63 BBL OF 2% KCL. CLEAN FLUID. LD POWER SWIVEL POOH w/ TBG. PU/MU PRODUCTION BHA RIH TO SET EOT @ 2315.04' FTKB. ND BOP & RU WOR TO START RUNNING ROD. PU NEW PUMP. RIH w/ 16 FT PUMP, 90 3/4 RODS & AN ASORTMENT PONY RODS. SEATED PUMP LOADED TBG w 9 BBLS OF FLUID. SPACED OUT ROD STRING START GOOD PUMP ACTION. RD WOR OVER RIG. CLEANED LOCATION RELEASED ALL EQUIPMENT. LEFT WELL PUMPING.

TBG STRING.

RIG KB= 8'

73 JTS OF 2-3/8 J-55 EUE TBG= 2281.34'

SEAT NIPPLE= 1.1'=2290.44'

2-3/8 x 2-7/8 CROSSOVER= 2290.44'

2-4FT 2-7/8 PER. SUBS=2298.74'

2-8FT 2-7/8 SUBS= 2314.74'

1- 2-7/8 BULLPLUG=2315.04 EOT.

ROD STRING

90- 3/4 ROD= 2250.00' 1-6' 3/4 ROD SUB=2256.00' 2-4' 3/4 ROD SUB=2264.00' 1-2' 3/4 ROD SUB=2266.00' 1-2 x1-1/2 x 16' ROD PUMP=2282.00'