Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103 Revised July 18, 2013
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748 1982		WELL API NO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 DIL CONSERVATION DIVISION		30-015-25272 5. Indicate Type of Lease	
District III - (505) 334-6178         1220 South St. Francis Dr.           1000 Rio Brazos Rd., Aztec, NM 87410         Santa Fe, NM 87505			STATE 🛛 FEE 🗌
District IV – (505) 476-3460 Salita FC, 19191 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No. LG-2040	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>New Mexico ES State</li> <li>8. Well Number</li> </ul>
PROPOSALS.) 1. Type of Well: Oil Well 🖾 Gas Well 🗋 Other			1
2. Name of Operator			9. OGRID Number
EOG Y Resources, Inc. 3. Address of Operator		025575 10. Pool name or Wildcat	
104 South Fourth Street, Artesia, NM 88210			Wildcat; Abo
4. Well Location			
Unit Letter <u>O</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line			
Section 7	Township 19S Rat 11. Elevation (Show whether DR,		NMPM Eddy County
and the second	3814'		a second s
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	TENTION TO:         PLUG AND ABANDON         CHANGE PLANS         MULTIPLE COMPL	SUB REMEDIAL WOR COMMENCE DRI CASING/CEMEN	
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
EOG Y Resources, Inc. plans to temporarily abandon this well as follows:			
<ol> <li>MIRU all safety equipment as needed. ND wellhead and NU BOP. POOH with production equipment.</li> <li>RIH with GR/JB to 3820'.</li> <li>Set a CIBP at 3800' and dump bail 35' Class "C" cement on top.</li> <li>Tag TOC and load the hole with plugging mud.</li> <li>Conduct MIT and chart for the NMOCD. Contact OCD to AND CONSERVATION ARTESIA DISTRICT</li> <li>NU wellhead and shut well in. Withouts Test</li> </ol>			
Wellbore schematics attached TA Status my Le granted JUL 23 2018			
Wellbore schematics attached TA Status my Le granted JUL 2 3 2018 NOTE: Recompletion to Abo was unsuccessful After Saccessfil Test LAST Prod 10/1/17 RECEIVED			
Spud Date:	Rig Release Da		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE (June 25, 2018 TITLE Regulatory Specialist DATE June 25, 2018			
Type or print name       Tina Huerta       E-mail address:       tina huerta@eogresources.com       PHONE:       575-748-4168         For State Use Only       Image: State Use Only       Image: State Use Only       Image: State Use Only			
APPROVED BY:			



