Submit 3 Copies To Appropriate District Office	= :::	State of New Mexico			Form C-103	
District I	Energy, Minerals and Natural Resources		ral Resources	Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-005-63558		
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease			
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X FEE			
District IV	Santa Fe, NM 87505		6. State Oil & G	as Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			VA-1758			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK-TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 2.				Jardin BCJ State		
PROPOSALS.)  1. Type of Well:			Jaidin BCJ State			
1. Type of Well: Oil Well Gas Well X	Other \  \rightarrow \frac{\fin}}}}{\frac}}}}}}{\frac	29	<b>T</b> (2)			
2. Name of Operator	Other		<del>JUN 2003 - 항</del>	8. Well No.		
Yates Petroleum Corpor	ration 124	, K	ECEIVED 🐰	1		
					Wildcat	
3. Address of Operator 105 South 4th Street, Artesia, NM 88210			£0/	Wildcat Precambrian		
	<u></u>	<u> </u>	<u> </u>			
4. Well Location		./3	1534			
Unit Letter N: 660 feet from the South line and 1980 feet from the West line						
gestien 2/	T1:- 70	D	045	NR MRA Ch	. Country	
Section 26	Township 7S  10 Elevation (Show wh	Range			naves County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3807'GR						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	<b>〈</b>	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRII	LLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN	ID		
OTHER:				ion Operations	v	
OTHER: OTHER: Completion Operations X  Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of						
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.						
5/29/03 – Perforate Strawn 4792'-4798', 4858'-4866' with 5642" holes.						
5/30/03-6/1/03 – Spotted 50g HCL over Strawn. Acidize Strawn with 1400g 7-1/2% IC HCL. 6/3/03 – Set CIBP at 4700' w/35' cement on top of plug. Perforate Abo 3522'-3536' with 1542" holes.						
6/4/03 – Acidize Abo with 2000g 7-1/2% IC HCL.						
6/5/03 – Perforate Abo 3428'-3432', 3450'-3456', 3478'-3482', 3550'-3562', 3588'-3594', 3598'-3602', 3606'-3610',						
3618'-3622' for a total of 5242" holes.						
6/10/03 – Frac Abo with 109,000g 55Q CO2 foamed 35# x-linked gelled 7% KCL water + 2000g 7-1/2% HCL						
ahead pad carrying 250,000# 16/30 Brady.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE						
Type or print name Tina Huerta Telephone No. 505-748-1471						
(This space for State use)					*****	
APPPROVED BY Jim W. Sum TITLE Quitiet Separation DATE JUN 25 2003						
Conditions of approval, if any:		IIILE			_DATE	