

United States Department of the Interior



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene
Carlsbad, New Mexico 88220-6292
www.nm.blm.gov



In Reply Refer to
3162.4 (P0220)

Marthon Oil Permian LLC
5555 San Felipe St
Houston, TX 77056

November 27, 2018

Gentlemen:

You're Application for Permit to Drill (APD) for the below referenced well has expired because drilling has not commenced per Onshore Order #1:

WELL NAME & NUMBER	LOCATION	ORIGINAL APD EXPIRATION	EXTENSION EXPIRATION
URRACA FEDERAL COM - 24H	330'FNL & 1750'FEL Sec.11 T23S R32E	10/31/2016	10/31/2018

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the current application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Duncan Whitlock at (575) 234-5926.

Sincerely,

J.D. Whitlock
For Cody Layton

Assistant Field Manager, Lands and Minerals

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 28 2018

RECEIVED