B SUNDRY Do not use th	UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANAG NOTICES AND REPOI is form for proposals to il. Use form 3160-3 (APL	; ARTESIA NTERIOR GEMENT MAR () RTS ON WELLS		FORM . OMB N	APPROVED 0 1004-0137 inuary 31, 2018 r Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2				7 If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other			8 W	ell Name and No.	EDERAL COM 31H
2. Name of Operator Contact: DAVID STEWART OXY USA INCORPORATED E-Mail: david_stewart@oxy.com				9 API Well No. 3230 30-015-45553-00-X1	
3a. Address 5 GREENWAY PLAZA SUITE HOUSTON, TX 77046-0521	110	3b Phone No. (include area code) Ph: 432.685.5717		10. Field and Pool or Exploratory Area PURPLE SAGE-WOLFCAMP (GAS)	
4. Location of Well (Footage, Sec. T., R., M., or Survey Description) Sec 6 T24S R29E 456FNL 706FWL 32.253586 N Lat, 104.030319 W Lon				11. County or Parish, State EDDY COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REP	ORT, OR OTH	IER DATA
TYPE OF SUBMISSION		ТҮРЕ ОГ	ACTION		
Notice of Intent	 Acidize Alter Casing 	 Deepen Hydraulic Fracturing 	Production (S	Start/Resume)	Water Shut-Off Well Integrity
Subsequent Report Final Abandonment Notice	Casing Repair	 New Construction Plug and Abandon 	Recomplete Temporarily	plete SO Other Change to Original	
	Convert to Injection	Plug Back	Water Dispos	sal	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f OXY USA Inc. respectfully red 30-015-45574 and the Height originally permitted laterals hill	rk will be performed or provide d operations. If the operation re- bandonment Notices must be file final inspection. quests to swap the SHL fo : CC 6-7 Federal Com 31H tting their approved FTP a	the Bond No. on file with BLM/BIA sults in a multiple completion or reco ed only after all requirements, includ or the Length CC 6-7 Federal (1-30-015-45553. The wells we and LTP.	Required subsequi impletion in a new ir ing reclamation, hav Com 21H ? Duld still drill their me other	int reports must be iterval, a Form 316 e been completed a	filed within 30 days 0-4 must be filed once
The change in total well depth than sundry Notice EC Transa surface in this area is private making this swap. The driver arrangement. We acknowledg sundry, but greatly appreciate The final well order from NW	action 453863, Serial Num surface and no additional to make the request is an ge we should have caught a the BLM?s support in res	ber 950-25738 submitted on surface disturbance would be ti-collision concerns with the the AC issues prior to filing the	incurred by current slot		
The change in total well depth than sundry Notice EC Transs surface in this area is private making this swap. The driver arrangement. We acknowledg sundry, but greatly appreciate	action 453863, Serial Num surface and no additional to make the request is an ge we should have caught the BLM?s support in res to SE would be:	nber 950-25738 submitted on surface disturbance would be nti-collision concerns with the o the AC issues prior to filing the solving the issue.	incurred by current slot ve original	lem	
The change in total well depth than sundry Notice EC Transa surface in this area is private making this swap. The driver arrangement. We acknowledg sundry, but greatly appreciate The final well order from NW 1 14. I hereby certify that the foregoing in	action 453863, Serial Num surface and no additional to make the request is an ge we should have caught the BLM?s support in res to SE would be: s true and correct. Electronic Submission # For OXY USA mmitted to AFMSS for proce	aber 950-25738 submitted on surface disturbance would be the collision concerns with the o the AC issues prior to filing the solving the issue. 454724 verified by the BLM We A INCORPORTED, sent to the essing by MU\$TAFA HAQUE of	incurred by current slot e original Il Information Sys Carisbad	H0027SE)	
The change in total well depth than sundry Notice EC Transa surface in this area is private making this swap. The driver arrangement. We acknowledg sundry, but greatly appreciate The final well order from NW 14. I hereby certify that the foregoing in Com Name (Printed/Typed) DAVID S	action 453863, Serial Num surface and no additional to make the request is an ge we should have caught the BLM?s support in res to SE would be: s true and correct. Electronic Submission # For OXY USA mmitted to AFMSS for proce	aber 950-25738 submitted on surface disturbance would be the collision concerns with the o the AC issues prior to filing the solving the issue. 454724 verified by the BLM We A INCORPORTED, sent to the essing by MU\$TAFA HAQUE of	Incurred by current slot be original Il Information Sys Carisbad n 02/21/2019 (19M ATORY ADVISC	H0027SE)	
The change in total well depth than sundry Notice EC Transa surface in this area is private making this swap. The driver arrangement. We acknowledg sundry, but greatly appreciate The final well order from NW 14. I hereby certify that the foregoing in Com Name (Printed/Typed) DAVID S	action 453863, Serial Num surface and no additional to make the request is an ge we should have caught a the BLM?s support in res to SE would be: s true and correct. Electronic Submission # For OXY USA mmitted to AFMSS for proce TEWART Submission)	ASSING by MUSTAFA HAQUE on Title REGUL	incurred by current slot be original Il Information Sys Carisbad n 02/21/2019 (19M ATORY ADVISC	H0027SE)	
The change in total well depth than sundry Notice EC Transa surface in this area is private making this swap. The driver arrangement. We acknowledg sundry, but greatly appreciate The final well order from NW 14. I hereby certify that the foregoing in Com Name (Printed/Typed) DAVID S	action 453863, Serial Nur surface and no additional to make the request is an ge we should have caught a the BLM?s support in res to SE would be: s true and correct. Electronic Submission # For OXY USA mmitted to AFMSS for proce TEWART Submission) THIS SPACE FO	ASA724 verified by the BLM We AINCORPORATED, sent to the essing by MUSTAFA HAQUE or Title REGUL Date 02/14/2 DR FEDERAL OR STATE	Incurred by current slot be original II Information Sys Carlsbad n 02/21/2019 (19M ATORY ADVISC 019 OFFICE USE	H0027SE) DR	RALS Date 02/21/20

•

• •

Ruf 3-5-	1	<i>G</i> ,
----------	---	------------

4

Additional data for EC transaction #454724 that would not fit on the form

*

32. Additional remarks, continued

Length CC 6-7 Fed Com 21H Height CC 6-7 Fed Com 32H Height CC 6-7 Fed Com 31H Length CC 6-7 Fed Com 22H

، د

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	APDCH NOI	APDCH NOI
Lease:	NMNM13996	NMNM13996
Agreement:		
Operator:	OXY USA INC P.O. BOX 50250 MIDLAND, TX 79710 Ph: 432-685-5717	OXY USA INCORPORATED 5 GREENWAY PLAZA SUITE 110 HOUSTON, TX 77046-0521 Ph: 713.350.4816
Admin Contact:	DAVID STEWART SR. REGULATORY ADVISOR E-Mail: david_stewart@oxy.com Cell: 432-634-5688 Ph: 432-685-5717	DAVID STEWART REGULATORY ADVISOR E-Mail: david_stewart@oxy.com Ph: 432.685.5717
Tech Contact:	DAVID STEWART SR. REGULATORY ADVISOR E-Mail: david_stewart@oxy.com Cell: 432-634-5688 Ph: 432-685-5717	DAVID STEWART REGULATORY ADVISOR E-Mail: david_stewart@oxy.com Ph: 432.685.5717
Location: State: County:	NM EDDY	NM EDDY
Field/Pool:	PIERCE CROSSING BN SPR	PURPLE SAGE-WOLFCAMP (GAS)
Well/Facility:	LENGTH CC 6-7 FEDERAL COM 21H Sec 6 T24S R29E NWNW 456FNL 706FWL 32.253050 N Lat, 104.030062 W Lon	HEIGHT CC 6_7 FEDERAL COM 31H Sec 6 T24S R29E 456FNL 706FWL 32.253586 N Lat, 104.030319 W Lon

Revisions to Operator-Submitted EC Data for Sundry Notice #454724

•

17