Norm 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter ar	7

OCD Artesia 5. Lease Serial No.

Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe Name			
Do not use thi abandoned we								
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. 891000303F							
Type of Well	8. Well Name and No. POKER LAKE UNIT 216							
Name of Operator Contact: TRACIE J CHERRY XTO PERMIAN OPERATING LLC E-Mail: tracie_cherry@xtoenergy.com					9. API Well No. 30-015-33861-00-\$1			
3a. Address 6401 HOLIDAY HILL ROAD E MIDLAND, TX 79707	10. Field and Pool or Exploratory Area NASH DRAW-DELAWARE							
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State			
Sec 19 T24S R30E SWNE 19	EDDY COUNTY, NM							
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICAT	TE NATURE O	F NOTICE	, REPORT, OR OTI	IER DATA		
TYPE OF SUBMISSION			TYPE OF	ACTION		-		
☐ Notice of Intent	☐ Acidize	☐ Deep	oen	☐ Produc	tion (Start/Resume)	■ Water Shut-	Off	
	☐ Alter Casing	☐ Hydi	aulic Fracturing	☐ Reclamation		☐ Well Integri	ity	
Subsequent Report	□ Casing Repair	□ New	Construction	Recom	plete	Other		
☐ Final Abandonment Notice	☐ Change Plans	s 🛛 Plug and Abandon 🔲 Tem		☐ Tempo	rarily Abandon			
	☐ Convert to Injection ☐ Plug Back ☐ Water			Disposal				
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fit BOPCO, LP respectfully submareferenced well. 03/07/19 - 03/11/19	rk will be performed or provide l operations. If the operation re- pandomment Notices must be fil- inal inspection. nits this sundry notice to re-	the Bond No. on sults in a multiple ed only after all report the plug	file with BLM/BIA completion or reco equirements, include and abandonme and abandonme are 4/3 crepted for reco	Required sompletion in a sing reclamation of the control of the co	ubsequent reports must be new interval, a Form 316 on, have been completed a RECLA	filed within 30 day 0-4 must be filed or	s nce	
MIRU. POOH with rods and p 1500 (good). RIH with 4.5 CIB	ump. Remove wellhead, i P to 7200', set. Tag w/tbg	nstall BOP. Fi to verify.	unction test/Pres	ssure Test	BOP to			
03/12/19 RIH w/4.25 CIBP to 7300', set	. Dump bail 35 cmt on top	o. RIIH w/ 2nd	CIBP to 6800',	set.		LAMAT		
03/14/19 TIH <u>w/tbg, tag CIBP at 680</u> 0'.	Circulated 160 bbls salt g	elled mud. PT	csg to 500 psi ((good). Spo		RECEIVED	L	
14. I hereby certify that the foregoing is	Electronic Submission #					APR 2 5 201		
Comm	For XTO PERMI. itted to AFMSS for process	sing by DEBO	G LLC, sent to the AH MCKINNEY of	on 04/15/201	9 (19DLM0283SE)	ICT ILABTESIA	OCD	
Name (Printed/Typed) TRACIE J	CHERRY		Title REGUL	AIUNIU			0.0.0	
Signature (Electronic S	Submission)	·	Date 04/13/20		CCEPTED FOR	RECORD		
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE L	ISE APR 15	20 19		
Approved By	1 10 10		Title		smolinner	HA		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or				<u> </u>	BURFALL OF LAND M	ANAGEMENT		
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office		CARLSBAD FIEL	D OFFICE	ل ل	

Additional data for EC transaction #461338 that would not fit on the form

32. Additional remarks, continued

25 sx Class C 6800'-6553'. SDFD.

03/18/19

RIH w/tbg, tag TOC @ 3824'. RIH perf @ 3500'. Set pkr @ 2950', EIR, sqz 110 sx 3500'-3150'. SDED.

03/19/19)
TIH w/tbg, tag_TOC @ 3138'. Perf @ 550', set pkr @ 188', EIR. Sqz 100 sx 500'-400'. WOC 4 hrs. TIH w/tbg, tag TOC 407'. Perf @ 60'. Set pkr @ 30', EIR and sqz 25 sx cmt 60'-surface.

Verify cmt to surface

03/22/19 Cut off WH, Install marker. Well P&A



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver
Environmental Protection Specialist
575-234-5943

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-5996

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612