Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM97110

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

6.	If Indian,	Allottee	or Tribe	Name
	,			

abandoned we	6. If Indian, Allottee or Tribe Name										
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM113985						
Type of Well Gas Well	8. Well Name and No. MCKITTRICK 14 FEDERAL 2										
Name of Operator OXY USA WTP LIMITED PTN	9. API Well No. 30-015-34266-00-S1										
3a. Address.	none No. (include area code) 432-685-5717										
HOUSTON, TX 77210		+32-063-3717									
4. Location of Well (Footage, Sec., T		·]	County or Parish							
Sec 13 T22S R24E SWSE 20	08FNL 991FWL			=	DDY COUN	ΓY, NM					
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	DICATE NATURE OF	NOTICE.	REP	ORT. OR OT	THER DA	ГА				
TYPE OF SUBMISSION		TYPE OF									
	☐ Acidize	□ Deepen	☐ Product	tion (S	tart/Resume)	☐ Wat	er Shut-C				
☐ Notice of Intent	· ·	☐ Hydraulic Fracturing	☐ Production (Start/Resume) ☐ Reclamation			☐ Water Shut-Off☐ Well Integrity					
Subsequent Report	-	☐ New Construction	Recom			Oth					
☐ Final Abandonment Notice		Plug and Abandon	☐ Tempor	_	Abandon	_					
	☐ Convert to Injection	☐ Plug Back	☐ Water I	Dispos	al						
determined that the site is ready for final inspection. 6/6/19 - MIRU PU 6/10/19 - NDWH, NU BOP & annular, start to POOH w/ tbg 6/11/19 - Continue to POOH w/ tbg & ESP equipment. RIH w/ bit & scrapper to 8320', POOH. 6/12/19 - RIH & set CIBP @ 8310', RIH & set pkr @ 8283', circ hole, test to 520# for 30min, tested good. Rel pkr, POOH. 6/13/19 - RIH w/ tbg & tag CIBP @ 8307', M&P 85sx CI H cmt w/ 1% CaCl2, PUH, WOC. RIH & tag cmt @ 7723', notified BLM, circ hole w/ 10# MLF.											
			Γ	100	FPTFD F	OR RE	CORD	1			
14. I hereby certify that the foregoing is Com Name (Printed/Typed) DAVID ST	Electronic Submission #470489 For OXY USA WTP LIMI mitted to AFMSS for processing b	TED PTNRSHIP, sent to by PRISCILLA PEREZ on	I Informatio	n Sysi id (19D	tem M044/18FE) 3			0.000			
Name (17th eth 17th e	ILWAN	The GR. KE	JOLATOK	ואלו	713011		- E	13.			
Signature (Electronic	Submission)	Date 06/25/20	019	BU	REAU OF LAN	D MANAGE	MENT				
	THIS SPACE FOR FE	DERAL OR STATE (OFFICE	SE	- C/ III CO DIA						
Approved By		Title				. D	ate				
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu		-									
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			willfully to n	nake to	any department	or agency of	the United	ļ.			



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Evnironmental Protection Specialist 575-234-5996

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612