Submit 3 Copies To Appropriate District Office	State of New Me	exico	Form C-103
District I	Energy, Minerals and Nati	ıral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSERVATION	IDIVISION	30-015-24156
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra		STATE S FEE
District IV	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			OG-784
87505		-	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIE			
PROPOSALS.)	CATION TORTERWIT (TORWIC-101)1	ok soen	New Mexico Z State
1. Type of Well: Oil Well	Gas Well Other	DECEIVED	8. Well Number 1
2. Name of Operator		RECEIVED	9. OGRID Number
• '	y Corporation	AUG 1 0 2005	013837
3. Address of Operator			10 Pool name or Wildcat
1 · · · · · · · · · · · · · · · · · · ·	Artesia, NM 88211-0960	OCU-AFTER!	Millman; Yates-SR QN-GB-SA, East
4. Well Location			
Unit LetterA:	660feet from theNortl	line and	660feet from theEastline
Section 12	Township 19S	Range 28E	NMPM County Eddy
a Programme Company	11. Elevation (Show whether DF	, RKB, RT, GR, etc.,	
	3378' GR	,	
Pit or Below-grade Tank Application 🔲 o	or Closure	· · · · · · · · · · · · · · · · · · ·	
Pit type Depth to Groundw	aterDistance from nearest fresh	vater well Dist	tance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	DDIS; Co	onstruction Material
12. Check A	Appropriate Box to Indicate N	lature of Notice,	Report or Other Data
	11 1	,	•
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WOR	K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	ILLING OPNS.□ P AND A 🛛
1	AND TIPLE COMPL	CASING/CEMEN	
PULL OR ALTER CASING	MULTIPLE COMPL		1306 11
PULL OR ALTER CASING	MULTIPLE COMPL	CASINO/OLIVILIA	1306
PULL OR ALTER CASING OTHER:	MOLTIPLE COMPL	OTHER:	
OTHER:		OTHER:	
OTHER: 13. Describe proposed or comp	oleted operations. (Clearly state all	OTHER:	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp of starting any proposed we	oleted operations. (Clearly state all	OTHER:	
OTHER: 13. Describe proposed or comp	oleted operations. (Clearly state all	OTHER:	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion.	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multip	OTHER:	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp of starting any proposed we	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multip	OTHER:	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', composed we or recompletion.	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple ap w/ 35' cmt. w/ bailer.	OTHER:	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', composed with the completion of the completion. 7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer.	OTHER:	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', composed with the completion of the completion. 7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead &	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface. c anchors, install dry hole marker, a	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface. c anchors, install dry hole marker, a	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of under bond is retained until	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. o surface. c anchors, install dry hole marker, a	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of under bond is retained until environmental	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. b surface. c anchors, install dry hole marker, a	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of under bond is retained until	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. b surface. c anchors, install dry hole marker, a	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of under bond is retained until environmental	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. b surface. c anchors, install dry hole marker, a	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of under bond is retained until environmental remediation and final inspect	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. b surface. c anchors, install dry hole marker, and anchors, install dry hole marker, anchors install dry hole marker.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & formulation and final inspection. Approved as to plugging of under bond is retained until environmental remediation and final inspection.	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. surface. anchors, install dry hole marker, a anchors, install dry hole marker, a ction is completed.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & formulation and final inspection. Approved as to plugging of under bond is retained until environmental remediation and final inspection.	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. surface. anchors, install dry hole marker, a anchors, install dry hole marker, a ction is completed.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & 1/28/05 RDMO. Cut off wellhead & 1/28/05 RDMO as to plugging of under bond is retained until environmental remediation and final inspection. I hereby certify that the information grade tank has been/will be constructed or	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. b surface. c anchors, install dry hole marker, and anchors, install dry hole marker, anchors is completed. The well bore. Liability surface restoration, ction is completed.	OTHER: pertinent details, and ole Completions: At a clean location. Test of my knowledg , a general permit .	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & form the second of the second	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. surface. anchors, install dry hole marker, a anchors, install dry hole marker, a ction is completed.	OTHER: pertinent details, and ole Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of under bond is retained until environmental remediation and final inspection. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'.	OTHER: pertinent details, and ole Completions: At a clean location. Test of my knowledg , a general permit .	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan DATE8/3/05
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', composed was or recompletion. 7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', taggregate to the second of the s	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'.	OTHER: pertinent details, and ole Completions: At a clean location. Test of my knowledg , a general permit .	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Approved as to plugging of under bond is retained until environmental remediation and final inspection. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'.	OTHER: pertinent details, and ole Completions: At a clean location. Test of my knowledg , a general permit .	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan DATE8/3/05
OTHER: 13. Describe proposed or composed starting any proposed we or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', c7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', tag 7/27/05 Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Market Spot Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. Cut off wellhead & Market Spot Spot Spot 10 sx. cmt. from 60' to 7/28/05 RDMO. The following spot Spot Spot Spot Spot Spot Spot Spot S	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'. surface. anchors, install dry hole marker, and the well bore. Liability surface restoration, ction is completed. above is true and complete to the best closed according to NMOCD guidelines TITLE E-mail address:	OTHER: pertinent details, and ole Completions: At a clean location. Test of my knowledg , a general permit .	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 8/3/05 Telephone No. (432) 530-0907
OTHER: 13. Describe proposed or composed was or recompletion. 7/27/05 Set 5-1/2" CIBP @ 1714', composed was or recompletion. 7/27/05 Circulate hole w/ MLF. 7/27/05 Spot 35 sx. cmt. @ 465', taggregate to the second of the s	pleted operations. (Clearly state all ork). SEE RULE 1103. For Multipletap w/ 35' cmt. w/ bailer. g plug @ 130'.	OTHER: pertinent details, and ole Completions: At a clean location. Test of my knowledg , a general permit .	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan DATE8/3/05