


UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS**

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*



FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

5. Lease Serial No.

**NM15429**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

**OXY Excalibur 1**  
**Federal**

9. API Well No.

**30-015-30771**

10. Field and Pool, or Exploratory Area

**Logan Draw Morrow**

11. County or Parish, State

**Eddy NM**

**SUBMIT IN TRIPLICATE - Other Instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

**OXY USA WTP Limited Partnership**

**192463**

3a. Address

**P.O. Box 50250, Midland, TX 79710-0250**

3b. Phone No. (include area code)

**432-685-5717**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**660 FNL 660 FWL NWNW(D) Sec 21 T17S R27E**

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**

☒ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

**TYPE OF ACTION**

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☒ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☒ Well Integrity

☐ Other **TA Status**

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

OXY USA WTP LP requests to temporarily abandon this well for possible future use.

TD-9340' PBTD-8945' Perfs-9004-9014' CIBP-8980'

Notify BLM/NMOC. RU pump truck 7/30/03 circulate well with treated water, pressure test casing to 530# for 30 min.

Accepted for record - NMOC

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

**David Stewart**

Title

**Sr. Regulatory Analyst**

Date

**8/1/03**

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**


Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office



7-30-03  
 Oxy U.S.A.  
 Excaliber  
 Tubing O PSI  
 Casing O PSI  
 John Deere  
 Key Energy  
 Truck # 43905