Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103 March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 88240 District II	Energy, Minerals and Natural Resour	WELL API NO. 30-015-32353
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISIO	N 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE 7 FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name A Gordon 23 State Com
PROPOSALS.)	HON FOR PERIVITI (FORMIC-101) FOR SUCH	8. Well Number
1. Type of Well: Oil Well Gas Well 🗸 O	Other RECEIV	
Name of Operator EOG Resource		
3. Address of Operator P.O. Box 226	7, Midland, TX, 79702	10. Pool name or Wildcat Angell Ranch, Atoka-Morrow
4. Well Location		
Unit Letter N :	997 feet from the South line	and1445feet from theWestline
Section 23	Township 19-S Range 27- 11. Elevation (Show whether DR, RKB, RT,	E NMPM Eddy County GR, etc.)
Pit or Below-grade Tank Application (For p	it or below-grade tank closures, a form C-144 must l	e attached)
		dwater 18 Distance from nearest fresh water well Over 1000'
	Below-grade Tank Location ULSect	
997 feet from the South line and 14	45 feet from the West line (Steel Tank)	
NOTICE OF INT	PLUG AND ABANDON REMEDIA	SUBSEQUENT REPORT OF: AL WORK ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT
	MULTIPLE CASING CEMENT	TEST AND DISTRIBUTION DISTRIBUT
OTHER:	☐ OTHER:	
		tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
 Notified Phil H. with OCD with P&A intent RU on 2 7/8 production csg, sqz 40sx, plu Cut 2 7/8" csg at 9000 not free, spot 30sx Cut 2 7/8" csg at 7690, POH and LD. Spot 100sx cmt from 7690-7300 (Stub) W Displace hole with MLF with 9.5# Brine wi Spot 60sx cmt from 6700-6500 (B. Spring) 	g from 9500-9762 (Strawn) WOC Tag at 9360. cmt from 9000-7800, WOC Tag at 7702. 1 OC Tag at 7311. 1 th 25# gel P/BBL. 1	 Spot 60sx cmt from 5900-5700 (B. Springs). Spot 60sx cmt from 2850-2700 (8 5/8" Shoe), WOC Tag @ 2706. Spot 60sx cmt from 2400-2200 (S. Andres). Spot 60sx cmt from 1400-1200 (Queen). Spot 130sx cmt from 500-Surf (11 3/4" Shoe) WOC Tag @ Surf. Install dry hole marker.
I hereby certify that the information abgrade tank has been/will be constructed or cle	ove is true and complete to the best of my kosed according to NMOCD guidelines , a general	nowledge and belief. I further certify that any pit or below- permit or an (attached) alternative OCD-approved plan .
SIGNATURE /	TITLE C	onsultant DATE 8-25-04
Type or print name Jimmy Bagle	E-mail address:	Telephone No. 432-561-8600
(This space for State use)		Gerry Guve
	Dept	ty Field Inspector AUG 1 0 2006
APPPROVED BY Conditions of approval, if any:		try Field Inspector AUG 1 0 2006 strict II - Artesia DATE