Form 3160-5 (September 2001)

N.M. Oil Cons. DIV-Dist. 2

UNITED STATES
DEPARTMENT OF THE INTERPARTE SIZE, NO. 1220
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135

BUILDAU OF LAND MANAGE		(4)	. Expires 30	muary 31, 2004	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or re enter an			5. Lease Serial No.		
			NM-18214 6. If Indian, Allottee or Tribe Name		
apandoned Well. Use Form 3160-3 (APD) to	or such proposals.	6.1	Indian, Allottee or	nbe name	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or releter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well Oil Well Gas Well A Name of Constant			7. If Unit or CA/Agreement, Name and/or No.		
Oil Well Gas Well X Other P&A			8. Well Name and No.		
2. Name of Operator			kalb Federal	#1	
Yates Petroleum Corporation			9. API Well No.		
3a. Address 3b. Phone No. (include area code)			30-005-00159		
105 S. 4th Str., Artesia, NM 88210 505-748-1471		10.	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,T.,R.,M., OR Survey Description)			Rock Schoolhouse; Wolfcamp		
			11. County or Parish, State		
660'FNL & 1980'FWL of Section 21-T8S-R26E (Unit C, NENW)			Chaves County, New Mexico		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION TYPE OF ACTION					
Acidize	Deepen	Production (Start,	/Resume)	Water Shut-Off	
Notice of Intent Alter Casing	Fracture Treat	Reclamation	,	Well Integrity	
			<u></u>	_	
X Subsequent Report Casing Repair	New Construction	Recomplete		Other	
Change Plans	Change Plans Plug and Abandon Temporarily Abandon				
Final Abandonment Notice Convert to Injection	Plug Back	Water Disposal	isposal		
13. Describe Proposed of Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)					
 1/11/07 Set a 4-1/2" CIBP at 4983'. RIH tagged and dumped 35' cement on top. Set a 2nd 4-1/2" CIBP at 4318'. RIH tagged and dumped 35' cement on top. Perforated at 2106'. Casing held 1000 psi. BLM OK'd. Spotted 25 sx cement at 2156'. 1/12/07 Tagged at 1778'. Perforated at 1060'. Pumped 35 sx cement. WOC. Tagged at 870'. Perforated at 150'. Circulated 40 sx cement to surface. Cut off wellhead and installed dry hole marker. WELL IS PLUGGED 					
AND ABANDONED. FINAL REPORT.					
Accepted for record NMOCD Accepted for record NMOCD Accepted for record NMOCD Accepted for record Accepted for record NMOCD Accepted for record Ac					
the inspector on location to confirm all reclamation requirements before receiving the notice of written order.					
14. I hereby certify that the foregoing is true and correct					
Name (Printed/Typed) Tina Huerta Title Regulatory Compliance Supervisor					
Signature Date January 16, 2007					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by /S/DA\/ID R GLASS TIBETROLEUM ENGINEER Date JAN 18 2007					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					