Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OMB No. 1004-0135

Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an an abandoned well. Use Form 3160-3 (APD) for such proposals.

Į٥	. Lease Senai No.
Ĺ	NM-30390
6	. If Indian, Allottee or Tribe Name

								
SUBMIT IN	TRIPLICATE - Of	ner instructions on	reverse side 12345	7 If Unit or CA/Agreement, Name and/or No.				
1 Type of Well			- 1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4					
Oil well X Gas Well	Other		AND STR SONS	ও৪. Well Name and No.				
2 Name of Operator			110	ESTORIL YZ FEDERAL #1				
Yates Petroleum	Corporation		130 MEDELLE	9: API Well No.				
3a. Address		3b. Phone No.(includ	e area code) D - ARTESIA	30-005-62155				
105 S.4th St-Arte	sia, NM 88210	505-748-147	71 CE	10. Field and Pool, or Exploratory Area				
4 Location of Well	(Footage, Sec.,T.,R.,M.,	OR Survey Description)	, c)	PECOS SLOPE ABO				
UNIT I 1980' FSI	L & 660' FEL S	ECTION 34-T4S-R24	E Some US	11. County or Parish, State				
			E ्रेंडशका प्रमास	CHAVES COUNTY, NM				
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISS	ION	TYPE OF ACTION						
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off				
	Alter Casing	Fracture Treat	Reclamation	Well Integrity				
Subsequent Report	Casing Repair	New Construction	Recomplete	Other				
	Change Plans	X Plug and Abandon	Temporarily Abandon					
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal					
			ed starting date of any proposed work and measured and true vertical depths of a					

- Attach the Bond under which the work will be performed or provide the Bond no, on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. following completion of the involved operations. If the operation results in a muliple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have completed, and the operator has determined that the site is ready for final inspection.) 1. NOTIFY NMOCD AT LEAST 24 HOURS BRFORE STARTING PLUGGING WORK. Call office for new directions if any
- abnormalities are noticed during plugging operations. MIRU WSU & all safety equipment as needed. Bleed pressure off tubing and load tubing & casing w/ 30+/- bbls of 2% KCL water; ND wellhead & NU BOP; release packer @ 3530' - POH w/ tbg. & pkr. 2. RU wireline; RIH w/ 4-1/2" gauge ring to 3600' to make sure casing is clear, RIH w/ 4-1/2" CIBP & set plug @ 3550'. MU dump
- bailer & RIH w/ bailer & dump 35' cement on top of CIBP. RD wireline. 3. RIH w/ tubing to 3515' & circ hole w/ 10.0 ppg brine plugging mud w/ 25# gel/bbl in mud; pull tubing up to 1700' & spot 25 sk plug from 1700' to 1450'. Pull tubing up to 900' & spot another 25 sk plug from 900' to 650' across 8-5/8" casing shoe. WOC 3 hours & tag plug, then pull tubing up to 60' & set a 10 sk plug to surface.

ND BOP & remove wellhead. Install regulation dry hole marker & clean location.

14 I hereby certify that the foregoing is true and correct	Title	continued on next page
Name (Printed/Typed)		• •
DONNA CLACK	REGULATORY COMPLIANCE	TECHNICIAN
Signature Dana Colle	Date August 29, 2003	
THUS PACE FOR FEDERAL OR STATE OF	FICE USE: 4 4 4 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Which would entitle the applicant to conduct operations thereon.	Office	

	Estoril YZ Federal # Ut I. Sec 34, T4S	Chaves County	D: Pecos Slope Abo Chaves County			
		KB: '				
	1/26/84 CON	CASING PROG	CASING PROGRAM			
COMMENTS:_			8 5/8". 24#, J-55	850		
			4 ½." 9.5# J-55 ST&C	4070		
(2 1⁄4. "Hole	60°	Plug @ 60' to Surface w/10 sx	TO OCD - AR	23 2 5 5 7 5 3 7 5 1 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1		
(650'	8 5/8. @850" w/600 sx cr Plug @ 900'-650' w/25 sx				
	10.0 PPG MUD 1450'	Plug @1700-1450'w/25 s 1" To Est. 1500' w/300 Sx C	San Andres Glorieta Fullerton Abo	600' 1549' 2920' 3545'		
7-7/8" Hole		TOC @ 2626 by CBL	<u>AFTER</u>			
	10.0 PPG MUD					
· P @ 3550' w/35' cmt		ABO Perf's-3853-60' w/8 .50" holes of the control o	%-5/23/84 les on 5/26/84			

TD 4070'