Form 3160-5 (April 2004)

MAR - 8 2007

FORM APPROVED UNITED STATES OCD - ARTESIA, I OM B No. 1004-0137 Expires: March 31, 2007 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 5. Lease Serial No. NM98120 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Oil Well Skelly Unit Gas Well 8. Well Name and No. 2. Name of Operator Forest Oil Corporation 9. API Well No. 30-015-05418 3a. Address 3b. Phone No. (include area code) 3504 NW County Road Hobbs, New Mexico 88240 505 392-9797 10. Field and Pool, or Exploratory Area Grayburg Jackson 7-Rivers QN GB SA 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 660' FNL & 660' FWL Sec. 26-T17S-R31E Unit D **Eddy County, New Mexico** 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/Resume) Water Shut-Off Deepen Notice of Intent Alter Casing Well Integrity Reclamation Fracture Treat Casing Repair Other New Construction Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Plug Back Convert to Injection Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

8/02/06 MIRU unit.

8/03/06 ND WH. Release pkr. POH w/2/3/8" tbg. RU WL. Set 5.5 CIBP & test. RIH w/tbg. Circulate pkr. fluid. POH. LD tbg. SIW.

8/04/06 ND BOP. NU WH. Pressured to 500 psi. RD unit.

12/14/06 Set 5.5 CIBP @ 3220'.

2/20/07 Ran MIT for 30 min. to 520 psi. Held ok. Test performed by Mr. Rueda w/Stone Oilfield Service. Witnessed by Gerry Guye w/NMOCD. Original chart retained by Gerry Guye. Copy of chart attached.

Accepted for record

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1			
Mary Jo Turner	Title 1	Production Analyst		
Signature Mary On Tuner	Date	March 1,200	07	
THIS SPACE FOR FEDER			USE	
Approved by	Ti	itle	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.