

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

26 September 2003

Ray Westall P. O. Box 4 Loco Hills, New Mexico 88255

Form C-103 Report of Plugging for your Myrtle Myra #3 K-9-21-27 API 30-015-25126 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been filled and leveled.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and

approval.

Name

3M

0 × 10 12 12 0 × 10 12 0 ×

Van Barton Field Rep. II Lori Wrotenbery

Director

servation Division

Submit 3 Copies To Appropriate Districts	Form C-103
Office State Of New Mexico	Revised March 25, 1999
District J. 1625 N. French Drive., Hobbs, NM 88240	Well API No.
District II OIL CONSERVATION DIVISION	30-015-25126
1301 W. Grand, Artesia, NM 88210 2002 2002 2004 South Pacheco	5. Indicate Type Of Lease
1301 W. Grand, Artesia, NM 88210 District III Service Company of the Company of	State X Fee
1000 Rio Brazos Rd., Aztec, MM 87410 RECENTESIA	6. State Oil and Gas Lease No.
District III 1000 Rio Brazos Rd., Aztec TMM 87410 RECENTESIA District IV 2040 South Pacheco, Santa Fe, NM 87400 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	L/48
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name Or Unit Agreement
(DO NOT USE THIS FORM FOR PROPOSAL TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type Of Well:	Myrtle Myra
Oil Well Gas Well Other	
	8. Well No.
Name Of Operator Ray Westall Operating	3 ·
Address Of Operator	9. Pool Name Or Wildcat
P.O. Box 4 - Loco Hills, New Mexico 88255	lattuerta Delaware
Well Location	
Unit Letter K: 1980' Feet From The South Line And 1980' Feet From The Line	
Section 09 Township 215 Range 27E NMPM County Edds	1
10. Elevation (Show whether DR, RKB, RT, GR, ect.)	
11. Check The Appropriate Box To Indicate Nature Of Notice, Report Or Other	Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
Remedial Work Plug And Abandon Remedial Work Alter Casing	
Temporarily Abandon Change Plans Commence Drilling OPNS. Plug and Abandonment	
Pull Or Alter Casing Multiple Completion Casing Test and Cement Job	
Other:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
9/19/03. 1st plug@ 2673' (75 sxs c+2% CACL)	
Tagged @ 2443'.	
200 plug @ 932' (25 sxs c Neat)	
3rd plug @ 497' (25 sxs c+246 cACL2)	
Tagged @ 391'.	
4th plug@ 60'- surface (25 sxs c neat) Circ.	
2 bbls to pit.	
· · · · · · · · · · · · · · · · · · ·	
9/22/03 - Install dry hole Marker.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	0100100
Signature Title Production Secretary	Date $9/22/03$
Type Or Print Name: Rene Mathews	ne No. (505) 677-2370
(THIS SPACE FOR STATE USE)	70
OOO	
ADDDOLED BY	
APPROVED BY Conditions Of Approval If Any: APPR	OVED OCT 2 9 2003