

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB NO 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Forest Oil Corporation

3a Address

707 17th Street, Suite 3600 Denver, CO 80202

AUG 07 2007

OCD-ARTESIA

3b Phone No (include area code)

303-812-1554

4 Location of Well (Footage, Sec., T, R., M., or Survey Description)

Sec 12-23S-31E Mer NWNW
660 FNL & 660 FWL

5. Lease Serial No

NMM22080

6 If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Barclay Federal

25

9 API Well No

30-015-30597-00-S1

10. Field and Pool, or Exploratory Area

Livingston Ridge

11. County or Parish, State

Eddy County

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

Pump Repair

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

6-6-07 RU PU unhung well head, long stroke pump, no action try to unseat pump, it was stuck pull & hear too, POH rods, rig up swabbing tools & swab tbg two trips. Unseat TAC POH 50 jts 2-7/8, had to S.I. wind started blowing. flange well head close valve.

6-7-07 Take off well head flange, started stripping job. POH 50 jts & RU swabing tool, swab tbg take off swabbing tool, POH tbg layed down jt w/pump. Jt was less than half full of sand, little of scale, and clean mud anchor, had 1'-6" of sand. Pick up mud anchor 3 jts 4' x 2-7/8" perf sub, S.N. RBTH tbg. Foreman call & said POH tbg need to put a de-sander in this well. POH tbg flange well head.

6-11-07 Check pump action, pumping good. RDPu, clean location.

ACCEPTED FOR RECORD

AUG 5 2007

14 I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Cindy Bush

Title

Sr. Regulatory Tech

Signature

Date

6-20-07

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Accepted for record - NMOCD

E. L. 107