Form 3160-5 (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM	A APPROVEI	)
OMB:	No 1004-013	7
Expires	March 31, 20	C

5. Lease Serial No

NM 0311499

6. If Indian, Allottee or Tribe Name

abandoned well.	Use Form 3160-3 (A	PD) for such proposal	s.				
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7 If Unit o	7 If Unit of CA/Agreement, Name and/or No.			
1 Type of Well Oil Well Gas W	ell Other	SEP 18 2007	8. Well Na	Well Name and No.     Burton Flat Deep Unit 6			
2 Name of Operator Devon Energy Production Co., LP	Name of Operator		A 9. API Wel	9. API Well No. 30-015-20921			
3a. Address 3b. Phone No. (include area code)		de) 10. Field ar	10. Field and Pool or Exploratory Area				
OKC, OK 73102-8260				Burton Flat; Atoka			
4. Location of Well (Footage, Sec., T, R, M., or Survey Description) Sec 34-T20S-R28E SWNE 1980 FNL & 1980 FEL			11 Country	11 Country or Parish, State Eddy County, New Mexico			
12 CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NATUR	E OF NOTICE, REPORT	f or othe	R DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACT						
Notice of Intent	Acidize	Deepen	Production (Start/	Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation		Well Integrity		
✓ Subsequent Report	Casing Repair	New Construction	Recomplete		Other Atoka Plugback;		
<b>-</b>	Change Plans	Plug and Abandon	Temporarily Abar	idon	Completion Report		
Final Abandonment Notice	Convert to Injection	✓ Plug Back	Water Disposal				
following completion of the involve testing has been completed. Final adetermined that the site is ready for 08/09/07 - 08/14/07:  MIRU. Bid well dwn. NU/BOP. Rishydro test tbg to 7000#. Top of pkr (10,940'. RIH w/50' cmt bir to dmp cr New PBTD @ 10,890'. PUH & perf TIH & set pkr @ 10,504' w/340 jts tb w/methanol + 100 ball sirs. RD tree	Abandonment Notices must by final inspection )  on/off tool & TOOH w/tbg. @ 10,942' - RU J kill & pick int on top of CIBP & stuck l Atoka @ 10,560' - 10,576 og in hole; EOT @ 10,514'	RU W/L; RIH w/guage ring & kle tbg - RD trk & TOH w/tbg. bir on top of CIBP. Tag on top '; (4SPF) 64 holes. RD W/L & . NU/DN/BOP - NU tree. Swa	ks, including reclamation  set dwn @ 10,786'. F Finish TOOH w/scrap of blr @ 10,886'. Blr set pkr & tbg. Bld dwn b. Acidize 10,560' - 10	, have been of RU tbg tstrs per - RU W 50' long - ro csg & tbg -	- PU 4 3/4" - 5.5" scrapper & //L. RIH & set 5.5" CIBP @ ope socket, CCL & 50' 3.5" bir pmp 20 fw dn csg to cut gas.		
14 I hereby certify that the foregoing is to	rue and correct		<del></del>				
Name (Printed/Typed) Stephanie A. Ysasaga		Title Sr. Staff	Engineering Technicia	an			
Signature		Date 09/17/20	007				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							

Title 18 U S.C. Section 1001 and Title 43 U.S C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Office

entitle the applicant to conduct operations thereon

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Approved by