

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTN.M. Oil Cons. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

S

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator **Armstrong Energy Corporation**3a. Address
P.O. Box 1973, Roswell, NM 882023b. Phone No. (include area code)
575-625-2222

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**990' FNL & 835' FWL, Unit D, NW/NW
Section 20-T11S-R27E****NOV 20 2007****OCD-ARTESIA**5. Lease Serial No.
NM-62182

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
North Park Federal #19. API Well No.
30-005-6255910. Field and Pool, or Exploratory Area
Coyote Wolfcamp11. County or Parish, State
Chaves County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☒ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other **Perforate**

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleting horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleting in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

10-22-07 R.U. Schlumberger, R.I.H. and perforate Wolfcamp "W-2" zone 5422-5430', 2 jsp, total 17 shots. P.O.H. and R.D. Schlumberger. T.I.H. with packer and tubing, set packer at 5350' with 20,000 lbs. tension.

10-23-07 Swab down tubing, no show. R.U. Halliburton and acidize with 2,000 gals. 15% NEFE acid and 34 7/8" ballsealers. Formation broke at 3268 psi, rate 3 BPM at 3100 psi, ball action 3000-3200 psi, balled out with 28 balls on at 4950 psi. Average pressure 3041 psi at 3.3 BPM. ISIP 2078 psi, 5 min. 385 psi, 10 min. 131 psi, 15 min. vac. 70 BLTR. Swabbing to recover load and test.

ACCEPTED FOR RECORD

OCT 26 2007

CARY GOURLEY

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)**Bruce A. Stubbs**Title **Vice President - Operations**

Signature

Date

10/25/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Accepted for record - NMOCD

11/2/07