Submit 3 Copies To Appropriate District Office Ener	State of New Mexico	Form C-103 May 27, 2004
District 1 1625 N. French Dr., Hobbs, NM 88240	5),	WELL API NO.
District II OII	CONSERVATION DIVISION	30-015-20570
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505		0. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		1724 CASS NORTH COM
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well Gas Well		291
2. Name of Operator	NOV 3 0 2007	9. OGRID Number
LCX ENERGY, LLC	OCD-ARTESIA	218885
3. Address of Operator	D. MY 70701	10. Pool name or Wildcat
110 N. MARIENFELD, STE. 200, MIDLAN	D, TX 79701	COLLINS RANCH; WOLFCAMP (GAS)
4. Well Location		
Unit Letter O: 660 feet from the SOUTH line and 1980 feet from the EAST line		
Section 29 Township 17S Range 24E NMPM County EDDY		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3825' Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
	E PLANS COMMENCE DR	
PULL OR ALTER CASING	LE COMPL	T JOB 🔲
OTHER:	☐ OTHER ⊠ : FRA	AC JOB
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
7/3/07 – 7/5/07 Rig Up rig, run tubing, bit and scraper to float collar at 8451', circulate clean, test casing to 2000 psi OK,		
POH. Run CBL, found TOC at 1810'. Run tubing, bit and scraper to float collar at 8451', drill out float collar and 10" cement		
to new PBTD of 8463'. Test casing to 5000 psi OK, pump pickle acid, (1000 gals 10% Acetic acid), circulate out and spot		
breakdown acid, (5000 gals 15% HCL). POOH, LD bit and scraper.		
7/6/07 TIH w/ TCP guns on tubing and Per	forate 1st Stage: 8460', 8240', 8020', 7	830', 7640', (50 – 0.42" holes) Break down
perfs at 15.8 BPM and 29070 psi. ISIP 1045 psi. POOH LD TCP guns. TIH w/ tubing, POOH LD tubing, ND BOPS, NU Well		
Head, RD rig.		
7/13/07 NU Frac Valve, Flowback Manifold	and BJ services Frac 1st Stage 8460	' - 7640' (50 - 0.42" holes) w/ 4500 gal
15% HCL, 2438 Bbls CO2 foamed slick water (74 tons CO2) w/ 2K lb 20/40 mesh sand and 12K lbs Lite Prop 125 20/40.		
73.3 BPM @ 3130 psi. ISIP 1890. RU WL, Lubricate in and run and set flow thru Frac Plug at 7530'. Perforate 2nd Stage		
7489, 7240', 7050', 6840, (50 – 0.42" holes). RD WL, RU BJ.	
I hereby certify that the information above is two	ue and complete to the hest of my knowledge	re and helief. I further contifu that any nit on hall-
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .		
1 1		1 1
SIGNATURE VICKIE L. GOTCHER Type or print name VICKIE L. GOTCHER	TITLE REGULATORY AN	ALYST DATE 1/29 0 7 nline.com Telephone No. 432-262-4013
For State Use Only		пппе.соп тетернопе №. 432-202-4013
Accepted for record .		12/12/
APPROVED BY:	TITLE	DATE 12/19/07
Conditions of Approval (if any):		