

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB No 1004-0137
Expires March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.5 Lease Serial No
NMNM9712
6 If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

7 If Unit of CA/Agreement, Name and/or No

1 Type of Well

☐ Oil Well☒ Gas Well☐ Other

DEC 11 2007

8 Well Name and No.
Chinaberry 5 Federal 12 Name of Operator
Devon Energy Production Co., LP

OCD-ARTESIA

9 API Well No
30-015-350133a Address
20 North Broadway
OKC, OK 73102-82603b Phone No (include area code)
(405)-552-780210 Field and Pool or Exploratory Area
Sheep Draw; Strawn (Gas)4 Location of Well (Footage, Sec, T, R, M, or Survey Description)
Sec 5-T23S-R26E SL Lot F 2300' FNL & 1400' FWL
BHL Lot E 1390' FNL & 738' FWL11. Country or Parish, State
Eddy County, New Mexico

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☒ Subsequent Report☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Final Abandonment Notice☐ Casing Repair☐ New Construction☐ Recomplete☒ Other Pull Packer☐ Change Plans☐ Plug and Abandon☐ Temporarily Abandon☐ Convert to Injection☐ Plug Back☐ Water Disposal

13 Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

11/30/07 - 12/01/07:

MIRU. Kill tbg & csg w/2% KCL. NU/DN/Tree - NU/BOP - RIs pkr @ 10,500'. TOH w/330 jts tbg - L/D sliding sleeve & pkr - kill well. TIH w/seat nipple & 280 jts tbg. Kill tbg & csg - finish TIH w/tbg as follows: KB 18' 330 jts of 2 7/8" N-80 tbg, 2 7/8" seat nipple @ 10,984'. NU/DN/BOP - NU/Tree - RD/MO/WSU. Turn well over to production.

Perforations Open:

10,270' - 10,290'

10,528' - 10,536'

10,538' - 10,546'

10,552' - 10,572'

14 I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Stephanie A Ysasaga

Title Sr Staff Engineering Technician

Signature

Date 12/03/2007

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

S/ DAVID R. GLASS
DEC 6 2007

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Accepted for record - NMOC

12/19/07