

Form 3160-5
(February 2005)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**OPERATOR'S COPY**FORM APPROVED
OMB NO. 1004-0137
EXPIRES: March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS**Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE - Other Instructions on page 2

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMLC060094
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP		6. If Indian, Allottee or Tribe Name
3a. Address 20 North Broadway, Ste 1500, Oklahoma City, OK 73102		7. Unit or CA Agreement Name and No.
3b. Phone No. (include area code) 405-562-4615		8. Well Name and No. Patton 6 Federal 5
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2090' FSL 1650' FWL 6 T18S R27E		9. API Well No. 30-015-29981
		10. Field and Pool, or Exploratory Area Red Lake; Q-GB-SA
		11. County or Parish, State Eddy NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once logging has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. MIRU for PA on 12/13/07.
2. TIM w/ tubing to CIBP @ 1,363'. Circulate wellbore w/ 10 ppg salt gel mud.
3. Spot cement plug from 1,363' up to 823'. (8-5/8" casing shoe @ 1,017')
4. Circulate cement from 100' to surface.
5. Cut wellhead off 3' below ground level. Set dry hole marker. Clean location.
6. Plugged & Abandoned - 1/8/08

Accepted for record
NMOCD TRI

ACCEPTED FOR RECORD

JAN 16 2008

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct

Name: **Ronnie Slack**Title: **Engineering Technician**

Signature

Ronnie Slack

Date

*1/8/08***THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

DEVON ENERGY PRODUCTION COMPANY LP

Well Name: PATTON 6 FEDERAL #5	Field: RED LAKE
Location: 2090' FSL & 1650' FWL; SEC 6-T18S-R27E	County: EDDY State: NM
Elevation: 3406' KB; 3397' GL	Spud Date: 11/22/98 Compl Date: 9/28/99
API#: 30-015-29981 Prepared by: Ronnie Slack	Date: 1/8/08 Rev:

PLUGGED & ABANDONED
1/8/08

Plug & Abandonment

1. Circulate cement from 100' to surface
2. Cut wellhead off 3' below ground level
3. Set dry hole marker, clean location.

10# Mud

12-1/4" Hole
8-5/8", 24#, J55, @ 1.017"
Cmt'd w/550 Sx. Circulated to surface.

Plug & Abandonment

1. RIH to CIBP @ 1,363'
2. Circulate hole w/10# salt gel mud
3. Spot 60 Sx cement from 1,363' up to 823'
4. Test casing to 500 psi. Ok.

UPPER SAN ANDRES
1384' - 1390'

CIBP @ 1363' (1/4/05)

SAN ANDRES
1508' - 1526'

CIBP @ 1540'

1558' - 1592'
1600' - 1651'
1706' - 1800'

7-7/8" Hole
5-1/2", 15.5#, J55, @ 2.297"
Cmt'd w/380 Sx. Circulated to surface.

2300' TD