Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JAN 29 2008 OCD-ARTESIA

FORM A	PPRO	VE
OMB No	1004	-013
Evoures In	Jv 21	201

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

5 Lease Serial No NMLC-028990B

abandoned well. Use Form 3100-3 (APD) for such proposals.		o it indian, Allottee of Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2.		2.	7 If Unit or CA/Agre	eement, Name and/or No	
1 Type of Well Oil Well Gas Well X Other P&A			8 Well Name and No		
2 Name of Operator			Creek AL Federal #2		
Yates Petroleum Corporation		9. API Well No.			
3a Address 3b Phone No (include area code)		ea code)	30-015-04540		
105 S. 4th Str., Artesia, NM 88210 575-748-1471		10. Field and Pool or Exploratory Area			
4 Location of Well (Footage, Sec ,T.,R.,M., OR Survey Description)			Shugart Yates 7Rivers Queen Grayburg		
		11 County or Parish, State			
660'FSL & 660'FEL of Section 24-T18S-R30E (Unit P, SESE)			Eddy County, New Mexico		
12. CHECK APPROPRI	ATE BOX(ES) TO IND	ICATE NATURI	E OF NOTICE, RE	PORT, OR OT	HER DATA
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION				•
	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity
	Casing Repair	New Construction	Recomplete		Other
X Subsequent Report	Change Plans	X Plug and Abando	n Temporarily	Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispo	sal	
2018'. Spotted 50 sx cemer 1/17/08 RIH to tag. No tag. Spotter 1/20/08 Tagged at 975'. Perforated WOC. Perforated at 150'. 1/21/08 Tagged at 650'. Re-spotted circulated to surface. Fell b 1/22/08 Tagged at 107' and called E WOC. Pumped 15 sx cemer	Vork and wash pipe through d at 2174'. RIH with tubing a nt at 1820' and WOC. Tagg d 30 sx cement at 1690' and at 798' and pumped 140 sx d 50 sx cement with LCM and tack and WOC. Tagged at 18LM. Pumped 30 sx cement to surface and stayed full	end tagged at 1820 ed at 1768'. Spotte WOC. Tagged at cement. WOC. Tod 2% CaCl2 and W 58'. Circulated 20 No circulation. V I. Cut off wellhead	or - Call BLM. Pumped ed 25 sx cement at 16 1768'. Spotted 50 sx agged at 965'. Re-spotted CC. Tagged at 650'. sx cement to surface.	d 30 sx cement at 190' and WOC. cement at 1690' a otted 100 sx thru pumped 100 sx. Fell back and we cement to surface	1820'. Tagged at and WOC. perfs at 798' and cement and
	ABANDONED. FINAL REP	<u>UK1</u> .			
14. I hereby certify that the foregoing is true an Name (Printed/Typed) Tina Hue		Title R	egulatory Complia	ance Superviso	or
Signature (\lambda in a) \lambda	erta		anuary 25, 2008		
	THIS SPACE FOR	FEDERAL OR STA	ATE OFFICE USE		
Approved by		7,	itle	Date	
Conditions of approval, if any, are attached of certify that the applicant holds legal or equita which would entitle the applicant to conduct op	ble title to those rights in the su	warrant or	Office		
Title 18 U S C Section 1001 and Title 43 U S.	C Section 1212, make it'a crime	for any person known	ngly and willfully to make	to any department or	agency of the United States

any false, fictilious or fraudulent statements or representations as to any matter within its jurisdiction