Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.
1625 N French Dr , Hobbs, NM 88240 District II	OH CONCEDUATION DIVIDION	30-015-29926
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505		20761
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Barclay State
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		8. Well Number
	Well Other	8
2. Name of Operator	o 0 2000	9. OGRID Number
Forest Oil Corporation	,ian 3 0 2008	10 D 1 W'11
3. Address of Operator 707 17 th Street, Suite 3600, Denver, Col	orada OCD-ARTESIA	10. Pool name or Wildcat Livingston Ridge South (Delaware)
	orado	Elvingston Riage South (Delaware)
4. Well Location		
Unit Letter: I feet from the 990 line and North feet and 470 from the East line		
Section 2 Township 23S Range 31E NMPM County Eddy		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3447		
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to Groundwater_	Distance from nearest fresh water well Dis	tance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume bbls; Co	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PAND A COMMENCE DRILLING OPNS.		
TEMPORARILY ABANDON		
FOLL ON ALTER CASING [] INC	DETIFIE COMPE	1 300
OTHER:	OTHER: Rod I	Repair⊠
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
12-17-07 Spot rig, rig broke down, from oil cooler. SION		
12-18-07 RU PU L.D. P.R. & a 2' x 7/8 sub, & 1-7/8 rod, pick up 8',6', 4' 2', 7/8 sub, ND WH to check TAC, if it was set, it was, WH		
12-19-07 Pick 2' x 7/8 sub from weatherford drove to location. Pull out P.R. & Add 2' 7/8 EL sub, RBIH P.R.space pmp, 45" from		
bottom RU hot oiler load tbg 27 bbls wtr press. 500# hold good. Check pmp, long stroke, good pmp action, RD hot oiler, RD		
PU clean location. M.O. weatherford will move Rollo Fax later today.		
	e is true and complete to the best of my knowledg according to NMOCD guidelines 🛭, a general permit 🗌	
SIGNATURE	TITLE Sr. Regulatory Tech	DATE 1-8-08
SIGNATURE	FITEE St. Regulatory Teen	DATE 1-0-00
Type or print name <u>Cindy Bush</u>	E-mail address: cabush@forestoil.com	Telephone No. 303-812-1554
For State Use Only FOR RECO	RDS ONLY	Institut day of a company
APPROVED BY:	TITLE	DATE FEB 0 1 2008
Conditions of Approval (if any): RECEIVED		
0 2		

JAN 112008

HOBBS OCD