

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-36004
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name RDX 16
8. Well Number 1
9. OGRID Number 246289
10. Pool name or Wildcat Brushy Draw - Delaware East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator RKI Exploration and Production, LLC.	
3. Address of Operator 3817 NW Expressway, Suite 950, Oklahoma City, OK. 73112	
4. Well Location Unit Letter <u>O</u> : <u>990</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>16</u> Township <u>26S</u> Range <u>30E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,056' GR	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Bond Log, Perf, Acidize, Frac <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Completion operations commenced on 2-25-08. Moved in the rigged up a completion rig. Installed and tested BOPE. Ran 4-3/4" bit. Drilled out DV tool and cleaned out fill/cement to 7,528'.

Ran cement bond log from 7,531' to 2,700'. Found top of cement at 2,870'. Perforated Delaware zone 6,321'-6,359' (total 76 holes). Acidized with 2,000 gal. 7-1/2% HCl using 114 ball sealers. Rigged up wireline. Ran gauge ring to 6,400'. Rigged down wireline unit. Fracture stimulated via 5-1/2" casing at 50 bpm with 63,695 gals. 10# brine, 7,600# 14/30 LiteProp 125, 2,000 # 20/40 white sand, and 15,000# 16/30 resin-coated proppant.

Tripped in hole with 4-3/4" bit to 7,221 and did not tag any fill. Circulated hole clean. Installed rod pump equipment and flow tested well. Completions operations completed on 2-29-08.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Gene Simer TITLE SUPERINTENDENT DATE 3/5/08

Type or print name GENE SIMER E-mail address: gsimer@rkixp.com Telephone No. 505-885-1313

For State Use Only

APPROVED BY: _____ TITLE _____ DATE _____

Conditions of Approval (if any): _____

Accepted for record - NMOCD