

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA



FORM APPROVED
OMB No. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side

1 Type of Well ☒ Oil Well ☐ Gas Well ☐ Other

2 Name of Operator **Asher Enterprises**

3a Address **12808 Lorien Way**

3b Phone No (include area code) **405-735-5645**

4 Location of Well (Footage, Sec., T., R. M., or Survey Description)

P-26-175-30E

5 Lease Serial No **LC 030570 B**

6 If Indian, Allottee or Tribe Name

7 If Unit or CA/Agreement, Name and/or No. **Grayburg Jackson Unit NM 709557**

8 Well Name and No. **4**

9 API Well No **30-015-043411**

10 Field and Pool, or Exploratory Area **GBJSA**

11 County or Parish, State

Eddy

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PA PROCEDURE

1-30-08 RIG UP

1-31-08 POOH W/ TUBING

2-1-08 RIH W/TUBING AND SPOT 30 SACK PLUG @ 3110' - POH

2-4-08 RIH AND TAG @ 3123' CIRCULATE PLUGGING MUD - PUH - PUMP 25 SACKS @ 1386' POH - WOC - RIH - AND TAG @ 1004' - RIH AND PERF @ 575'

2-5-08 RIH WITH PACKER AND PUMP 60 SACKS - POH - WOC - RIH AND TAG @ 475'. CALL BLM - RIH AND PERF @ 60' - CIRCULATE 40 SACKS TO SURFACE

2-6-08 DIG OUT CELLAR - CUT OFF WELLHEAD AND ANCHORS AND INSTALL DRY HOLE MARKER

ACCEPTED FOR RECORD

MAR 28 2008

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Kellye Jones


Signature

Kellye Jones

**Gerry Guye, Deputy Field Inspector
NMOCD-District II ARTESIA**

Date

3-12-08



THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 USC Section 1001 and Title 43 USC Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)