

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505



WELL API NO.

90-30-015-33721

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

JUL 18 2008

7. Lease Name or Unit Agreement Name

OCD-ARTESIA

Foot Joy "14" State

8. Well Number

1

9. OGRID Number

004378

10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

CHI OPERATING, INC

3. Address of Operator

PO BOX 1799 MIDLAND, TX 79702

4. Well Location

Unit Letter A : 990 feet from the NORTH line and 710 feet from the EAST line

Section 14 Township 19S Range 27E NMPM EDDY County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3458' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RU DDP

POOH with packer and 2 3/8" production tubing

PU CIBP and RIH to 8,470' - set plug.

Notify NMOCD of intent to perform mechanical integrity test by pressure testing 5 1/2" casing to 500 psi for 30 mins.

Dump 35' of cement on top of CIBP

Clean location.

**Notify OCD 24 hrs. prior to
Any work done.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been ~~will be~~ constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE: [Signature] TITLE: Regulatory Clerk DATE: 7/6/08

Type or print name: PAM CORBETT E-mail address: pamc@chienergyinc.com Telephone No: 432-685-5001

For State Use Only

APPROVED BY: [Signature] TITLE: Gerry Guye DATE: JUL 18 2008
Conditions of Approval (if any): Compliance Officer