

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

JUL 16 2008
OCD-ARTESIA

FORM APPROVED
OMB NO. 1004-0135
EXPIRES. March 31, 2007

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE

1a. Type of Well ☐ Oil Well ☒ Gas Well ☒ Other _____

2. Name of Operator
DEVON ENERGY PRODUCTION COMPANY, LP

3. Address and Telephone No.
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611

4. Location of Well (Report location clearly and in accordance with Federal requirements)*
1980 FNL 1980 FEL G SEC 17 T22S R28E

5. Lease Serial No.

NM-0415688-A

6. If Indian, Allottee or Tribe Name

7. Unit or CA Agreement Name and No.

8. Well Name and No.

Foal 17 Federal Com 1

9. API Well No.

29656
30-015-35892-

10. Field and Pool, or Exploratory

11. County or Parish State

Eddy

NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

2/5/08 - 5/30/08 MIRU. ND tree. NU BOP. Fish bad csg above 4040'. Csg pulled in two (split collar looking up) below cut point. RU WL & RIH w/ temp survey tool 9500' to surf. Attempt to cut csg w/chem cutter. RIH to 4200', did not fire. TOO H w/ cutter & bad csg. RIH w/ seal lead patch on new 7" 26# J-55 csg. Failed to seal. RIH w/pkr. Test csg to 3500#, ok. RIH w/ mech cutter & cut off csg stub @ 4336'. CO junk in hole. DO CIBPs. Repair sd line & RIH w/ shoe w/ diamond cutters & wire. Rec 5 3/8" plate & 3" of stem from jet cutter. Made magnet & shoe runs impression block; looks like top of RBP retrv hd. POOH w/ RBP @ 10,526'. DO CIBPs & perm pkr. CHC. RIH w/ 4 1/2" liner to 12,456'. Test liner & seal to 1500#. RU BJ pump 20 bbls Turboflow 111 @ 11.5#/g + 5 g FW + 500g Surebond 111 + 10 bbls FW. Cmt w/ 235 sx POZ C + CSE +2 + 0.3% R-3 + 1% bwow Potassium Chloride + .75% bwoc EC-1 + 0.125#/sx CF + 0.4% bwoc CD-32 + 3#/sx LCM-1 + 0.6% bwoc FL-25 + 0.6% bwoc FL25A + 72.3% FW. Circ 72 sx to pit. TOL @ 10,564'. Set on btm @ 12,456'. New PBTD @ 12,409'. Test @ 1500#, ok. CHC. Swab. Perf Morrow 12,296-312'. RDPU & RU & RIH w/ swab. Acidize perfs w/2500 g 7 1/2% acid + 20% methanol. Swab. Set CIRC @ 12,240'. Sqz L. Morrow 12,296-312' w/125 sx H to 5600# w/38 sx in perfs. Perf M. Morrow 11940-12152' @ 2 spf. Acidize w/ 2500g 7 1/2% HCL w/10% methanol & 100 BS. Swab. LT w/ KCL wtr. Rise pkr. TIH w/ ArrowSet pkr & 2 3/8" tbg @ 11,877'. ND BOP. NU Tree. Test pkr to 1000#. Swab. POP.

14. I hereby certify that the foregoing is true and correct

Signed Judy A. Barnett Name Judy A. Barnett X8699
Title Regulatory Analyst Date 6/19/2008

(This space for Federal or State Office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations to any matter within its jurisdiction

*See Instruction on Reverse Side

Accepted for record - NMOCD

