

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Primero Operating, Inc.

3a. Address

PO Box 1433, Roswell, NM 88202-1433

3b. Phone No. (include area code)

505-622-1001

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 20. T16S, R31E. 804' FNL & 1650' FWL

JUL 22 2008

OCD-ARTESIA

5. Lease Serial No

NM-77042

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No

Ford Federal # 3

9. API Well No.

30-015-36083

10. Field and Pool, or Exploratory Area

Square Lake, GB/SA

11. County or Parish, State

Eddy, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☒ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other Add Premier

and Penrose zones

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1/09/08 Perforate Premier 3334-3343. 3 spf and acidize w/ 1500 gals 10% NEFE

1/11/08 Frack Premier w/ 35800 lbs 16/30 sand carried by 943 bbls gel.

Install wireline RBP @ 3250' and perforate Penrose formation 2912-23'. 3 spf

Frack Penrose formation w/ 53,480 lbs 16/30 sand carried by 1113 bbls gel.

After swabbing most of the load, 2 7/8" tubing was run with seating nipple set at 3495'. 3/4" rods were run and

the well was put on pump. The Irvington, Premier and Penrose zones are commingled down hole.

Note: This is a correction of previously submitted form.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Phelps White

Title President

Signature

Date 1/14/08

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date

JUL 18 2008

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

ACCEPTED FOR RECORD

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

FOR RECORDS ONLY