Form 3160-5 RECEIVED (September 2001)

## Oil Coris. N.M. DIV-Dist. 2 UNITED STATES 01 W. Grand Avenue DEPARTMENT OF THE INTERLOP. BUREAU OF LAND MANAGEMENTA, NM 88210

FORM APPROVED OMB No. 1004-0135

Expires January 31, 2004

LES BARYAK

PETROLEUM EI

OCD-APTESIA NOTICES AND REPORTS ON WELLS

NM-90807

5. Lease Designation and Serial No.

Do not use this form for proposals to drill or to re-enter an Abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee of	r Tribe Name	
Abandoned Well.	ose i omi o ioo-o (Ai D) ioi	Suon proposaio.			
SUBMIT IN TRIPLICATE – Other instructions on reverse side			7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well			Osage Federal	Osage Federal	
X Oil Well Gas Well Other					
2. Name of Operator			8. Well Name and No.	1	
St. Mary Land & Exploration Co. c/o Nance Petroleum Corporation			ı #17		
3. Address and Telephone No.			9. API Well No.	1	
P.O. Box 7168, Billings, MT 59103, Phone 406-245-6248				30-015-26298	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			· ·	10. Field and Pool, or Exploratory Area	
2310' FSL & 2310' FWL				Parkway Bone Spring & Delaware	
Sec. 34-T19S-R29E UL:K			11. County or Parisl	11. County or Parish, State	
			Eddy Co.	Eddy Co., NM	
12. CHECK APPRO	PRIATE BOX(s) TO INDIC	ATE NATURE OF N	OTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Res	sume) Water Shut-Off	
	Alter Casing (add perfs)	Fracture Treat	Reclamation	Well Integrity	
x Subsequent Report	Casing Repair	Casing Repair New Construction Recomplete Other			
	Change Plans	x Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
13. Described Proposed or Completed C thereof. If the proposal is to deepen dire and zones. Attach the Bond under which within 30 days following completion of the shall be filed once testing has been computed that the site	ctionally or Recomplete horizontally the work will be preformed to provide involved operations. If the operal leted. Final Abandonment Notices is ready for final inspection.)	y, give subsurface locations yide the Bond No. on file wi ation results in a multiple co shall be filed only after all r	and measured and true vertical th BLM/BIA. Required subsection or recompletion in a requirements, including reclamations.	depths of all pertinent markers quent reports shall be filed new interval, a Form 3160-4 ation, have been completed, and	
9/26/03 RU Well Pluggers, Inc for turnkey P&A job			jaregon is composed umi jaregon is composed umi	erenta,	
9/27 – 10/3/03 1) Tag top of plug at 5260' 2) Circ. 9.5 # mud from 5260' to surface					
,	Δ	PPROVED			
3) Spot 31 sx c		A D X A SHEET			
4) Free point in 5 ½" csg @ 2900'; Cut & pull csg @ 2600'					
5) Circ. 9.5# m		3			
6) Spot 31 sx c					
7) Spot 31 sx cement @ 1170': WOC: Tag TOC @ 1032'					

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed Herb Thackeray

8) Spot 16 sx surface plug; Install dry hole marker

Title Operations Engineer

Date 10/292/03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved By Title Date Condition of Approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.