



4

**marbob**  
energy corporation

January 8, 2008

Oil Conservation Division  
1301 W. Grande Ave.  
Artesia, N.M. 88210

Attention: Bryan Arrant

Re: E L Federal #9	330' FNL & 790' FEL, Sec 21, T17S - R30E	Eddy County, New Mexico	30 015 36160
Loco Federal #6	1750' FNL & 2310' FEL, Sec 21, T17S - R30E	Eddy County, New Mexico	30 015 36164
Tyler Federal #3	690' FNL & 330' FWL, Sec 21, T17S - R30E	Eddy County, New Mexico	30 015 36159
Red Federal #5	1650' FSL & 330' FEL, Sec 17, T17S - R30E	Eddy County, New Mexico	30 015 36163
Birdie Federal #9	1650' FNL & 990' FEL, Sec 17, T17S - R30E	Eddy County, New Mexico	30 015 36158
Birdie Federal #12	2310' FSL & 1650' FWL, Sec 17, T17S - R30E	Eddy County, New Mexico	30 015 36161
Randy Federal #5	2310' FNL & 1650' FEL, Sec 22, T17S - R30E	Eddy County, New Mexico	30-015-36162

Dear Bryan:

Marbob Energy has conducted a review to determine if an H2S contingency plan is required for the above referenced wells. We were able to conclude that any potential hazardous volume would be minimal. H2S concentrations of wells in this area from surface to TD are low enough; therefore we do not believe that an H2S Contingency Plan would be necessary.

Please advise us if you feel differently or need further information.

Sincerely,

Nancy Agnew  
Landman

/na