

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
811 South First, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO.  
30-015-25458

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-255

7. Lease Name or Unit Agreement Name

GJ West Coop Unit

8. Well No.  
77

9. Pool name or Wildcat  
Grayburg Jackson, SR, QN, GB, SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Mack Energy Corporation

3. Address of Operator  
P.O. Box 960, Artesia, NM 88211-0960

4. Well Location

Unit Letter O : 330 Feet From The South Line and 2310 Feet From The East Line  
Section 28 Township 17S Range 29E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3561' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set CIBP @ 2347' w/35' cement cap. Top perf @ 2447' *255x plug @ 895'*
3. Set 100' plug from 670-570', 50' above and below bottom of salt, WOC and tag.
4. Set 100' plug from 325-225', 50' above and below 8 5/8" casing shoe. - *TA*
5. Set 10 sx surface plug, WOC and tag.
6. Install dry hole marker.

Notify OCD 24 hrs. prior to any work done

Salt gel mud consisting of 10#  
Brine W/25# of gel per bbl  
must be placed between each plug

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 10/31/2003  
TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO (505)748-1288

(This space for State Use)

APPROVED BY [Signature] TITLE Wild Sep ID DATE NOV 13 2003  
CONDITIONS OF APPROVAL, IF ANY: