

Submit 3 Copies To Appropriate District
 Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505


State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised May 08, 2003

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30.015.22823
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: Empire Abo Unit "G"
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well No. 361
2. Name of Operator BP America Production Company		9. OGRID Number 000778
3. Address of Operator P.O. Box 1089 Eunice NM 88231		10. Pool name or Wildcat Empire Abo
4. Well Location Unit Letter H : 2400 feet from the N line and 300 feet from the E line Section 34 Township 17S Range 28E NMPM County Eddy		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3670.5' GR		



12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: MIT	<input checked="" type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10.16.03: Load and test casing to 580# psi. Held 30 mins. Casing test was not witnessed by a NMOCD representative. Chart attached.

BP America Production Company has evaluated this wellbore and has determined that there is production potential in the Abo formation. Permission to retain TA status is therefore requested in order to complete our current workover program and develop another workover program which will require interest owner approval to provide funding.

Temporary Abandoned Status approved
 on 10-16-06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Staff Support DATE 10.24.03

Type or print name Kellie D. Murrish Telephone No. 505.394.1649

(This space for State use)
 APPROVED BY [Signature] TITLE Field Rep DATE 10-28-03

Conditions of approval, if any: **APPROVED OCT 28 2003**

