Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources May 27, 2004 WELL API NO. 1625 N. French Dr , Hobbs, NM 88240 District II 30-005-63036 OIL CONSERVATION DIVISION 1301 W Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 🖂 FEE 1000 Rio Brazos Rd , Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr , Santa Fe, NM 87505 V-2982 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Quincy AMQ State 1. Type of Well: Oil Well Gas Well Other 8. Well Number #6 2. Name of Operator 9. OGRID Number Hanson Operating Company, Inc. 009974 илы 0.5 2009 3. Address of Operator 10. Pool name or Wildcat P. O. Box 1515, Roswell, NM 88202-1515 Acme San Andres Southeast OCD-ARTESIA 4. Well Location Unit Letter 2310 feet from the North feet from the West line and 12 Township 8 South Range 27 East Section **NMPM** Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3947' GR Pit or Below-grade Tank Application 🗌 or Closure 🔲 Pit type Depth to Groundwater >100' Distance from nearest fresh water well >2 miles Distance from nearest surface water >10 miles Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING □ PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK П P AND A TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. Ø П PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: \Box OTHER: П 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Plug and abandon well as follows: 10/31/2008: MIRU. Set CIBP at 2054'. Circulate hole with 10# brine with 12.5# per barrel salt water gel. Spot 25 sack cement plug on CIBP. Perforate 4 squeeze holes at 464'. Pump 120 sacks cement and circulate to surface. Well plugged and abandoned. Plugging witnessed by Phil Hawkins. Clean and remediate location, and set Dry Hole Marker by January 31, 2009. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines 🖂, a general permit 🗌 or an (attached) alternative OCD-approved plan 🗔. TITLE Production Analyst SIGNATURE DATE 12/30/2008 E-mail address: hanson@dfn.com Telephone No. 575-622-7330 Type or print name For State Use Only Accepted for record Approved for plugging of well bore only. APPROVED BY: TITLE Liability under bond is retained pending r Conditions of Approval (if any): NMOCD of C-i03 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.