Stemit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico Energy, Minerals and Natural Resources	Form C-103 May 27, 2004 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-005-63050
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE ☐ FEE ☐
1000 Rio Brazos Rd , Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505	V-2982
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	7. Lease Name or Unit Agreement Name Quincy AMQ State
1. Type of Well: Oil Well Gas Well Other	8. Well Number
2 Name of Outside the	#7 9. OGRID Number
Hanson Operating Company, Inc. OCD-ARTESIA	009974
3. Address of Operator	10. Pool name or Wildcat
P. O. Box 1515, Roswell, NM 88202-1515	Acme San Andres Southeast
4. Well Location	
Unit Letter F: 1650 feet from the North line and 165	
Section 12 Township 8 South Range 27 East 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Chaves County
3956' GR Pit or Below-grade Tank Application or Closure	
Pit typeDepth to Groundwater <u>>100'</u> Distance from nearest fresh water well <u>>2 miles</u> Distance from nearest surface water <u>>10 miles</u>	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING OPNS. PAND A STATTING Any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Plug and abandon well as follows:	
10/31/2008: MIRU. SD. 11/03/2008: Set CIBP at 2100'. Circulate hole with 10# brine with 12.5# per barrel salt water gel. Spot 25 sacks cement plug on CIBP. Perforate 4 squeeze holes at 460'. Unable to break down perfs. 11/04/2008: Pump 50 sack cement plug inside 5 ½" casing and circulate to surface. Well plugged and abandoned. Witnessed by Phil Hawkins. Clean and remediate location, and set Dry Hole Marker by January 31, 2009.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURE and J. Smith TITLE Production Analyst	DATE <u>12/31/2008</u>
Type or print name Carol J. Smith E-mail address: hanson@dfn.com	Telephone No. 505-622-7330
For State Use Only ACCEPTED for record Approved for plugging of the Approved for plugging for plugg	cell hore only.
APPROVED BY: Conditions of Approval (if any): NMOCD TITLE Liability under bond is ret of C.103 (Subsequent Rep which may be found at OC Forms, www.cmnrd.state.n	ort of Well Plugging DATE // 6/57 D Web Page under