

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-015-32472
Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.	
Lease Name or Unit Agreement Name	Pecos 32 State
Well No.	
Pool name or Wildcat	McMillan Morrow North (Gas)
Line and Loc.	Line 1650
Section	32
Township	19S
Range	27E
NMPM	Eddy
County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	3325'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Pogo Producing Company	
Address of Operator P. O. Box 10340, Midland, TX 79702-7340	
Well Location Unit Letter C : 660 Feet From The North Line and Loc. 1650 Feet From The West Line	
Section 32 Township 19S Range 27E NMPM Eddy County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3325'	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☒ PLUG AND ANBANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud & Set Surface Csg - MIRU Patterson #142. Spud well @ 03:00 hrs 06/02/03. Drld 17-1/2" hole to 225'. TD reached @ 12:45 hrs 06/02/03. Ran 5 jts 13-3/8" 48# H-40 ST&C csg. Cmt'd w/ 300 sks Cl "C" + 2% CaCl2 @ 14.8 ppg. Plug down @ 16:00 hrs 06/02/03. Circ 100 sks to surface. WOC 18 hrs. Make cut-off. Weld on WH. NU BOP's & test ok.

Intermediate Csg - Drld 12-1/4" hole to 3010'. TD reached @ 12:00 hrs 06/07/03. Ran 73 jts 9-5/8" 53.5# N-80 & P-110 BTC & LTC, 43.5# N-80 LTC. Cmt'd w/ 600 sks 35:65 POZ C + 1% CaCl2 @ 14.8 ppg. Plug down @ 10:45 hrs 06/08/03. Circ 130 sks to surface. WOC 22 hrs. Make cut-off. Install WH. NU BOP's & test to 5000#ok.

TD & Production Csg - Drld 7-7/8" hole to 10,585'. Logged well w/ Schlumberger. Notified Mike Bratcher of NMOCD of plugback job. Set plug #1 @ 10520 - 120 sks Cl "H" + additives @ 15.7 ppg. Set plug #2 @ 10170 - 60 sks Cl "H" + additives @ 15.7 ppg. Set plug #3 @ 9624 - 100 sks Cl "H" + additives @ 15.7 ppg. Set plug #4 @ 8100 - 100 sks Cl "H" + additives @ 15.7 ppg. Set whipstock plug @ 7700 - 230 sks Cl "H" @ 17.5 ppg. Drld 7-7/8" hole to 10870'. TD reached @ 01:45 hrs 07/31/03. Logged well w/ Schlumberger. Ran 258 jts 5-1/2" 17# L-80 LT&C csg. Cmt'd 1st stage w/ 950 sks Cl "H" + additives @ 15.7 ppg. Circ 201 sks to surface. Cmt'd 2nd stage w/ 725 sks Cl "C" + additives @ 14.09 ppg. Circ 200 sks to surface. Cmt'd 3rd stage w/ 475 sks 65:35 POZ "C" @ 12.4 ppg followed by 100 sks Cl "C" Neat @ 14.8 ppg. Plug down @ 17:45 hrs 08/02/03. No cmt circulated. Ran CBL 08/17/03. TOC @ 1040'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy Wright TITLE Sr. Operation Tech DATE 10/09/03  
TYPE OR PRINT NAME Cathy Wright 432-685-8100 TELEPHONE NO.

(This space for State Use)

APPROVED BY

Jim W. Brown

TITLE

District Supervisor

DATE

OCT 20 2003

CONDITIONS OF APPROVAL, IF ANY: