Submit 3 Copies To Appropriate District State of New Mexico	
Some OI I TO I I I I I I I I I I I I I I I I	Form C-103
Office District I Energy, Minerals and Natural Resources	MAR 2 5 2009 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-31791
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	o. State on & das hease 10.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	, ,
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State 14 Com
1. Type of Well: Oil Well Gas Well Other	8. Well Number
	002
2. Name of Operator	9. OGRID Number
Cimarex Energy Co. of Colorado	162683
3. Address of Operator	10. Pool name or Wildcat
5215 N. O'Connor Blvd., Ste. 1500; Irving, TX 75039	Turkey Track; Atoka
4. Well Location	
SHL Unit Letter E: 2040 feet from the North line and 560	feet from theWestline
Section 14 Township 19S Range 29E NMPM	CountyEddy
Section 14 Township 19S Range 29E NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3410' GR	c.)
THE LANGE PARTY MADE AND THE PROPERTY OF THE PARTY OF THE	And the second s
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well	_ Distance from nearest surface water
Pit Liner Thickness: Below-Grade Tank: Volume bbls; Co	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	<u> </u>
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DI	-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	NT JOB
OTHER: Request continued TA 🛛 OTHER:	
10. December and a community of the continue o	give pertinent dates, including estimated date of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and g starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v recompletion.	
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v recompletion.	
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v	
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06).	wellbore diagram of proposed completion or
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06).	wellbore diagram of proposed completion or
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). O3-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich	wellbore diagram of proposed completion or name of proposed completion or name of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06).	wellbore diagram of proposed completion or name of proposed completion or name of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). O3-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a	wellbore diagram of proposed completion or nard Inge of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a	wellbore diagram of proposed completion or nard Inge of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a	wellbore diagram of proposed completion or nard Inge of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). O3-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a	wellbore diagram of proposed completion or nard Inge of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich	wellbore diagram of proposed completion or nard Inge of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). O3-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a	wellbore diagram of proposed completion or nard Inge of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a	wellbore diagram of proposed completion or nard Inge of the Artesia NMOCD witnessed.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach vincompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a Until 2/2/2001	wellbore diagram of proposed completion or hard Inge of the Artesia NMOCD witnessed. Iready on file at the OCD.
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach verecompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a Until 2/2.	wellbore diagram of proposed completion or hard Inge of the Artesia NMOCD witnessed. Iready on file at the OCD. Complete Artesia NMOCD witnessed.
recompletion. CIBP @ 11165' w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a	wellbore diagram of proposed completion or hard Inge of the Artesia NMOCD witnessed. Iready on file at the OCD. Conduction Opioved A 2010 dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach vincompletion. CIBP @ 11165′ w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a Until 2/2. I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit [1]	dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE March 24, 2009
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach vecompletion. CIBP @ 11165′ w/ 25 sx cmt on top (set in 01-06). 03-02-09 Filled hole with fluid and ran MIT test to 500 psi for 30 minutes. Rich Cimarex requests continued TA of this well. Please note that the chart is a Until 2/2. I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit SIGNATURE Value September 17 SIGNATURE Regulatory Analyst Type or print name Natalie Krueger email address: nkrueger@cimarex.cepor State Use Only	dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE March 24, 2009