•							
Statistical Control To Assessing Princip					_	_	
Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources					Form Revised March		
1625 N. French Dr., Hobbs, NM 88240 District II	O		i	WELL API NO 30-). -015-32591		
1301 W. Grand Avenue, Artesia, NM 88 District III	y=.v	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	razos Rd., Azicc, NM 87410 Santa Fe, NM 87505			STATE FEE 6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 8		,	'	6. State Oil &	¿ Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit Agreement N			
DIFFERENT RESERVOIR. USE "APF PROPOSALS.)					TIZ NOW		
1. Type of Well:							
Oil Well Gas Well 2. Name of Operator		· · · · · · · · · · · · · · · · · · ·		8. Well No.			
MURCHISON OIL & GAS, INC.				1			
3. Address of Operator 1100	MIRA VISTA BLVD.,	PLANO, TX. 7	5093-4698	9. Pool name EAGLE CRE	or Wildcat EK;ATOKA-MOF	R	
4. Well Location							
Unit Letter H	: 1480 feet from th	e NORTH	_ line and6	60 fcet fi	rom the <u>EAST</u>		
Section 29	Township	17S Range		NMPM	County EDI	YC	
	10. Elevation (Show	w whether DR, RI	KB, RT, GR, etc.,		7		
11. Checl	Appropriate Box to I	Indicate Nature	e of Notice, R	eport or Othe	er Data		
NOTICE OF	INTENTION TO:		SUBS	EQUENT R	EPORT OF:		
PERFORM REMEDIAL WORK[PLUG AND ABANDO	N L RE	MEDIAL WORK		ALTERING CA	SIN	
TEMPORARILY ABANDON [CHANGE PLANS		MMENCE DRILI	LING OPNS.	PLUG AND ABANDONME	٧T	
PULL OR ALTER CASING [MULTIPLE COMPLETION		SING TEST AND MENT JOB)			
OTHER:			HER:				
 Describe proposed or con of starting any proposed we or recompilation. 	apleted operations. (Clear ork). SEE RULE 1103. For	arly state all pertinor Multiple Comp	nent details, and olctions: Attach	give pertinent d wellbore diagra	lates, including esti- m of proposed com	nat ple	
Drilled 8-1/2" hole to a	depth of 8705'. Logged			abandon well a	as follows. Pump		
		' w/ 60 SXS CI ' w/ 60 SXS CI					
· P	Plug #3 5560' - 5560'	w/ 50 SXS CI					
		w/ 50 SXS CI w/ 50 SXS CI					
	Plug #6 1343' - 1567'	w/ 50 SXS CI	ass "C"				
r		cement @ 1343					
۲	Plug #7 290' to 460' WOC, Tag top of	w/ 50 SXS Cla cement @ 295'					
, P	Plug #8 0' to 64'	w/ 30 SXS C					
Nipple down BOP and	Circulate 5 SXS to s cut off wellhead and inst		marker. Relea	se ria 1200 Hr	3/29/03 Wellbo	re	
schematic attached.		A T I WAI		I	. 5,25,55. 11000	-	
I hereby certify that the informa	ition above is true and com	plete to the best	of my knowledge	e and belief.			
SIGNATURE // NOME	UJU/augkuly	TITLE	V P OPERATI	ONS	DATE_4/7/03		
Type or print name MICHA	AEL S. DAUGHERT	Υ		Te	lephone No. (972)	931	
(This space for State use)	X O	A Di	roved d	iec 8 200	ir		
APPPROVED BY	X	_717/LE	NOTED U		DATE		
Conditions of approval, if any:	· Lu	Id Had					
		· · \	•				

MURCHISON OIL & GAS INC

P&A'D 3/28/03

TIZ NOW #1 SEC 29 T-17S R-26E 1480' FNL & 660' FEL EDDY COUNTY NEW MEXICO

GL @ 3383'

FORMATION TOPS

GLORIETA 2303'
YESO 2356'
ABO 4298'
WOLFCAMP 5660'
STRAWN 7832'
ATOKA 8223'
MORROW 8414'

