

District I
1625 N French Dr. Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 27 2009

Form C-141
Revised March 17, 1999

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

NMLB0912449922

Release Notification and Corrective Action

30-05-30448

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211		Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Shugart 23 Fed Com #1		Facility Type <input type="checkbox"/> Oil Well

Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>
---------------	---------------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section 23	Township 18S	Range 31E	Feet from the 1650	North/South Line South	Feet from the 1980	East/West Line East	County Eddy County, NM
-------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------------------

NATURE OF RELEASE

Type of Release Oil	Volume of Release 40 bbls	Volume Recovered <input type="checkbox"/> 11 bbls
Source of Release Hole in bottom of oil tank.	Date and Hour of Occurrence April 23, 2009 (? Hour)	Date and Hour of Discovery April 23, 2009 12:15 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES. To Whom? Sherry Bonham - Artesia OCD ; Doug Hogan - BLM (Carlsbad)	
By Whom? <input type="checkbox"/> David Sherrell	Date and Hour <input type="checkbox"/> April 23, 2009 3:10 PM (OCD) 3:21 PM BLM)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken *

Discovered hole in bottom of tank caused by internal corrosion. Will air out area, rake, and fertilize.

Describe Area Affected and Cleanup Action Taken *

70'x20' air out area, rake, and fertilize Will repeat if necessary

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>Roger Hernandez by G.V.</i>	OIL CONSERVATION DIVISION	
Printed Name. Roger Hernandez	Approved by: District Supervisor <i>Mike Brannon</i>	
Title Production Foreman	Approval Date MAY 04 2009	Expiration Date
Date. April 24, 2009 Phone: 575-748-5238	Conditions of Approval <i>SEE ATTACHMENT</i>	Attached <input checked="" type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-302