

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

De
CG
PP
DK
BW
RB
mm

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		MAY 19 '88	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Yates Petroleum Corporation ✓		O. C. D. ARTESIA OFFICE	5. State Oil & Gas Lease No. LG 5233
3. Address of Operator 105 South 4th St., Artesia, NM 88210			7. Unit Agreement Name Sunny Side State Unit
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 10S RANGE 26E NMPM.			8. Farm or Lease Name Sunny Side State Unit
			9. Well No. 1
			10. Field and Pool, or Wildcat Wildcat San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3838.7' GR			12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission given by Mike Williams, NMOCD, Artesia, NM, to plug well as follows:

TD 6500'; PBTD 2000'.

Cut off and laid down 10 joints 5-1/2" casing. Circulated hole with heavy gel.

Spot 25 sx Class "C" plug from 1893-1650'.

Spot 25 sx Class "C" plug from 1183-936'.

Spot 25 sx Class "C" cement across 5-1/2" stub at 490-340'.

Spot 10 sx surface plug.

Installed regulation abandonment marker.

Plugging completed 5-17-88.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Francis D. Doolittle TITLE Production Supervisor DATE 5-18-88

APPROVED BY Daniel Moore TITLE Geologist DATE 5/10/89

CONDITIONS OF APPROVAL, IF ANY:

(1) 7-20-89 to 1-1-1990. P. D.