

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Ave , Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

JUN 15 2009

Form C-103
June 19, 2008

fm

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-36645
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Higgins 33
8. Well Number 1H
9. OGRID Number 217955
10. Pool name or Wildcat Wildcat Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator OGX Resources LLC	
3. Address of Operator P. O. Box 2064 Midland, Texas 79702	
4. Well Location Unit Letter <u>I</u> : <u>2300</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>33</u> Township <u>23S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3066' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Workover ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU workover unit. Set RBP at 7045'. RU WL & TIH with GR-CBL. Run logs from 7000' - 2500'. Good cement. Perf Upper Bone Springs 6917', 6905', 6670', 6641', 6615', 6562', 6528', 6500', 6298', 6278', 6267'. POOH. RD WL. MIRU Halliburton to frac. Pump 4000 gals 15% NEFE acid followed by 70,988 gals slick water pad followed by 11,871 lbs 40/70 white sand. RD Halliburton. Production rate 7 BO, 20 BW, 170 MCF.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shelley Bush TITLE Production Clerk DATE 6/11/09

Type or print name Shelley Bush E-mail address: PHONE: 432/685-1287

For State Use Only

APPROVED BY: Jaime R TITLE Geologist DATE 6/16/09

Conditions of Approval (if any):