Form 3160-5 (August 1999)

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR

JUL 13 2009

OCD-ARTESIA

Water Disposal

FORM APPROVED OMB NO. 1004-0135

pending pieline

	NID MANACEMEN	-		Expire	es: November 30, 2000							
BUREAU OF LA	AND MANAGEMEN	1		5. Lease Ser	ial No.							
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side					NM048344 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or N 8. Well Name and No OXY Speed Bump Fed #1							
								1. Type of Well Oil Well X Gas Well Other				
								2. Name of Operator OXY USA WTP Limited Partnership				
3a. Address 3b. Phone No. (include area code)				9. API Well No.								
P.O. Box 50250, Midland, TX 79710-	915-685-5717	,	30-015-30967 10. Field and Pool, or Exploratory Area									
4. Location of Well (Footage, Sec., T., R., M., or Survey I				Empire Per								
660 FNL 810 FEL NENE(A) Sec 21 T17	S R28E											
					11. County or Parish, State							
				Eddy	NM							
12. CHECK APPROPRIATE	BOX(ES) TO INC	DICATE NATURE OF N	NOTICE, REPO	ORT, OR OT	HER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION											
X Notice of Intent	Acıdıze	Deepen	Production	(Start/Resume)	Water Shut-Off							
Subsequent Report	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamatio		Well Integrity Other Flow Well							
Final Abandanmant Nation	Change Plans	Plug and Abandon	Temporaril		nending nieline							

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Plug Back

Convert to Injection

Per phone conversion between BLM-Wesley Ingram and OXY-Chris Humphreys on 2/20/09, OXY USA WTP LP respectfully requests permission to continue flowing/flaring well until it can be reconnected to pipeline. This will eliminate the possibly of the well going down and being unable to produce again. The volumes will be reported during this interim period. Well tied in to test unit 2/18/09 and flow test well until it was connected to gas sales line on 2/28/09.

14. I hereby certify that the foregoing is true and correct Name (Printed Typed) David Stewart		Sr. Regulatory	Analyst		
De State		5/19/09	APP	ROVED	
THIS SPACE FOR FEDERAL	OR STA	TE OFFICE USE		-200	
Approved by	Title		JUL	Date ZUUS	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office		WESLE	Y W. INGRAM	

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfull to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.