Submit 3 Copies To Appropriate District Office	State of New Mexico		JUN 26 2009	Form C-103
District I	Energy, Minerals and Natural Resources		•	June 19, 2008
1625 N French Dr., Hobbs, NM 88240	d'en		WELL API NO. 30-015-28279	
<u>District II</u> 1301 W Grand Ave , Artesia, NM 88210	OIL CONSERVATION DÍVISION		5. Indicate Type of Leas	Δ
District III	1220 South St. Francis Dr.		STATE	FEE
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease	
1220 S St Francis Dr , Santa Fe, NM			LC-029435-B	
87505	ICES AND REPORTS ON WELLS		7. Lease Name or Unit 'A	Agramont Nama
•	ICES AND REPORTS ON WELLS ISALS TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A	7. Lease Name of Omit F	Agreement Name
DIFFERENT RESERVOIR USE "APPLIE	CATION FOR PERMIT" (FORM C-101) FO		J L Keel B	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		8. Well Number 077	
2. Name of Operator		9. OGRID Number		
Merit Energy Company		14591	14591	
3. Address of Operator		10. Pool name or Wildcat		
13727 Noel Rd. Suite 500 Dallas, Texas 75240		Grayburg - Jackson		
4. Well Location				
Unit LetterH:	1930feet from theN	line and	714feet from the	Eline
Section 08	Township 17S	Range 31E	NMPM Eddy	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
			i	
12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF IN	ITENTION TO:	CLID	CEOUENT DEDODI	- 05.
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			SEQUENT REPORT OF: K	
TEMPORARILY ABANDON	- -		ILLING OPNS. P AND	
PULL OR ALTER CASING				'A
DOWNHOLE COMMINGLE	MOETH LE COM L	O/ (OII TO/ OEIVIE! T	1 000	V 2
	* * * * *			
OTHER: Convert to Injection				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or starting any proposed we or recompletion.	ork). SEE RULE 1103. For Multipl	e Completions: "Al	ttach wellbore diagram of p	roposed completion
or recompletion.			(No.	
Injection Order dated 06/01/09		6	16 P = 10663-18	
Injection Order dated $06/01/09$ $ \mathcal{W} = \frac{10663 - B}{2} $				
MIRU PU. ND WH. NU BOPE. POOH w/rods LD. Unseat TA & POOH w/production tbg. LD. PU & RIH w/Baker Hornet injection pkr.				
on 2-3/8" IPC tbg. testing in. Set inj. Pkr. +/- 50' above perforations (+/- 3040'). ND BOPE. Install injection wellhead. RD MO PU. Install fiberglass injection lines to well. Remove pumping unit. Perform MIT. If successful begin injection.				
instan nocigiass injection lines to wen. Remove pumping unit. Terrorin wit i, it successful organ injection.				
			1	
			1	
			i 	
6 15 / /	n' n' n		1	
Spud Date: 18/02/95	Rig Release Da	te: 08/09/	95	
			The state of the s	at the second
I hereby certify that the information	above is true and complete to the be	et of my knowlede	<u></u>	
Thereby certify that the information	above is true and complete to the be	st of my knowledg	ge and benef.	
1	,		1	
SIGNATURE THE ME	TITLE_Regu	atory Manager	DATE06	5/24/2009
				0.00 (0.0 1.00)
Type or print nameLynne Moon_	E-mail address:		PHONE: _	972-628-1569
For State Use Only	1		1	1 1
APPROVED BY: Puthro	NGS TITLE COM	PLIANCE (STACES DATE 7	124/09
Conditions of Approval (if any):		,		' ' t '

Contract to the second